Location:	Tony	Husske	
•	Powell Butt	e, OR	

## TRUCK AND EQUIPMENT CONSULTING LLC - LOADER BACKHOE CHECKLIST

Date (Y/M/D	8/12/2022
INSPECTOR INITIALS	J.R.

(Basic Information)						
(Manufacturer)		Case				
(Model Number)		580 Super N				
(Serial Number/PIN)		JJGN58SNCEC706413				
(Year of Manufacturing)		2014				
(Hour Meter Reading)		1901.9 HRS				
(Engine Model)	TIER IV A	Fiat F5HFL413B I4 3.4L 95 Hp TurboD				
(Transmission)		PowerShuttle 4 Fwrd + 4 Rev				
(Loader Lift Capacity)		7044 lbs				
(Final Drive 2WD/4WD)		4WD				

Α	(Near t	to	Brand	New	or	Excellent	Condition)

- B (A little Wear but Good Condition)
- C (Fair Average Condition for hours and year)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

Specification and Dimensions						
Serial Plate/Frame Inscription		JJGN58SNCEC706413				
Cabin • Canopy	(Circle)	Enclosed Cab Single door				
EPA Certificate / Permits	s Posted	EROPS / EFOPS				
Loader Bucket/Capacity		82 in bucket / 1.03 yd3 (est)				
Hydraulic/Eng Oil/Coolant Capacities		Hyd Sys=132 qt/Eng Oil=14.4 qt/Coolant=19 qt				
Size of tire		Mitas 12.0L x 16.5 / Grip-n-Ride 19.5L x 24				
Hydraulic Relief		3450 psi				
Backhoe Max Reach/Height		24 in Universal / 25 Ft 5 in / 13 Ft 3 in				
Air Con/Window Venting		A/C and Heat (working)				
Auxillary Hydraulics		No				
Other		Extendahoe, Mechanical Coupler, Hyd Outriggers				

I	(Check List)	Α	В	С	D	Е	(Remarks)
GENERAL	(General Appearance-Front)		Х				Good appearance pins, hydraulics, loader bucket, Level stance, No damage
APPEARANCE	(General Appearance-Rear)		Χ				Good appearance backhoe + stick, No damage, Minor surface cosmetics
	(General Appearance-Right )		Х				Right Good panel fitment + good panel gaps No damage Good appearance
	(General Appearance-Left )		Х				Left Good panel fitment + good panel gaps No damage Good appearance
	(General Appearance-Upper )		Х				Cab roof, Hood, upper panel surfaces, Good appearance No damage
	(Major / Minor Surface Rust)		Х				No rust issues No rust seen
	(Body Panel Rust Damage / Cancer)		Χ			No rust damage No panel damage	
	(Visible Weld Repairs / Stress Cracks)		Χ				No weld repairs No stress cracks seen
	(Glass Condition)		Χ				Good Glass
	(Chassis / Undercarriage Damage)		Χ				Good chassis and frame appearance No damage Dry appearance
	(Operator Cabin)		Χ				Straight+complete Solid floors Good steering wheel No damaged panels
OPERATOR'S	(Operator Controls and Switches)		Χ				Complete No damage Good Appearance and function
COCKPIT	(Hour Meter Activity)		Χ				Working
	(Other Gauge Activity)		Χ				All Gauges Working
	(Door / Canopy Latches)		Χ				Single Door Good function, Hood latch and panel latches Good function
			Working				
			Χ				Good seat condition Some minor discoloration
	(Safety - Seat Belts / Fire Extinguisher)		Χ				yes
ENGINE	(Oil Color / Fluid Appearance / Particulates or Granuales)		Χ				Good appearance No signs of cross contamination
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		Χ				No unusual noises at start up Good Idle No noise at shutdown
	(Engine Exhaust Color – White / Blue / Black / Clear)		Χ				Clear + Clear at operating temp
	(Oil Leaks )		Χ				No active engine oil leaks seen
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		Χ				No smoke issues
	(Coolant Color / Fluid Appearance )		Χ				Good coolant appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		Χ				None seen
	(Coolant Leaks from Radiator)		Χ				None seen
	(Overall Engine Appearance Clean / Wet / Dry)		Χ				Clean and Dry engine appearance No rust No dried seepages
	(Overall appearance of Hydraulic lines/fittings - worn/cracked)		Χ	Χ			Some dried seepages backhoe swing cylinder+end caps Good hoses
HYDRAULICS	(Hydraulic Pump Sounds / Noises)		Χ				No unusual noises or vibrations under load
OVERALL	Wet or Damp hydraulic lines and fittings / fluid leaks)		Х				No active leaks seen
	(External Controls / Levers Condition)		Χ				Good condition
	(Hydraulics Service Records / Maintenance History)						not marked

	(Lighting Sv	stem Condition)			Y		1	Working		
		arm / Backup Sigi	nal)		X			N/A		
ELECTRICAL	(Battery Cor		iai)		X			Battery compartment Good No rust		
LLLOTTIONL	(Outrigger Controls)			X			Good Function			
	(Foot Brake)				X			Good Brake Function		
BRAKES			Jorking Condition)		X			Good		
BRAKES	(Inching Brake Functional & Working Condition) (Parking Brake)				X			Working		
	(Other Remarks)				X			Good Brake Function		
	( · · · · · · · · · · · · · · · ·	e / Function)			X			Smooth function No noises No vibrations		
TRANSMISSIO		n Noise / Function	on)		X			No noises or banging Good Forward and Reverse Travel		
TIVAIVOIVIIOGIOI	•	Condition & Fund	•		X			Good shifter appearance		
	(Other Rem		cion,		X			Transmission Good Performance		
		(Oil Leak from C	vlinder)		X	+		No active leaks or seepages seen Good appearance cylinders+pistons		
	Loader	(Mounting Pin C			X			No damage Good appearance of pins		
HYDRAULICS		(Oil Leak from C			X	Х		Pistons Clean No rust or pitting Some dried seepages end caps See pics		
CYLINDERS	Backhoe	(Mounting Pin C	•		Х	1		Good appearance No damage		
CYLINDERS		(Oil Leak from Cylinder)			Х	1		No active leaks or seepages seen Good appearance cylinders+pistons		
	Steering	(Mounting Pin Condition)			Х	1		No damage Good appearance of pins		
	Outriggers (Other Remarks)				Х			Good appearance cylinders+pistons Outrigger Pads Good Appearance		
	Bucket	(Other Remarks)			Х			Good Bucket Response Up and Down		
	(Transom / Boom / Arm Function / Noise )				Χ			No unususal noises Good Function		
	(Slack in Pin	s / Loose Pins /	Soft Bushings)		Χ			No excess slack or vibration noises		
	(Level stance and alignment)				Χ			Yes		
CHASSIS	(Front Axle	Appearance)			Χ			Clean and Dry appearance No rust No dried seepages		
& COMPONENT	T(Rear Axle A	ppearance)			Χ			Clean and Dry appearance No rust No dried seepages		
	(Center Pin	Appearance)			Χ			Good appearance No damage seen		
		(Front)	Remaining Ratio Of Right *(A)to(E)		Χ			R F Tire =B Good appearance		
	(Wheel	(1 TOTIC)	Remaining Ratio Of Left *(A)to(E)		Χ			L F Tire =B Good appearance use (A)90% to (E) 20%		
	Condition)	(Rear)	Remaining Ratio Of Right *(A)to(E)		Χ			R R Tire =B Good appearance		
		, ,	Remaining Ratio Of Left *(A)to(E)		Х			L R Tire =B Good appearance		
	(Tread Cond	•			Χ			No sidewall damage seen Front Tread =B / Rear Tread = B		
		Bucket Appearance)			Х			Good Bucket and Edge No dents No dings		
LOADER	(Bucket Cor				Χ			Good		
		(Arm/Link Condition)			Χ			Good appearance and Good loader function		
	(Other Remarks)			Χ			Good condition			
	( Bucket Appearance)				Χ	<u> </u>		Good Backhoe + Extend a Hoe bucket appearance and function		
BACKHOE	(Bucket Condition)				Χ	<u> </u>		No damage Good appearance		
	(Arm/Link Condition)				Χ	1		Good appearance		
	(Other Rema	arks)			Χ			Good Side to Side Right + Left lateral function		

OVERALL EXTERIOR RATING:B	QUALITY: <u>B</u>	<b>DIMENSIONS:</b> (shipping reference)	*A:Remaining Ratio	90% or more
OVERALL INTERIOR RATING:B	SAFETY: <u>B</u>	Length: 280 in	*B:Remaining Ratio	70% or more
OVERALL PERFORMANCE: B	FUNCTIONALITY: <u>B</u>	Width: 7 Ft 2 in	*C:Remaining Ratio	50% or more
OVERALL EVALUATION GRADE: B		Height: 133 in	*D:Remaining Ratio	20% or more
FLUID SAMPLE REQUEST (Y/N) $\underline{n}$ OIL $\underline{n}$	COOLANT <u>n</u>	Weight: 19,750 lbs	*E:Remaining Ratio	20% or less