

Inspection Report (Generator)

General Info

Year	2016
Make	Multiquip
Model	Whisperwatt DCA - 70SSIU4F
Serial Number	7353197
Hour Meter Reading	15,272
Previous Application (e.g., earth moving, mining, demolition, etc)	General construction

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	15'
Width (ft and inches)	6'
Height (ft and inches)	7'
Operating Weight (lbs)	7,000 lbs.

Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Towable	Yes
Current Inspection / State Cert / DOT	N/A
Trailer VIN	5SLBG1428FL017734
Trailer GWVR	7000
Wheelbase (ft and inches)	31"
Hitch Type	Pintle
Standby Power Rating (kW/KVA)	40kVA (single phase) 70kVA (3 Phase)
Phase Type	Other (see comments)
Comments	Single 3 Phase
OMM (Operator & Maintenance Manual)	No
Telematics	No

General Appearance

General Appearance


Front	3 - Normal Wear & Tear
Front Condition	No visible damage, Other (see comments)
Comments	Front panel hardware missing

Inspection Report (Generator)




Front Photos



Inspection Report (Generator)






Inspection Report (Generator)

	
	
Rear	3 - Normal Wear & Tear
Rear Condition	No visible damage
Rear Photos	

Inspection Report (Generator)






Inspection Report (Generator)

		
Left	3 - Normal Wear & Tear	
Left Condition	No visible damage, Other (see comments)	
Comments	No major damage just surface scratch on left side engine compartment door	
Left Photos		
		

Inspection Report (Generator)



Inspection Report (Generator)

	
	
Right	3 - Normal Wear & Tear
Right Condition	No visible damage
Right Photos	




Inspection Report (Generator)



Inspection Report (Generator)



Inspection Report (Generator)

	
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage, Other (see comments)
Comments	Dusty
Upper Photos	
	
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment

Inspection Report (Generator)




Body Panels Photos



Inspection Report (Generator)



Inspection Report (Generator)

		
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Doors / Canopy Latches Photos		
		

Inspection Report (Generator)

		
		
Glass Condition	0	
Mirrors	0	
Lighting System	3 - Normal Wear & Tear	
Lighting System Condition	Other (see comments)	
Comments	Exterior of lights and wire harness look to be good, unable to test	
Lighting System Photos		

Inspection Report (Generator)





Inspection Report (Generator)






Exterior 360 Walkaround

Exterior 360 Walkaround

Front	3 - Normal Wear & Tear
Front Condition	No visible damage
Front Photos	
	




Inspection Report (Generator)

	
Rear	3 - Normal Wear & Tear
Rear Condition	No visible damage
Rear Photos	
	

Inspection Report (Generator)

	
	
	
Left	3 - Normal Wear & Tear
Left Condition	Other (see comments), No visible damage
Comments	Minor surface scratch on l/s door

Inspection Report (Generator)


<p>Left Photos</p>	
<p>Right</p>	<p>3 - Normal Wear & Tear</p>
<p>Right Condition</p>	<p>No visible damage</p>
<p>Right Photos</p>	
	

Inspection Report (Generator)


	
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	Isuzu/BR - 4JJ1X - 6 Cyl. - 95HP
Emissions Tier	Tier 4F
Engine Serial Number	193097
Engine Fuel Type	Diesel
Engine Photos	

Inspection Report (Generator)



Inspection Report (Generator)



Inspection Report (Generator)




Blow-by (Visual Observation Check)	Yes
Comments	Minor blow by coming from valve cover breather hose
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Like new, recently replaced, Clean & dry appearance, tight connections




Inspection Report (Generator)

Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	
	

Inspection Report (Generator)



Inspection Report (Generator)


	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Belt Photos	
	
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks

Inspection Report (Generator)


Hose Photos





Inspection Report (Generator)






Inspection Report (Generator)




Inspection Report (Generator)

	
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	Yes
Cooling System Condition	Other (see comments, No indication of coolant leaks seen)
Comments	No active leaks seen just a sign of residual coolant from egr valve to manifold
Cooling System Leaks Photos	
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	Yes
Oil Leak Notes	Dried oil seepages seen, Other (see comments)
Comments	Possible oil seepage coming from valve cover, oil coming out of cold side and charge side




Inspection Report (Generator)

<p>Oil Leak Photos</p>		
		
		


Inspection Report (Generator)






Inspection Report (Generator)

	
	
	
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated

Inspection Report (Generator)






Inspection Report (Generator)

	
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
DEF Tank Photos	
	
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Besides the small oil leak from turbo and seepage from valve cover, the rest of the engine looks well maintained. Engine oil buildup around intake and discharge hoses from turbo may be an indication of wet stacking.

Electrical Connections

Inspection Report (Generator)

Wire Harness	3 - Normal Wear & Tear
Wire Harness Photos	
	
	


Inspection Report (Generator)



Inspection Report (Generator)






Inspection Report (Generator)






Cables & Fittings

3 - Normal Wear & Tear




Inspection Report (Generator)

<p>Cables & Fittings Photos</p>	
	
	
<p>Electrical Connections</p>	<p>3 - Normal Wear & Tear</p>

Inspection Report (Generator)

Electrical Connections Photos	
	
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Photos	

Inspection Report (Generator)

	
Disconnect Switch	3 - Normal Wear & Tear
Disconnect Switch Photos	
	




Generator Panel

110V	Yes
Number of Outlets	2
110V Outlet Condition	3 - Normal Wear & Tear

Inspection Report (Generator)

<p>110V Outlet Photos</p>	
	
<p>240V</p>	<p>Yes</p>
<p>Number of Outlets</p>	<p>3</p>
<p>240V Outlet Condition</p>	<p>3 - Normal Wear & Tear</p>

Inspection Report (Generator)

<p>240V Outlet Photos</p>	
<p>480V</p>	<p>Yes</p>
<p>480V Outlet Condition</p>	<p>3 - Normal Wear & Tear</p>
<p>480V Outlet Photos</p>	
	

Inspection Report (Generator)






Relay Panel

3 - Normal Wear & Tear



Relay Panel Photos




Inspection Report (Generator)

		
Receptacles	3 - Normal Wear & Tear	
Receptacles Photos		
Panel Indicator Lights	3 - Normal Wear & Tear	
Panel Indicator Lights Photos		
Disconnect Switch	3 - Normal Wear & Tear	




Inspection Report (Generator)

Disconnect Switch Photos	
Emergency Shut Off Switch	0
Fuse Block	3 - Normal Wear & Tear
Fuse Block Photos	




Gauges & Meters

Hour Meter	3 - Normal Wear & Tear
Hour Meter Photos	




Inspection Report (Generator)

	
RPM Display	3 - Normal Wear & Tear
RPM Display Photos	
	
Volt Display	3 - Normal Wear & Tear



Inspection Report (Generator)

Volt Display Photos	
Pressure Display	3 - Normal Wear & Tear
Pressure Display Photos	
	

Inspection Report (Generator)

	
	
Menu Display	3 - Normal Wear & Tear
Menu Display Photos	
Display Screen Appearance	3 - Normal Wear & Tear
<h3>Mounting Plate</h3>	
Overall Mounting Plate Appearance	0
Bottom Surface	3 - Normal Wear & Tear
Comments	Dusty normal wear


Inspection Report (Generator)

Bottom Surface Photos	
	
Mount Security	3 - Normal Wear & Tear
Comments	All hardware tight and no hardware missing

Trailer & Fuel Tanks

Trailer Inspection Points




Frame & Body

Frame Condition	3 - Normal Wear & Tear
Frame Photos	


Inspection Report (Generator)





Inspection Report (Generator)

		
		
<p>Fenders</p>	<p>3 - Normal Wear & Tear</p>	
<p>Fender Photos</p>		



Inspection Report (Generator)

	
Mud Flaps	0
Trailer Lights/Wiring (Stop, Tail, Turn)	3 - Normal Wear & Tear
Comments	Unable to test but visually, exterior lighting in good shape
Reflectors	0


Hitch

Hitch Type	Pintle
Hitch Condition	3 - Normal Wear & Tear
Hitch Photos	
	




Inspection Report (Generator)

Drawbar	3 - Normal Wear & Tear
Strand Wear?	No
Comments	Safety breakaway cable missing
Drawbar Photos	
	

Suspension

Springs	0
U-Bolts	0
Torque Arms	3
Torque Arms Photos	

Inspection Report (Generator)

		
		
		
Equalizer	0	

Wheels & Tires




Wheels & Hub Condition	3 - Normal Wear & Tear
-----------------------------------	------------------------

Inspection Report (Generator)



Wheels & Hub Photos




Inspection Report (Generator)

		
Loose Lugs	No	
Tire Brand	Mastertrack	
Tire Size	ST 205/75R15	
Front Left Tire - Ratio Remaining	50%	
Front Left Tire Photos		
Front Right Tire - Ratio Remaining	50%	
Front Right Tire Photos		
Rear Right Tire - Ratio Remaining	50%	

Inspection Report (Generator)




Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	50%
Rear Left Tire Photos	

Brake Components

Brake Type	Surge Brakes
Brake Controller	No
Emergency Brake/Break-Away	1 - Service Required
Comments	Missing break away pull cable (did not test)
Emergency Brake/Break-Away Photos	

Overall Trailer Condition

Inspection Report (Generator)


Overall Trailer	3 - Normal Wear & Tear
Overall Trailer Comments	Overall trailer in good shape with no major repairs needed. Unable to test brake, trailer light functions.
Overall Trailer & Undercarriage Photos	
	
	

Inspection Report (Generator)






Additional Axle Inspection




Additional Axle

Instructions	Check the condition of additional axle(s), wheels & tires. Note any damage or wear. Take photos.
Axle Description & Position	2 solid bolt to frame axles
Steerable?	No
Drop Axle?	No
Super Dump?	No
Weight Rating	3,750lbs.
Axle Condition	3 - Normal Wear & Tear
Axle Condition Photos	



Inspection Report (Generator)

	
	
	
Wheels & Tires	3 - Normal Wear & Tear
Fuel Tank Condition	3 - Normal Wear & Tear

Inspection Report (Generator)

<p>Fuel Tank Photos</p>	
	
	
<p>Fuel Lines & Hoses</p>	<p>3 - Normal Wear & Tear</p>

Inspection Report (Generator)

Fuel Lines & Hoses Photos	
	

Functional Test

Instructions	Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate): 4 = Like New, Recently Replaced 3 = Normal Wear & Tear 2 = Above Average Wear 1 = Service Required
Engine	3 - Normal Wear & Tear
Comments	Turbo may be worn and or wet stacking conditions caused oil buildup
Controls	3 - Normal Wear & Tear
Gauges & Meters	3 - Normal Wear & Tear
Power Output	3 - Normal Wear & Tear
Outlets	3 - Normal Wear & Tear
Trailer	3 - Normal Wear & Tear
Overall Functional Test Comments	Overall from a visual standpoint, the generator is producing voltage to outlets and connections. Engine sounds healthy and all functions tested without a load seem to be normal.
Operating Video	Click to Download

Inspection Summary

Inspection Report (Generator)

Overall Assessment	
Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	Generator is well maintained and all functions that were tested function properly.
What Needs Work	Turbo may need further inspecting because of residual oil at turbo inlet/outlets. Possible oil leak at valve cover, signs of coolant leak at egr valve to cooler. Some panel hardware missing Breakaway trailer hitch cable missing. This generator shows signs of wet stacking and should be tested.
Date/Time	10-06-2022