

Inspection Report (On-Highway Dump Truck)

General Info

Year	2011
Make	Peterbilt
Model	367
Serial Number	1NP - TLUOX - 8 - BD127978
Truck Odometer Reading	400,445 Mi.
Previous Application (e.g., earth moving, mining, demolition, etc)	Asphalt Construction

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	30'2"
Width (ft and inches)	8'2"
Height (ft and inches)	12'10" to top of strong arm axle
Wheelbase (ft and inches)	20'8"
GVWR (lbs)	66,000



Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
PTO Details	Trans mounted Muncie
Engine Brake	Yes
Differential Lock	Yes
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (On-Highway Dump Truck)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)






General Appearance Inspection Points




General Appearance

Front	3 - Normal Wear & Tear
Front Condition	No visible damage, Other (see comments)
Comments	minor clear coat peeling

Inspection Report (On-Highway Dump Truck)

<p>Front Photos</p>	
	
	
<p>Rear</p>	<p>3 - Normal Wear & Tear</p>
<p>Rear Condition</p>	<p>No visible damage, Other (see comments)</p>
<p>Comments</p>	<p>normal wear and tear</p>




Inspection Report (On-Highway Dump Truck)

<p>Rear Photos</p>	
	
<p>Left</p>	<p>3 - Normal Wear & Tear</p>
<p>Left Condition</p>	<p>No visible damage</p>
<p>Left Photos</p>	

Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

		
		
Right	3 - Normal Wear & Tear	
Right Condition	No visible damage	
Right Photos		




Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

		
		
Upper	3 - Normal Wear & Tear	
Upper Condition	No visible damage	
Upper Photos		




Inspection Report (On-Highway Dump Truck)

		
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear	
Body Panel Condition	No visible damage, good paint condition and panel fitment, Other (see comments)	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Photos		
		




Inspection Report (On-Highway Dump Truck)

		
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Handrail Photos		
Glass Condition	3 - Normal Wear & Tear	
Glass Condition Notes	Glass intact, no visible damage	
Glass Condition Photos		

Inspection Report (On-Highway Dump Truck)

	
	
	
Mirrors	3 - Normal Wear & Tear
Mirror Condition Notes	Mirrors present and intact, no visible damage

Inspection Report (On-Highway Dump Truck)

Mirrors Photos	
	
Lighting System	3 - Normal Wear & Tear
Lighting System Condition	No visible damage, lighting system is operational
Lighting System Photos	

Inspection Report (On-Highway Dump Truck)



Cab Inspection Points

On Highway - Cab

Serial Number Plate Photo



Operator Cabin

3 - Normal Wear & Tear

Inspection Report (On-Highway Dump Truck)




Operator Cabin Photos






Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

	
	
<p>Operator's Seat & Arm Rests</p>	<p>3 - Normal Wear & Tear</p>
<p>Operator's Seat & Arm Rests Photos</p>	

Inspection Report (On-Highway Dump Truck)

		
Seat Belt	3 - Normal Wear & Tear	
Cabin Lights	3 - Normal Wear & Tear	
Cabin Lights Photos		
Controls & Switches	3 - Normal Wear & Tear	
Controls & Switches Photos		



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

	
Odometer Activity	3 - Normal Wear & Tear
Odometer Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Activity Photos	

Inspection Report (On-Highway Dump Truck)

	
Heater & A/C	3 - Normal Wear & Tear
Heater & A/C Photos	
Fans / Vents	3 - Normal Wear & Tear
Horn	3 - Normal Wear & Tear
Reverse Alarm / Backup Signal	3 - Normal Wear & Tear
Backup Camera	0
Other Electronic Devices	0
Fire Extinguisher	0
First Aid Kit	0


Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	CAT - C13 - 6Cyl. - 470HP - 12.5L
Emissions Tier	Tier 4i
Engine Serial Number	N/A
Engine Fuel Type	Diesel

Inspection Report (On-Highway Dump Truck)


Engine Photos





Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

		
Blow-by (Visual Observation Check)	No	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Unusual Noise Notes	No unusual noises heard	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke Notes	No engine smoke issues observed	
Engine Exhaust Color	Clear	
Battery	3 - Normal Wear & Tear	
Battery Condition	Clean & dry appearance, tight connections	
Radiator	3 - Normal Wear & Tear	
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks	
Radiator Photos		




Inspection Report (On-Highway Dump Truck)

		
		
Belts	3 - Normal Wear & Tear	
Belt Condition	Belts appear in good condition & alignment with proper tension	
Belt Photos		



Inspection Report (On-Highway Dump Truck)

		
Hoses	3 - Normal Wear & Tear	
Hose Condition	Firm, pliant hoses with no signs of wear or leaks	
Hose Photos		
		

Inspection Report (On-Highway Dump Truck)

		
		
Water Pump	3 - Normal Wear & Tear	
Cooling System Leaks	No	
Coolant Color / Appearance	3 - Normal Wear & Tear	
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination	
Oil Leaks	Yes	
Oil Leak Notes	Wetness & discoloration observed, Other (see comments)	
Comments	small oil leak observed at rear, right side of oil pan to back cover & engine block area	
Oil Leak Photos		

Inspection Report (On-Highway Dump Truck)




Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
DPF Photos	
	
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Minor leak at top r/s of engine oil pan to block and back cover

Drivetrain Inspection Points




Drivetrain

Transmission Info (Make/Model)	Eaton Fuller 10 Speed Manual
Drive Type	4X2
Overdrive	No
Transmission	3 - Normal Wear & Tear




Inspection Report (On-Highway Dump Truck)

Transmission Condition	No unusual noises or vibrations
Transmission Condition Photos	
	
	
Clutch	3 - Normal Wear & Tear
Clutch Condition	Clutch is functioning as expected
Shift Lever	3 - Normal Wear & Tear
Shift Lever Condition	Good forward and reverse function




Inspection Report (On-Highway Dump Truck)

Shift Lever Photos	
	
Differential	Check condition of the differential(s). Take photos and notes as relevant.
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation
Rear Differential Photos	

Inspection Report (On-Highway Dump Truck)

		
		
		
Front Differential	3 - Normal Wear & Tear	
Front Differential Condition	Dry housing appearance, no unusual noises heard during operation	




Inspection Report (On-Highway Dump Truck)

Front Differential Photos		
		
Brake System Type	Air Brakes	
Air Brakes Build Correct Pressure	Yes	
Air Brake System Leaks	No	
Air Brake Hose Condition	3 - Normal Wear & Tear	
Air Brake System Photos		

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)




	
	
Foot Brake	3 - Normal Wear & Tear
Foot Brake Condition	Good brake function
Foot Brake Photos	
Engine Brake Configuration	2 Position
Engine Brake	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain in good condition

Inspection Report (On-Highway Dump Truck)


Chassis & Axle Inspection Points

Chassis


Frame

Frame Condition	3
Frame Photos	
	
	

Inspection Report (On-Highway Dump Truck)



Suspension

<p>Suspension</p>	<p>3</p>
<p>Suspension Photos</p>	

Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)






Steering

Steering Components	3
Steering Components Photos	


Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

		
Steer Axle Condition	3	
Steer Axle Photos		
		


Inspection Report (On-Highway Dump Truck)






Wheels & Tires

Wheels & Hub Condition	3
Wheels & Hub Photos	




Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

	
	
Wheel Seal Leaks	No
Tire Brand	(Front) Yokohama (Rear) Generic Recaps
Tire Size	(Front) 315/80R/22.5 (Rear) 11R22.5
Front Left Tire - Ratio Remaining	10%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	30%



Inspection Report (On-Highway Dump Truck)

Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	50%
Rear Right Tire Photos	
	


Inspection Report (On-Highway Dump Truck)

		
		
		
<p>Rear Left Tire - Ratio Remaining</p>	<p>50%</p>	

Inspection Report (On-Highway Dump Truck)

Rear Left Tire Photos		
		


Brake Components

Brake Shoe Thickness	50%
Comments	Most brake shoes above 50% of brake shoe material left
Brake Shoe Photos	


Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Overall Chassis Condition

Overall Chassis	3
Overall Chassis & Undercarriage Photos	




Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

Additional Axles




Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.

Addition Axle Inspection

Additional Axle

Instructions	Check the condition of additional axle(s), wheels & tires. Note any damage or wear. Take photos.
Axle Description & Position	Rogue Strong Arm Axle
Steerable?	No

Inspection Report (On-Highway Dump Truck)

Drop Axle?	Yes
Super Dump?	Yes
Weight Rating	12,000
Axle Condition	3 - Normal Wear & Tear
Axle Condition Photos	
	
	

Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)





Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

	
	
	
Wheels & Tires	3 - Normal Wear & Tear
Comments	tread life left above 70%

Inspection Report (On-Highway Dump Truck)

Wheels & Tires Photos		
		
Tire Brand	Ameristeel	
Tire Size	11R22.5	
Left Tire(s) Ratio Remaining	70%	
Right Tire(s) Ratio Remaining	70%	

Additional Inspection Points

On Highway - Dump Truck

Additional Inspection Points: Dump Body, Tailgate, Support & Tarp

Dump Body Make & Material	Rogue	
Dump Body Length (ft and inches)	15'	
Dump Body Height (ft and inches)	5'3"	
Bed Body	3 - Normal Wear & Tear	

Inspection Report (On-Highway Dump Truck)


Bed Body Photos



Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

		
<p>Tailgate</p>	<p>3 - Normal Wear & Tear</p>	
<p>Tailgate Photos</p>		
<p>Tailgate Latch</p>	<p>3 - Normal Wear & Tear</p>	
<p>Tailgate Latch Photos</p>		

Inspection Report (On-Highway Dump Truck)

		
		
Support Frame	3 - Normal Wear & Tear	
Support Frame Photos		
Hinge Points	3 - Normal Wear & Tear	


Inspection Report (On-Highway Dump Truck)

Hinge Point Photos	
	
Tarp	3 - Normal Wear & Tear
Tarp Photos	

Inspection Report (On-Highway Dump Truck)



Additional Inspection Points: Dump Hydraulics

Hydraulics	Check the condition of the hydraulics. Check lines, hoses, fittings, leaks, function, etc. Note any damage or wear. Take photos.
Hydraulic Tank	3 - Normal Wear & Tear
Hydraulic Tank Photos	

Inspection Report (On-Highway Dump Truck)



Hoses	3 - Normal Wear & Tear
Hydraulic Cylinders	3 - Normal Wear & Tear
Cylinder Pins and Bushings	3 - Normal Wear & Tear
Hydraulic Function	3 - Normal Wear & Tear

Functional Test

Forward & Reverse	3 - Normal Wear & Tear
Steering	3 - Normal Wear & Tear
Engine	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Overall Functional Test Comments	Overall all functions operate well. The dump body raises and lowers normally. The strong arm axle operates great. The tarp assembly works well.

Inspection Summary

Overall Assessment

Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	Truck well maintained and no major problems observed. Engine, transmission and rear dump body assembly in good shape and operating well. Suspension in solid shape.
What Needs Work	Some tires need to be replaced soon. Minor engine oil leak observed at right side oil pan to engine block area.
Date/Time	11-15-2022