


## Inspection Report (Mini Excavator)

### General Info

|  |                 |
|--|-----------------|
| Year   | 2013            |
| Make   | Bobcat          |
| Model  | 324M            |
| Serial Number  | AKY522295       |
| Hour Meter Reading   | 401.5           |
| Previous Application (e.g., earth moving, mining, demolition, etc) | Demolition Work |

### Dimensions

|                           |   |
|---------------------------|---|
| Measurement Guide         |  |
| A. Length (ft and inches) | 12'10"  |
| B. Width (ft and inches)  | 3'3"  |
| C. Height (ft and inches) | 7'2"  |
| Operational Weight (lbs)  | 3,428 LBS.  |



### Features and Configuration

|                                     |        |
|-------------------------------------|--------|
| Control Station Type                | Canopy |
| Bucket                              | Yes    |
| Bucket Size (in inches)             | 8      |
| Blade                               | Yes    |
| Additional Attachment(s)            | Yes    |
| Hydraulic Coupler                   | No     |
| Auxiliary Hydraulics                | No     |
| Hydraulic Thumb                     | No     |
| Heat                                | No     |
| A/C                                 | No     |
| Radio                               | No     |
| Backup Camera                       | No     |
| OMM (Operator & Maintenance Manual) | No     |
| Telematics                          | No     |

### Exterior Walkaround Photos

## Inspection Report (Mini Excavator)

### Exterior 360 Walkaround


|  |   |
|--|---|
| <p><b>Instructions</b></p>               | <p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> <li>- Front</li> <li>- 45 degree corner shot of left front</li> <li>- 45 degree corner shot of right front</li> <li>- Left side</li> <li>- Right side</li> <li>- Rear</li> <li>- 45 degree corner shot of left rear</li> <li>- 45 degree corner shot of right rear</li> </ul> <p>Tips for good photos:</p> <ul style="list-style-type: none"> <li>- Move the equipment into a open area without any visual distractions or other equipment in the background</li> </ul> |
| <p><b>Exterior Walkaround Photos</b></p> |    |
|  |   |

Inspection Report (Mini Excavator)





## Inspection Report (Mini Excavator)




### General Appearance Inspection Points

#### General Appearance

|                                |   |
|--------------------------------|---|
| Front                          | 3 - Normal Wear & Tear  |
| Front Condition                | Large dents or cracks, Other (see comments)   |
| Comments                       | Front blade has surface plate damage, the rest has normal wear and tear scuff marks |
| Rear                           | 3 - Normal Wear & Tear  |
| Rear Condition                 | Other (see comments)  |
| Comments                       | Normal wear and tear scuff marks on counterweight                                   |
| Left                           | 3 - Normal Wear & Tear  |
| Left Condition                 | Other (see comments), No visible damage   |
| Right                          | 3 - Normal Wear & Tear  |
| Right Condition                | Other (see comments), No visible damage   |
| Comments                       | Normal wear and tear scuff marks  |
| Upper                          | 3 - Normal Wear & Tear  |
| Upper Condition                | No visible damage   |
| Body Panels (Any Rust Damage?) | 3 - Normal Wear & Tear  |



## Inspection Report (Mini Excavator)

|                                  |  |
|----------------------------------|--|
| Body Panel Condition             | No visible damage, good paint condition and panel fitment                            |
| Doors / Canopy Latches           | 3 - Normal Wear & Tear   |
| Doors / Canopy Latches Condition | No visible damage, Other (see comments)  |
| Comments                         | Rear engine door latch may need adjustment (door latch tough to unlock)              |
| Steps / Ladders                  | 0  |
| Handrails                        | 0  |
| Glass Condition                  | 3 - Normal Wear & Tear   |
| Glass Condition Notes            | Glass intact, no visible damage, Other (see comments)                                |
| Comments                         | Top R.O.P.S. Window normal wear  |
| Mirrors                          | 0  |
| Lighting System                  | 2 - Above Average Wear   |
| Lighting System Condition        | Other (see comments), One or more exterior lights are non-operational                |
| Comments                         | Normal light exterior wear (lens dull)   |
| Lighting System Photos           |  |

## Control Station Inspection Points

### Control Station

## Inspection Report (Mini Excavator)




|   |  |
|---|--|
| <b>Serial Number Plate Photo</b>        |    |
| <b>Operator Cabin Overall</b>           | 3 - Normal Wear & Tear   |
| <b>Operator Cabin Overall Condition</b> | Good cabin appearance, solid floors, panels, and ceiling, Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling |
| <b>Operator Cabin Photos</b>            |   |
|   |    |

Inspection Report (Mini Excavator)








### Inspection Report (Mini Excavator)

|  |   |  |
|--|---|--|
|  |   |  |
|  |    |  |
|  |   |  |
| <b>Operator's Seat &amp; Arm Rests</b>           | 3 - Normal Wear & Tear  |  |
| <b>Operator's Seat &amp; Arm Rests Condition</b> | Seat(s) in good condition, no stains or tears in upholstery, Seat(s) have minor surface staining or small tears, Other (see comments) |  |
| <b>Comments</b>                                  | No tears just minor surface wear  |  |

## Inspection Report (Mini Excavator)



|   |  |
|---|--|
| <b>Operator's Seat &amp; Arm Rests Photos</b> |    |
| <b>Seat Belt</b>                              | 3 - Normal Wear & Tear   |
| <b>Cabin Lights</b>                           | 0  |
| <b>Safety Lock Out / Stop</b>                 | 3 - Normal Wear & Tear   |
| <b>Safety Lock Out / Stop Condition</b>       | Safety lock out device is present, in good condition, and functional                 |
| <b>Controls &amp; Switches</b>                | 3 - Normal Wear & Tear   |
| <b>Controls &amp; Switches Condition</b>      | Switches have good functionality, minor cosmetic damage observed                     |
| <b>Comments</b>                               | Switch decals worn (unreadable)  |
| <b>Controls &amp; Switches Photos</b>         |  |
| <b>Hour Meter Activity</b>                    | 3 - Normal Wear & Tear   |
| <b>Hour Meter Condition</b>                   | Hour meter is functional and in good condition                                       |

### Inspection Report (Mini Excavator)

|                                   |   |
|-----------------------------------|---|
| <p>Hour Meter Activity Photos</p> |                      |
| <p>Other Gauge Activity</p>       | <p>2 - Above Average Wear</p>   |
| <p>Other Gauge Condition</p>      | <p>One or more gauges are unreadable or not functioning (specify in comments), Other (see comments)</p> |
| <p>Comments</p>                   | <p>Gauges work, worn and unreadable</p>   |



## Inspection Report (Mini Excavator)




|                               |  |  |
|-------------------------------|--|--|
| Other Gauge Activity Photos   |   |  |
|                               |  |  |
| <b>Heater &amp; A/C</b>       | 0  |  |
| <b>Fans / Vents</b>           | 0  |  |
| <b>Travel Alarm</b>           | 2 - Above Average Wear   |  |
| <b>Travel Alarm Condition</b> | System is configured but not operating correctly                                     |  |
| <b>Comments</b>               | Travel alarm inop. (May be disconnected )  |  |
| <b>Horn</b>                   | 3 - Normal Wear & Tear   |  |
| <b>Horn Condition</b>         | Horn is installed and functioning as expected  |  |
| <b>Backup Camera</b>          | 0  |  |
| <b>Fire Extinguisher</b>      | 0  |  |

## Inspection Report (Mini Excavator)




|               |   |
|---------------|---|
| First Aid Kit | 0 |
|---------------|---|

### Engine Inspection Points

#### Engine




|  |   |
|--|---|
| Engine Type (Make, Model, Cylinders, Hp) | Kubota - D722-ET17 - 14HP - 3CYL.   |
| Emissions Tier                           | Tier 4F   |
| Engine Serial Number                     | N/A   |
| Engine Fuel Type                         | Diesel  |
| Engine Photos                            |    |

### Inspection Report (Mini Excavator)



|   |   |  |
|---|---|--|
|   |   |  |
|   |    |  |
|   |  <p>EMISSION CONTROL INFORMATION<br/>(SUPPLEMENTAL LABEL)<br/>THIS ENGINE MEETS 2012 Tier4 EMISSION REGULATIONS<br/>FOR U. S. EPA AND CALIFORNIA NONROAD CI ENGINES.</p> <p><b>Kubota</b> KUBOTA Corporation</p> <p>MODEL : D722-ET17      ENGINE DISP. : 0.719L<br/>     FAMILY : CKBXL 719KCB      ECS:EM-1FI<br/>     POWER : 10.4kW/2500 rpm      CATEGORY: 8-15kW<br/>     VALVE CLEARANCE (COLD) : IN 0.165mm EX 0.165mm<br/>     INJ. TIMING: 18 DEG BTDC<br/>     ULTRA LOW SULFUR DIESEL FUEL ONLY<br/>     CONTACT KUBOTA FOR FUEL SETTING.</p> |  |
| <b>Blow-by (Visual Observation Check)</b>             | No  |  |
| <b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b> | No  |  |
| <b>Unusual Noise Notes</b>                            | No unusual noises heard   |  |
| <b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>   | No  |  |
| <b>Engine Smoke Notes</b>                             | No engine smoke issues observed   |  |
| <b>Engine Exhaust Color</b>                           | Clear   |  |




## Inspection Report (Mini Excavator)

|                    |  |
|--------------------|--|
| Battery            | 2 - Above Average Wear   |
| Battery Condition  | Inaccessible, unable to determine condition  |
| Radiator           | 3 - Normal Wear & Tear   |
| Radiator Condition | Radiator fins & components appear to be in good working order, no signs of damage or leaks |
| Radiator Photos    |         |
|                    |        |
| Belts              | 3 - Normal Wear & Tear   |
| Hoses              | 3 - Normal Wear & Tear   |
| Hose Condition     | Firm, pliant hoses with no signs of wear or leaks  |
| Hose Photos        |        |

Inspection Report (Mini Excavator)



## Inspection Report (Mini Excavator)

|  |  |
|--|--|
|  |            |
| <b>Water Pump</b>                                    | 3 - Normal Wear & Tear   |
| <b>Water Pump Condition</b>                          | No unusual pump noises heard   |
| <b>Coolant Color / Appearance</b>                    | 3 - Normal Wear & Tear   |
| <b>Coolant Color/Appearance Notes</b>                | Normal Translucent appearance, no visual signs of contamination                              |
| <b>Oil Leaks</b>                                     | No   |
| <b>Oil Color / Appearance</b>                        | 3 - Normal Wear & Tear   |
| <b>Oil Color / Appearance Notes</b>                  | Clean oil appearance, no signs of cross contamination, Appropriate oil level                 |
| <b>Fuel Leaks</b>                                    | No   |
| <b>Equipped with DPF (Diesel Particulate Filter)</b> | No   |
| <b>Requires DEF (Diesel Exhaust Fluid)</b>           | No   |
| <b>Overall Engine Appearance</b>                     | Clean & dry, Dusty & dry   |
| <b>Overall Engine Comments</b>                       | Overall engine in good condition. No obvious major problems observed with engine components. |



## Drivetrain Inspection Points

### Drivetrain

|  |                           |
|--|---------------------------|
| <b>Hydrostatic Transmission?</b>       | Yes                       |
| <b>2 Speed?</b>                        | Yes                       |
| <b>Hydrostatic Drive Configuration</b> | Split Transmission        |
| <b>Drive Motors</b>                    | 2 - Above Average Wear    |
| <b>Comments</b>                        | Drive motors working well |






## Inspection Report (Mini Excavator)

|                                     |  |
|-------------------------------------|--|
| Drive Motor Photos                  |  |
|                                     |  |
| Hydrostatic Parking Brake           | 3 - Normal Wear & Tear   |
| Hydrostatic Parking Brake Condition | Good brake function  |
| Overall Drivetrain Comments         | Overall drivetrain in good condition.  |

## Chassis Inspection Points

|                |  |
|----------------|--|
| Boom Condition | 3 - Normal Wear & Tear   |
| Boom Photos    |  |

**Inspection Report (Mini Excavator)**

|                               |  |
|-------------------------------|--|
|                               |    |
|                               |   |
| <p><b>Stick Condition</b></p> | <p>3 - Normal Wear &amp; Tear</p>  |
| <p><b>Stick Photos</b></p>    |  |

**Inspection Report (Mini Excavator)**






**Boom Base Pin & Bushings**





3 - Normal Wear & Tear






### Inspection Report (Mini Excavator)

|  |  |  |
|--|--|--|
| <p>Boom Base Pin &amp; Bushings<br/>Photos</p> |    |  |
|  |   |  |
|  |  |  |
| <p>Boom to Stick Pin &amp; Bushings</p>        | <p>3 - Normal Wear &amp; Tear</p>  |  |

## Inspection Report (Mini Excavator)

|   |  |
|---|--|
| <p><b>Boom to Stick Pin &amp; Bushings Photos</b></p>   |    |
| <p><b>Stick to Bucket Pin &amp; Bushings</b></p>        | <p>3 - Normal Wear &amp; Tear</p>  |
| <p><b>Stick to Bucket Pin &amp; Bushings Photos</b></p> |   |
| <p><b>Turntable Bearing</b></p>                         |  |
| <p><b>Turntable Bearing Photos</b></p>                  | <p>3 - Normal Wear &amp; Tear</p>  |
| <p><b>Turntable Bearing Photos</b></p>                  |  |

## Inspection Report (Mini Excavator)

|                                 |  |  |
|---------------------------------|--|--|
|                                 |    |  |
| <b>Bottom Covers</b>            | 3 - Normal Wear & Tear   |  |
| <b>Bottom Covers Photos</b>     |   |  |
|                                 |  |  |
| <b>Overall Chassis</b>          | 3 - Normal Wear & Tear   |  |
| <b>Overall Chassis Comments</b> | Overall chassis in good condition with no obvious problems found.                    |  |




### Undercarriage Inspection Points

#### Rubber Track Undercarriage




|                      |                        |
|----------------------|------------------------|
| <b>Roller Frames</b> | 3 - Normal Wear & Tear |
|----------------------|------------------------|








### Inspection Report (Mini Excavator)

|                             |  |  |
|-----------------------------|--|--|
| <p>Roller Frames Photos</p> |    |  |
|                             |   |  |
|                             |  |  |

### Inspection Report (Mini Excavator)






|                          |  |
|--------------------------|--|
|                          |    |
|                          |   |
| <b>Track Belt</b>        | 3 - Normal Wear & Tear   |
| <b>Comments</b>          | Track belts above 60% of tread life left   |
| <b>Track Belt Photos</b> |  |

### Inspection Report (Mini Excavator)

|                                      |  |  |
|--------------------------------------|--|--|
|                                      |    |  |
|                                      |   |  |
|                                      |  |  |
| <b>Rubber Belt Drive Lugs</b>        | 3 - Normal Wear & Tear   |  |
| <b>Rubber Belt Drive Lugs Photos</b> |  |  |
|                                      |  |  |
| <b>Track Tensioners</b>              | 3 - Normal Wear & Tear   |  |
| <b>Front Idlers</b>                  | 3 - Normal Wear & Tear   |  |



## Inspection Report (Mini Excavator)




|                      |  |
|----------------------|--|
| Front Idlers Photos  |    |
|                      |    |
| Rear Idlers          | 0  |
| Track Rollers        | 3 - Normal Wear & Tear   |
| Track Rollers Photos |  |
| Sprockets            | 3 - Normal Wear & Tear   |
| Sprockets Photos     |  |
|                      |  |

## Hydraulics Overall Inspection Points




### Hydraulics Overall

|  |     |
|--|-----|
| Wet or Damp Hydraulic Lines / Fittings | Yes |
|--|-----|

### Inspection Report (Mini Excavator)


|  |  |
|--|--|
| <b>Appearance of Hydraulic Lines / Fittings</b>        | 3  |
| <b>Hydraulic Lines / Fittings Condition</b>            | Hydraulic lines & fittings are clean and in good condition, Active leaks in hoses or fittings observed, Other (see comments) |
| <b>Appearance of Hydraulic Lines / Fittings Photos</b> |    |
|  |   |
|  |    |

### Inspection Report (Mini Excavator)

|   |  |  |
|---|--|--|
|   |    |  |
|   |   |  |
| <b>Unusual Noises (Hydraulic Pump)</b>      | No   |  |
| <b>Hydraulic Pump Notes</b>                 | No unusual noises heard during operation   |  |
| <b>External Controls / Levers</b>           | 3  |  |
| <b>External Controls / Levers Condition</b> | Good function & condition of hydraulic controls                                      |  |
| <b>External Controls / Levers Photos</b>    |  |  |



## Inspection Report (Mini Excavator)



### Hydraulics Cylinders Inspection Points




|                             |   |
|-----------------------------|---|
| Boom Cylinder               | Check the boom cylinder. Note any wear, pitting, discoloration, etc. Take photos. |
| Boom Cylinder: Mounting Pin | 3   |
| Boom Cylinder: Oil Leaks    | No  |

### Inspection Report (Mini Excavator)

Boom Cylinder Photos






### Inspection Report (Mini Excavator)




|                                     |  |  |
|-------------------------------------|--|--|
|                                     |    |  |
|                                     |   |  |
| <b>Stick Cylinder</b>               | Check the stick cylinder. Note any wear, pitting, discoloration, etc. Take photos.   |  |
| <b>Stick Cylinder: Mounting Pin</b> | 3  |  |
| <b>Stick Cylinder: Oil Leaks</b>    | No   |  |
| <b>Stick Cylinder Photos</b>        |  |  |



### Inspection Report (Mini Excavator)

|                                      |  |  |
|--------------------------------------|--|--|
|                                      |    |  |
|                                      |   |  |
| <b>Bucket Cylinder</b>               | Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.  |  |
| <b>Bucket Cylinder: Mounting Pin</b> | 3  |  |
| <b>Bucket Cylinder: Oil Leaks</b>    | Yes  |  |
| <b>Comments</b>                      | Bucket cylinder leaks observed from hoses/fittings and possibly cylinder rod seal    |  |
| <b>Bucket Cylinder Photos</b>        |  |  |



### Inspection Report (Mini Excavator)

|                 |  |
|-----------------|--|
|                 |    |
|                 |   |
|                 |  |
| <b>Blade</b>    | Check the blade. Note any wear, pitting, discoloration, etc. Take photos.            |
| <b>Blade</b>    | 3  |
| <b>Comments</b> | Front right side of blade surface wear plate bent out                                |

## Inspection Report (Mini Excavator)

|              |  |
|--------------|--|
| Blade Photos |  |
|--------------|--|

## Bucket Inspection Points

|                  |  |
|------------------|--|
| Bucket Condition | 3 - Normal Wear & Tear   |
| Comments         | 2 buckets with machine are 8" and 12"  |
| Bucket Photos    |   |
|                  |  |



## Inspection Report (Mini Excavator)



|                        |                        |
|------------------------|------------------------|
| Bucket Hose & Fittings | 3 - Normal Wear & Tear |
| Bucket Cylinder        | 3 - Normal Wear & Tear |

### Blade Inspection Points

|                       |                        |
|-----------------------|------------------------|
| Blade Condition       | 3 - Normal Wear & Tear |
| Blade Edge            | 2 - Above Average Wear |
| Blade Hose & Fittings | 3 - Normal Wear & Tear |
| Blade Cylinder        | 3 - Normal Wear & Tear |

### Functional Test

|                                  |   |
|----------------------------------|---|
| Forward & Reverse                | 3 - Normal Wear & Tear  |
| Swing Table Rotation             | 3 - Normal Wear & Tear  |
| Boom Lift / Angle / Tilt         | 3 - Normal Wear & Tear  |
| Blade Functionality              | 3 - Normal Wear & Tear  |
| Overall Functional Test Comments | Overall machine functions well. No abnormal functioning observed and all implements in solid condition. |
| Operating Video                  | <a href="#">Click to Download</a>   |

### Overall Assessment

#### Overall Assessment

|                                |  |
|--------------------------------|--|
| Exterior Rating                | 3  |
| Interior Rating                | 3  |
| Safety Rating                  | 3  |
| Quality Rating                 | 3  |
| Functionality Rating           | 3  |
| Overall Rating                 | 3  |
| What's Great About the Machine | Machine works well and has 2 different buckets for digging. Engine and hydraulics well maintained and sound healthy under load. Machine displays low hours and relates to how machine functions normal. No obvious major repairs needed. |



## Inspection Report (Mini Excavator)

|                        |   |
|------------------------|---|
| <b>What Needs Work</b> | Bucket cylinder may need to be resealed. Hydraulic leaks at bucket cylinder needs attention. Lights inoperable. Front blade wear plate bent out and should be addressed for proper fitment. Minor seepage seen at engine fuel injector hardlines. |
| <b>Date/Time</b>       | 11-17-2022  |