

Inspection Report (Mini Excavator)

General Info

Year	2014
Make	Bobcat
Model	E85 M
Serial Number	B34T11776
Hour Meter Reading	2,232
Previous Application (e.g., earth moving, mining, demolition, etc)	General Construction

Dimensions

Measurement Guide	A B
A. Length (ft and inches)	20'6"
B. Width (ft and inches)	6'6"
C. Height (ft and inches)	8'4"
Operational Weight (lbs)	19,000 LBS.

Features and Configuration

Control Station Type	Cab
Bucket	Yes
Bucket Size (in inches)	36
Blade	Yes
Additional Attachment(s)	Yes
Hydraulic Coupler	No
Auxiliary Hydraulics	Yes
Hydraulic Thumb	No
Heat	Yes
A/C	Yes
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No
Other Configuration Details / Notes	Manual/Fixed bucket thumb included



Inspection Report (Mini Excavator)

Exterior Walkaround Photos

Exterior 360 Walkaround

Instructions

Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.

Must have shots to capture:

- Front
- 45 degree corner shot of left front
 45 degree corner shot of right front
 Left side
- Right side
- Rear
- 45 degree corner shot of left rear45 degree corner shot of right rear

Tips for good photos:
- Move the equipment into a open area without any visual distractions or other equipment in the background

Exterior Walkaround Photos
















Inspection Report (Mini Excavator)







General Appearance Inspection Points

General Appearance	
Front	3 - Normal Wear & Tear
Front Condition	No visible damage, Other (see comments)
Comments	Normal wear and tear



Inspection Report (Mini Excavator)


Front Photos


















Inspection Report (Mini Excavator)


Left Photos






















Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear
Body Panel Condition	Other (see comments)
Comments	Normal wear and tear scuff marks all the way around
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Glass Condition	3 - Normal Wear & Tear
Glass Condition Notes	Glass intact, no visible damage



Inspection Report (Mini Excavator)

Glass Condition Photos















Mirrors	3 - Normal Wear & Tear
Mirror Condition Notes	Mirrors present and intact, no visible damage
Lighting System	3 - Normal Wear & Tear
Lighting System Condition	No visible damage, lighting system is operational, One or more exterior lights are non-operational
Comments	R/S Boom light not working



Inspection Report (Mini Excavator)

Lighting System Photos





Control Station Inspection Points

Control Station

Serial Number Plate Photo




Operator Cabin Overall

3 - Normal Wear & Tear


Operator Cabin Overall Condition

Good cabin appearance, solid floors, panels, and ceiling





















Inspection Report (Mini Excavator)

Safety Lock Out / Stop Photos





Controls & Switches

Controls & Switches Condition


Controls & Switches Photos

3 - Normal Wear & Tear


All switches are installed and functional













Inspection Report (Mini Excavator)

Other Gauge Activity Photos	COOLANT FUEL LEVEL TOME CCO
Heater & A/C	3 - Normal Wear & Tear
Heater & A/C Condition	Heater and A/C work and transition through full temperature range
Fans / Vents	3 - Normal Wear & Tear
Fans / Vents Condition	Fan vents are functional, in good condition, and move through a full adjustable range of motion
Fans / Vents Photos	
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Fire Extinguisher	0
First Aid Kit	0

Engine Inspection Points

Engine	
Engine Type (Make, Model, Cylinders, Hp)	Yanmar - 4Cyl 4TNV98C - 3.3L - 66HP
Emissions Tier	Tier 4F



Engine Serial Number	05628
Engine Fuel Type	Diesel
Engine Photos	
















Inspection Report (Mini Excavator)



Radiator 3 - Normal Wear & Tear

Radiator Condition Radiator fins & components appear to be in good working order, no signs of damage or leaks

Radiator Photos









Belts 3 - Normal Wear & Tear	
Belt Condition Belts appear in good condition & alignment with proper tension	
Belt Photos	
D2I IIAO ROULUNDS B44 PROULUNDS B44 PAULUNDS B44	
Hoses 3 - Normal Wear & Tear	
Hose Condition Firm, pliant hoses with no signs of wear or leaks	












	And Impropried direct forms of the Control of the C
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
DPF Photos	
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Dusty & dry



Drivetrain Inspection Points	
Drivetrain	
Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear
Drive Motor Photos	




Inspection Report (Mini Excavator)




Chassis Inspection Points

Boom Condition	3 - Normal Wear & Tear
Boom Photos	31776 Robcol































Inspection Report (Mini Excavator)







Overall Chassis

3 - Normal Wear & Tear

Overall Chassis Comments

Overall chassis in good condition. No major issues found.

Undercarriage Inspection Points

Rubber Track Undercarriage

Roller Frames

3 - Normal Wear & Tear



Inspection Report (Mini Excavator)


Roller Frames Photos

























Rubber Belt Drive Lugs


Rubber Belt Drive Lugs Photos

3 - Normal Wear & Tear
















Inspection Report (Mini Excavator)

Track Rollers Photos









Inspection Report (Mini Excavator)





Sprockets

Sprockets Photos

3 - Normal Wear & Tear





Inspection Report (Mini Excavator)







Hydraulics Overall Inspection Points

Hydraulics Overall	
Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition



Inspection Report (Mini Excavator)


Appearance of Hydraulic Lines / Fittings Photos























Inspection Report (Mini Excavator)

External Controls / Levers Photos










Inspection Report (Mini Excavator)



Hydraulics Cylinders Inspection Points

Hydraulics Cylinders Insp	pection Points
Boom Cylinder: Mounting Pin	3 - Normal Wear & Tear
Boom Cylinder: Oil Leaks	No
Boom Cylinder Photos	








Stick Cylinder Photos	
Bucket Cylinder: Mounting Pin	3 - Normal Wear & Tear
Bucket Cylinder: Oil Leaks	Yes
Comments	Residual oil observed from rod seal indicating possible oil leak
Bucket Cylinder Photos	S25b







Inspection Report (Mini Excavator)



Bucket Inspection Points

Bucket inspection Poir	IIS
Bucket Condition	3 - Normal Wear & Tear
Comments	36" inch and 18"
Bucket Photos	
Bucket Hose & Fittings	3 - Normal Wear & Tear

Blade Inspection Points



Blade Photos	
Blade Edge	3 - Normal Wear & Tear
Blade Hose & Fittings	3 - Normal Wear & Tear
Blade Hose & Fittings Photos	
Blade Cylinder	3 - Normal Wear & Tear



Inspection Report (Mini Excavator)

Blade Cylinder Photos





Additional Attachment Inspection Points

Additional Attachment(s)

Additional Attachments

Attachment Type	Manual, fixed bucket thumb
Attachment Condition	3 - Normal Wear & Tear

Functional Test

Forward & Reverse	3 - Normal Wear & Tear
Swing Table Rotation	3 - Normal Wear & Tear
Boom Lift / Angle / Tilt	3 - Normal Wear & Tear
Blade Functionality	3 - Normal Wear & Tear
Overall Functional Test Comments	Overall all machines functions operating well. No major problems observed.
Operating Video	Click to Download

Overall Assessment

Overall Assessment	
Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear



Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal Wear & Tear
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	Machine in great condition and well maintained with only 2,232 hours. Plenty of life left on this machine and no major obvious problems observed. Engine, hydraulics and undercarriage in great shape.
What Needs Work	Stick to bucket coupler has excess play. Cosmetic damage to front left side bumper. Possible leak at bucket cylinder. One boom work light inoperable.
Date/Time	12-07-2022