


#### **Inspection Report (Vibratory Compactor)**

#### **General Info**

Year	2012
Make	Bomag
Model	BMP 8500
Serial Number	101 720 11 2686
Hour Meter Reading	562 Hours
Previous Application (e.g., earth moving, mining, demolition, etc)	General Construction

#### **Dimensions**



#### **Features and Configuration**


reatures and Configuration	
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Drum System	Dual Drum
Padfoot Roller?	Yes
Vibration Frequency (Hz)	42 HZ
Centrifugal Force - Low/High (lbs)	16,186/8,093 Lbs.
Water Spray System	N/A

## **OMM Specifications**



## **Inspection Report (Vibratory Compactor)**

**OMM Specifications** 



**Exterior 360 Walkaround** 

**Exterior 360 Walkaround** 



#### **Inspection Report (Vibratory Compactor)**

#### Instructions

Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.

Must have shots to capture:

- 45 degree corner shot of left front 45 degree corner shot of right front
- Left side
- Right side
- Rear
- 45 degree corner shot of left rear45 degree corner shot of right rear

Tips for good photos:
- Move the equipment into a open area without any visual distractions or other equipment in the background

#### **Exterior Walkaround Photos**















# **Inspection Report (Vibratory Compactor)**





## **General Appearance Inspection Points**

General Appearance	
Front	3 - Normal Wear & Tear
Front Condition	Other (see comments), No visible damage
Rear	3 - Normal Wear & Tear
Rear Condition	No visible damage, Other (see comments)
Left	3 - Normal Wear & Tear
Left Condition	Other (see comments), No visible damage
Right	3 - Normal Wear & Tear
Right Condition	No visible damage, Other (see comments)
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage, Other (see comments)
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear
Body Panel Condition	Other (see comments)
Comments	Scuff marks on engine and hydraulic compartment hoods



# **Inspection Report (Vibratory Compactor)**

# Body Panels Photos









## **Inspection Report (Vibratory Compactor)**



Doors / Canopy Latches

Doors / Canopy Latches Photos

3 - Normal Wear & Tear




Steps / Ladders	0
Handrails	0
Glass Condition	0
Mirrors	0
Lighting System	0

## **Control Station Inspection Points**

#### **Control Station**








Controls & Switches Condition	All switches are installed and functional
Controls & Switches Photos	
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Hour Meter Activity Photos	BOMBS BOMBS
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Other Gauge Activity Photos	E. C.
Heater & A/C	0
Fans / Vents	0




Travel Alarm	0
Horn	0
Backup Camera	0
Fire Extinguisher	0
First Aid Kit	0

<b>Engine Inspection Points</b>	
Engine	
Engine Type (Make, Model, Cylinders, Hp)	Kubota - D1005-ET06 - 3Cyl 19HP
Emissions Tier	Tier 4F
Engine Serial Number	CD0998
Engine Fuel Type	Diesel
Engine Photos	
	BOOM &











Radiator Photos	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Belt Photos	
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No




## **Inspection Report (Vibratory Compactor)**

Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry, Dusty & dry
Overall Engine Comments	Overall engine in great condition. No major problems seen and well maintained.


#### **Drivetrain Inspection Points**

Drivetrain Commence of the Com	
Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain in great condition.


#### **Chassis Inspection Points**




























#### **Inspection Report (Vibratory Compactor)**

# **Drum Scraper Photos Padfoot Feet Condition** 3 - Normal Wear & Tear **Padfoot Fitment** 3 - Normal Wear & Tear 0 **Padfoot Hardware Overall Chassis** 3 - Normal Wear & Tear Overall chassis in great condition. Chassis holding together well and no issues **Overall Chassis Comments**

## **Hydraulics Overall Inspection Points**

Hydraulics Overall	
Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition



# **Inspection Report (Vibratory Compactor)**


Appearance of Hydraulic Lines / Fittings Photos


















## **Inspection Report (Vibratory Compactor)**

External Controls / Levers Photos



# **Hydraulics Cylinders Inspection Points**

Steering Cylinders	Check the steering cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinders: Mounting Pin	3
Steering Cylinders: Oil Leaks	No

Steering Cylinders Photos



## **Functional Test**

Forward & Reverse	3 - Normal Wear & Tear
Steering	3 - Normal Wear & Tear
Vibratory System	3 - Normal Wear & Tear
Front Drum	3 - Normal Wear & Tear
Rear Drum	3 - Normal Wear & Tear
Overall Functional Test Comments	All functions work properly. Machine showed no signs of issues with powertrain or vibratory system.
Operating Video	Click to Download

#### **Overall Assessment**

Overall Assessment	
Exterior Rating	3



Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	Machine has low hours and it shows. Engine and hydraulics in great condition with no active leaks observed. Machine is controlled by wireless remote and it makes this machine safe and easier to use in tight areas.
What Needs Work	Minor cosmetic scuff marks all around.
Date/Time	12-08-2022