Rivera Hauling

TRUCK AND EQUIPMENT CONSULTING LLC - TRACK LOADER SKID STEER CHECKLIST Date (Y/M/D Inspector

12/13/2022

L.W.

(Basic Information)					
(Manufacturer)	John Deere				
(Model Number)	323E				
(Serial Number)	1T0323EAHJJ325941				
(Year of Manufacturing)	2018				
(Hour Meter Reading)	558.9 HRS				
(Transmission/Drive)	Std Single Speed Hydrostatic				
(Engine Model) TIER 4	Yanmar 4TNV98CT 3.3L 70Hp I4 TurboD				
(Hydraulic System Capacity)	6.6 gal				
(Hydraulic Relief)	3250 psi / Std 18 gal per min				

Specification and Dimensions					
Serial Plate/Frame Inscription		1T0323EAHJJ325941			
Cabin•Canopy	(Circle)	Canopy w/Rear Glass + Side Grilles			
EPA Certificate / Permits Posted	ł	ROPS / FOPS			
Tipping Load		7400 lbs			
Track Rollers		Track Rollers =4 / Track Idlers =2 (per side)			
Fluid Capacities		Eng Oil = 3.4 gal Fuel =20 gal			
Load Capacity		2590 lbs (Rated Operating Capacity)			
Dump Height		8 Ft 2 in			
Operating Weight		9400 lbs			
Track Width		Rubber / Std 12.6 in width			
Ground Pressure		5.7 psi			
Attachments s/n 0001098		T76 76 in bucket 18.5 Ft3			

Initials

A (Near to Brand New or Excellent Condition)

B (A little Wear and Good Condition)

C (Fair Workable Condition for Hour Meter Reading)

D (Workable but minor repair is required)

E (Workable but major repair is required)

	(Check List)	А	В	С	D	Е	(Remarks)
GENERAL	(General Appearance-Front)		Х				Good appearance front components,panels+panel gaps ,no damage
APPEARANCE	(General Appearance-Rear)		Х				Good appearance rear components,panels+panel gaps, no damage
	(General Appearance-Right)		Х				Good panels+panel gaps, Some surface cosmetics scrapes +scratches
	(General Appearance-Left)		Х				Good panels+panel gaps, Some surface cosmetics scrapes +scratches
	(General Appearance-Upper)		Х				Upper cab surfaces,roof panels+engine covers+panels Good condition
	(Major / Minor Surface Rust)		Х				Some surface rust on idler, rollers No rust damage
	(Body Panel Rust Damage / Cancer)		Х				No panel damage No dents No dings No rust damage or cancer
	(Visible Weld Repairs / Stress Cracks)		Х				No patches or panels damages seen
	(Glass / Polycarbonate ? Condition ?)		Х				Rear Glass Good appearance No Front or Side glass
	(Chassis / Undercarriage Damage)		Х				Good appearance underside panels Dry appearance
	(Operator Cabin)		Х				Clean and straignt Solid floors,Good panels+gaos, Good joysticks
OPERATOR'S	(Operator Controls and Switches)		Х				Good appearance Operator controls Complete and working
COCKPIT	(Hour Meter Activity)		Х				Working
	(Other Gauge Activity)		Х				Working
	(Door / Canopy Latches)		Х				Engine cover panel+latches Good function
	(Safety – Horn / First Aid Kit)		Х				Good function
	(Operator Seat Condition)		Х				Seat Good Condition
	(Safety – Seat Belts / Fire Extinguisher)		Х				Yes
ENGINE	(Oil Color / Fluid Appearance / Particulates or Granuales)		Х				Clean + Dry Good appearance No blow by seen at operating temps
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		Х				Easy start Smooth Idle No unusual engine noise at startup or shut down
	(Engine Exhaust Color – White / Blue / Black / Clear)		Х				Clear Clear at operating temp
	(Oil Leaks)		Х				No active oil leaks seen from engine
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		Х				No smoke issues at start up or when hot
	(Coolant Color / Fluid Appearance)		Х				Good appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		Х				No noises from cooling system
	(Coolant Leaks from Radiator)		Х				No radiator leaks seen Good appearance of fins
	(Overall Engine Appearance Clean / Wet / Dry)		Х				Clean and Dry appearance
	(Other)		Х	Х			Hydraulic tank level low
	(Overall appearance of Hydraulic lines/fittings - worn/cracked)		Х				Good appearance No dried seepages No fraying Dry+clean fittings
HYDRAULICS	(Hydraulic Pump Sounds / Noises)		Х				Smooth No unusual hydraulic clicking or pump noises or vibrations
OVERALL	Wet or Damp hydraulic lines and fittings / fluid leaks)		Х				No active leaks No dried seepages Pistons no discoloration no pitting
	(External Controls / Levers Condition)		Х				Working
	(Hydraulics Service Records / Maintenance History)						not marked or provided

Sylmar, CA

	(Lighting Sy	stem Condition)		Х			Lights Working
1	(Reverse Alarm / Backup Signal)						N/A
ELECTRICAL	(Battery Condition)			Х			Battery compartment, battery + posts looks good
	(Other Electric Device Condition)		Х			Driver display clear and sharp No diagnostic codes No service codes	
	(Foot Brake)			Х			Good brake function
BRAKES	(Inching Brake Functional & Working Condition)			Х			Good function
	(Parking Brake)			Х			Good function
	(Other Remarks)						
	(Clutch Nois	e / Function)		Х			Smooth Shifting No unusual noises
TRANSMISSION	(Transmission Noise / Function)			Х			Good Forward and Reverse Function
	(Shift Lever Condition & Function)			Х			Shifter Good Appearance
	(Other Rem	arks)					
	(Lift)	(Oil Leak from C	Cylinder)	Х			No active leaks seen
	(LITT)	(Mounting Pin C	ondition)	Х			Good appearance No wear issues
HYDRAULICS	(Bucket)	(Oil Leak from C	Cylinder)	Х			No active leaks seen
CYLINDERS	(Ducket)	(Mounting Pin C	Condition)	Х			Good appearance No wear issues
	(Steering)	(Oil Leak from		Х			No active leaks seen
		(Mounting Pin Condition)		Х			Good appearance No wear issues
		(Other Remarks	.)	Х			Good appearance No wear issues
	(Transom /	Boom / Arm Fun	nction / Noise)	Х			Quiet Lift + Drop No unusual noises Smooth function
	(Slack in Pins / Loose Pins / Soft Bushings)		Х			No vibration or noise	
		e and alignment)		Х			Level Stance
		Roller/Idler App			Х		R/Track Surfaces show wear+tear, surfaces uneven with some rust
& COMPONENT	NT (Left Track Roller/Idler Appearance) (Track Side Guards Appearance)			Х		L/Track Surfaces show wear+tear, surfaces uneven with some rust	
			nce)		Х		R+L Track side guards heavy scrapes + scratches
	TRACKS	(Right)	Right Upper Appearance		Х		R / Upper Rubber tracks show heavy wear+tear C/C+
		(Tright)	Right Lower Appearance		Х		R/ Lower Rubber tracks show heavy wear+tear C/C+
		(Left)	Left Upper Appearance		Х		L / Upper Rubber tracks show heavy wear+tear C/C+
		(Left Lower Appearance		Х		L/ Lower Rubber tracks show heavy wear+tear C/C+
	(Tracks Overall Condition)				Х	Х	Undercarriage screeching+squeeling noises See Video
	(Overall Appearance)		Х			Bucket Good appearance No dings No dents No damage	
Attachment	(Bucket Edge)			Х			Good appearance
	(Bucket Articulation)			Х			Good articulation of hydraulics
	(Bucket Performance Vibrations ? Noises ?)			Х	1		Good Lift + Drop Performance

OVERALL EXTERIOR RATING: <u>B/B-</u> OVERALL INTERIOR RATING: <u>B</u> OVERALL PERFORMANCE: C/C+ OVERALL EVALUATION GRADE: C+

QUALITY: <u>C+</u> SAFETY: <u>B</u> FUNCTIONALITY: B

FLUID ANALYSIS RECOMMENDED (Y/N) _n_ OIL _n_ COOLANT _n_

TRANSPORT DIMENSIONS:

Length: 11 Ft 5 in (w/bucket) Width: 6 Ft Height: 6 Ft 9 in Weight: 9440 lbs

*A:Remaining Ratio *B:Remaining Ratio *C:Remaining Ratio *D:Remaining Ratio *E:Remaining Ratio

90% or more 70% or more 50% or more 20% or more 20% or less