

Inspection Report (On-Highway Truck Cab + Chassis)

General Info

Year	2014
Make	Kenworth
Model	T800
Serial Number	1XKDDP9X9EJ387099
Truck Odometer Reading	410,503
Current Inspection / State Cert / DOT	Last Performed 8/2022 In Accordance with 49CFR,Part 396, FMCSR
Previous Application (e.g., earth moving, mining, demolition, etc)	Equipment Rental Hauler

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	24'6"
Width (ft and inches)	8'3"
Height (ft and inches)	11'
Wheelbase (ft and inches)	15'6"
GVWR (lbs)	52,350lbs.

Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
PTO Details	Trans mounted
Engine Brake	Yes
Engine Brake Configuration	2 Position
Differential Lock	Yes
OMM (Operator & Maintenance Manual)	No
Telematics	Yes
Auxiliary Engine	No
Liftgate	No

Inspection Report (On-Highway Truck Cab + Chassis)

Other Configuration Details / Features / Notes	5th wheel Hitch
--	-----------------

Exterior 360 Walkaround

Exterior 360 Walkaround

Instructions	Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components. Must have shots to capture: - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear Tips for good photos: - Move the equipment into a open area without any visual distractions or other equipment in the background	
Exterior Walkaround Photos		
		

Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



General Appearance Inspection Points

General Appearance

Inspection Report (On-Highway Truck Cab + Chassis)

Close-up Exterior Photos



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)




Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)

	
	
	
Body Panels	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment, Other (see comments)
Comments	Center of front bumper dented in, rear tire mudguards bent

Inspection Report (On-Highway Truck Cab + Chassis)

Body Panels Photos		
		
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Bent or broken steps or rungs	
Steps / Ladders Photos		
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	3 - Normal Wear & Tear	


Inspection Report (On-Highway Truck Cab + Chassis)

Glass Condition	Glass intact, no visible damage
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational, Other (see comments)
Comments	A few small, roof mounted running lights, inoperable, rear right signal light inoperable
Exterior Lights Photos	
	
	

Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Cab Inspection Points

On Highway - Cab

VIN/Serial Number Plate Photo



Odometer Photo



Inspection Report (On-Highway Truck Cab + Chassis)

Cab Interior Photos



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)

		
		
		
Odometer Activity	3 - Normal Wear & Tear	
Odometer Condition	Odometer is working and in good condition	
Controls/Switches/Gauges	3 - Normal Wear & Tear	
Controls/Switches/Gauges Condition	All switches/gauges are in good condition and functioning	
Horn	3 - Normal Wear & Tear	
Horn Condition	Horn is functioning as expected	
Reverse Alarm / Backup Camera	3 - Normal Wear & Tear	

Inspection Report (On-Highway Truck Cab + Chassis)

Reverse Alarm / Backup Camera Condition	Reverse alarm working as expected
Heater & A/C	3 - Normal Wear & Tear
Heat & A/C Condition	Heater and A/C work as expected
Interior Lights	3 - Normal Wear & Tear
Interior Lights Condition	All interior lights are installed and functioning
Seats/Seat Belts	3 - Normal Wear & Tear
Seats/Seat Belt Condition	Seat(s) has major surface staining or tears
Cab Interior Overall Rating	2 - Above Average Wear
Comments	Rated two only because Both seats have large stains ,broken switches and air brake knob's worn

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	Paccar - 6CYL. - 430HP - 12.9L
Emissions Tier	Tier 4F
Engine Serial Number	Y022932
Engine Fuel Type	Diesel
Engine Photos	

Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)






Inspection Report (On-Highway Truck Cab + Chassis)

		
		
Blow-by (Visual Observation Check)	Yes	
Comments	Very minor blowby seen	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Unusual Noise Notes	No unusual noises heard	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke Notes	No engine smoke issues observed	
Engine Exhaust Color	Clear	
Battery	1 - Service Required	
Battery Condition	Needs charge or replacement, Other (see comments)	
Comments	Should be replaced soon	

Inspection Report (On-Highway Truck Cab + Chassis)

Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	
	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension

Inspection Report (On-Highway Truck Cab + Chassis)

Belt Photos	
	
	
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination

Inspection Report (On-Highway Truck Cab + Chassis)

Oil Leaks	Yes
Oil Leak Notes	Other (see comments), Dried oil seepages seen
Comments	Possible oil seepage at valve cover and oil pan (around breather tube)
Oil Leak Photos	
	
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear

Inspection Report (On-Highway Truck Cab + Chassis)

DPF Photos	
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
DEF Tank Photos	
	
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	Overall engine well maintained, minor seepage at valve cover breather.

Drivetrain Inspection Points

Drivetrain

Inspection Report (On-Highway Truck Cab + Chassis)

Transmission Info (Make/Model)	Eaton Fuller 13 Speed
Drive Type	4X6
Overdrive	No
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations
Transmission Condition Photos	
	
	
Clutch	3 - Normal Wear & Tear
Clutch Condition	Clutch is functioning as expected

Inspection Report (On-Highway Truck Cab + Chassis)

Shift Lever	3 - Normal Wear & Tear
Shift Lever Condition	Good forward and reverse function
Differential	Check condition of the differential(s). Take photos and notes as relevant.
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation
Rear Differential Photos	
	
Front Differential	3 - Normal Wear & Tear
Front Differential Condition	Dried seepages seen on differential housing cover, Other (see comments)
Front Differential Photos	

Inspection Report (On-Highway Truck Cab + Chassis)

		
		
Brake System Type	Air Brakes	
Air Brakes Build Correct Pressure	Yes	
Air Brake System Leaks	Yes	
Comments	Minor air leak engine compartment firewall area	
Air Brake Hose Condition	3 - Normal Wear & Tear	
Air Brake System Photos		

Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)

	
Foot Brake	3 - Normal Wear & Tear
Foot Brake Condition	Good brake function
Engine Brake Configuration	2 Position
Engine Brake	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain in good condition.

Chassis & Axle Inspection Points

Chassis

Frame

Frame Condition	3
Frame Photos	

Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)

Suspension

Suspension	3
Suspension Photos	

Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Steering

Steering Components	3
Steering Components Photos	
	

Inspection Report (On-Highway Truck Cab + Chassis)

		
		
Steer Axle Condition	3	
Steer Axle Photos		

Wheels & Tires

Wheels & Hub Condition	3
Wheel Seal Leaks	No
Tire Brand	Front - Goodyear
Tire Size	11R-22.5
Front Left Tire - Ratio Remaining	90%

Inspection Report (On-Highway Truck Cab + Chassis)

Front Left Tire Photos	
Front Right Tire - Ratio Remaining	50%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	30%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	50%


Inspection Report (On-Highway Truck Cab + Chassis)

Rear Left Tire Photos		
		

Brake Components

Brake Shoe Thickness	90%
Comments	All brake shoes above 80%
Brake Shoe Photos	

Inspection Report (On-Highway Truck Cab + Chassis)



Overall Chassis Condition

Overall Chassis	3
Overall Chassis & Undercarriage Photos	

Inspection Report (On-Highway Truck Cab + Chassis)

	
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.

Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Engine	3 - Normal, Operating as Expected
Controls	3 - Normal, Operating as Expected
Overall Functional Test Comments	Overall all functions work well
Operating Video	Click to Download

Inspection Summary

Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	For having over 400,000 miles the truck is in great condition. This truck has been well maintained. Most tires have plenty of life left. All brakes have plenty of brake shoe material left.
What Needs Work	Minor cosmetic damage to front bumper and rear mudguards. Pro switch exterior cracked. Front windshield may need to be replaced soon. New batteries possibly needed and or minor electrical draw. (Batteries we're low on charge)
Any Additional Info from the Seller?	GPS to stay on truck
Date/Time	12-20-2022