

## Inspection Report (On-Highway Flatbed Truck)

### General Info

Year	2015
Make	Ford
Model	F750XLT
Serial Number	3FRXF7FE0FV662351
Truck Odometer Reading	193,992
Current Inspection / State Cert / DOT	Last performed 6/2020
Previous Application (e.g., earth moving, mining, demolition, etc)	Compact Rentals Equipment Tow/Hauler

### Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	34' (Total) 24' bed
Width (ft and inches)	8'6"
Height (ft and inches)	8'6"
Wheelbase (ft and inches)	20'4"
GVWR (lbs)	33,000



### Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
Engine Brake	No
Differential Lock	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Auxiliary Engine	No
Liftgate	No
Other Configuration Details / Features / Notes	24' Hydraulic Rollback Flatbet

### Exterior 360 Walkaround

## Inspection Report (On-Highway Flatbed Truck)

### Exterior 360 Walkaround

<p><b>Instructions</b></p>	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> <li>- Front</li> <li>- 45 degree corner shot of left front</li> <li>- 45 degree corner shot of right front</li> <li>- Left side</li> <li>- Right side</li> <li>- Rear</li> <li>- 45 degree corner shot of left rear</li> <li>- 45 degree corner shot of right rear</li> </ul> <p>Tips for good photos:</p> <ul style="list-style-type: none"> <li>- Move the equipment into a open area without any visual distractions or other equipment in the background</li> </ul>
<p><b>Exterior Walkaround Photos</b></p>	
	

### Inspection Report (On-Highway Flatbed Truck)



## Inspection Report (On-Highway Flatbed Truck)



### General Appearance Inspection Points

#### General Appearance



## Inspection Report (On-Highway Flatbed Truck)

Close-up Exterior Photos



**Inspection Report (On-Highway Flatbed Truck)**



**Inspection Report (On-Highway Flatbed Truck)**





Inspection Report (On-Highway Flatbed Truck)








Inspection Report (On-Highway Flatbed Truck)




Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

		
<b>Body Panels</b>	3 - Normal Wear & Tear	
<b>Body Panel Condition</b>	No visible damage, good paint condition and panel fitment, Other (see comments)	
<b>Comments</b>	Minor fiberglass damage to front left side of hood, small dent center of front bumper	
<b>Body Panels Photos</b>		
		

## Inspection Report (On-Highway Flatbed Truck)

	
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational

### Cab Inspection Points

#### On Highway - Cab

VIN/Serial Number Plate Photo	
-------------------------------	--



### Inspection Report (On-Highway Flatbed Truck)

<p>Odometer Photo</p>	
<p>Cab Interior Photos</p>	
	

Inspection Report (On-Highway Flatbed Truck)



**Inspection Report (On-Highway Flatbed Truck)**






**Inspection Report (On-Highway Flatbed Truck)**








### Inspection Report (On-Highway Flatbed Truck)



**Inspection Report (On-Highway Flatbed Truck)**



## Inspection Report (On-Highway Flatbed Truck)

	
	
<b>Odometer Activity</b>	3 - Normal Wear & Tear
<b>Odometer Condition</b>	Odometer is working and in good condition
<b>Controls/Switches/Gauges</b>	3 - Normal Wear & Tear
<b>Controls/Switches/Gauges Condition</b>	All switches/gauges are in good condition and functioning
<b>Horn</b>	3 - Normal Wear & Tear
<b>Horn Condition</b>	Horn is functioning as expected
<b>Reverse Alarm / Backup Camera</b>	3 - Normal Wear & Tear
<b>Reverse Alarm / Backup Camera Condition</b>	Reverse alarm working as expected
<b>Heater &amp; A/C</b>	3 - Normal Wear & Tear
<b>Heat &amp; A/C Condition</b>	Heater and A/C work as expected
<b>Interior Lights</b>	3 - Normal Wear & Tear
<b>Interior Lights Condition</b>	All interior lights are installed and functioning
<b>Seats/Seat Belts</b>	3 - Normal Wear & Tear
<b>Seats/Seat Belt Condition</b>	Seat(s) in good condition, no stains or tears in upholstery
<b>Cab Interior Overall Rating</b>	3 - Normal Wear & Tear






## Inspection Report (On-Highway Flatbed Truck)

Comments	Cabin in good condition just recommend a detail wash
----------	--

### Engine Inspection Points

#### Engine




Engine Type (Make, Model, Cylinders, Hp)	Cummins - ISB 6.7L - 6CYL. - 280HP
Emissions Tier	Tier 4i
Engine Serial Number	73689724
Engine Fuel Type	Diesel
Engine Photos	  





Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)




	
	
	
<b>Blow-by (Visual Observation Check)</b>	Yes
<b>Comments</b>	Minor (normal) blowby seen at tube
<b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b>	No
<b>Unusual Noise Notes</b>	No unusual noises heard
<b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>	No
<b>Engine Smoke Notes</b>	No engine smoke issues observed

## Inspection Report (On-Highway Flatbed Truck)

Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections, Dusty & dirty appearance
Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	




### Inspection Report (On-Highway Flatbed Truck)




		
<b>Belts</b>	3 - Normal Wear & Tear	
<b>Belt Condition</b>	Belts appear in good condition & alignment with proper tension	
<b>Belt Photos</b>		
		
<b>Hoses</b>	3 - Normal Wear & Tear	
<b>Hose Condition</b>	Firm, pliant hoses with no signs of wear or leaks	
<b>Water Pump</b>	3 - Normal Wear & Tear	
<b>Water Pump Condition</b>	No unusual pump noises heard	
<b>Cooling System Leaks</b>	No	



## Inspection Report (On-Highway Flatbed Truck)

Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
DPF Photos	



### Inspection Report (On-Highway Flatbed Truck)

	
<b>Requires DEF (Diesel Exhaust Fluid)</b>	Yes
<b>DEF Tank</b>	3 - Normal Wear & Tear
<b>DEF Tank Condition</b>	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
<b>DEF Tank Photos</b>	
	
<b>Overall Engine Appearance</b>	Clean & dry
<b>Overall Engine Comments</b>	Overall engine in great condition




### Drivetrain Inspection Points

#### Drivetrain

## Inspection Report (On-Highway Flatbed Truck)




Transmission Info (Make/Model)	Ford 5Speed Automatic
Drive Type	4X2
Overdrive	N/A
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations
Transmission Condition Photos	
Clutch	0
Shift Lever	3 - Normal Wear & Tear
Shift Lever Condition	Good forward and reverse function
Differential	Check condition of the differential(s). Take photos and notes as relevant.
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation
Rear Differential Photos	

### Inspection Report (On-Highway Flatbed Truck)

	
	
<b>Front Differential</b>	0
<b>Brake System Type</b>	Air Brakes
<b>Air Brakes Build Correct Pressure</b>	Yes
<b>Air Brake System Leaks</b>	Yes
<b>Comments</b>	Very minor leaks noticed after truck has been off and parked a while
<b>Air Brake Hose Condition</b>	3 - Normal Wear & Tear
<b>Air Brake System Photos</b>	



### Inspection Report (On-Highway Flatbed Truck)




	
	
	
<b>Engine Brake Configuration</b>	N/A
<b>Parking Brake</b>	3 - Normal Wear & Tear
<b>Parking Brake Condition</b>	Good brake function
<b>Overall Drivetrain Comments</b>	Overall Drivetrain I'm good condition with no problems observed.

### Chassis & Axle Inspection Points


#### Chassis & Tires

#### Frame

### Inspection Report (On-Highway Flatbed Truck)

Frame Condition	3
Frame Photos	
	
	

### Inspection Report (On-Highway Flatbed Truck)



### Suspension

Suspension	3
Suspension Photos	



Inspection Report (On-Highway Flatbed Truck)










### Inspection Report (On-Highway Flatbed Truck)



### Steering

Steering Components	3
Steering Components Photos	
	




### Inspection Report (On-Highway Flatbed Truck)

		
		
<b>Steer Axle Condition</b>	3	
<b>Steer Axle Photos</b>		

### Wheels & Tires




<b>Wheels &amp; Hub Condition</b>	3	
-----------------------------------	---	--

### Inspection Report (On-Highway Flatbed Truck)

Wheels & Hub Photos		
		
Wheel Seal Leaks	No	
Tire Brand	Front-Sumitomo. Rear - Hankook	
Tire Size	275/70R/22.5	
Front Left Tire - Ratio Remaining	10%	
Front Left Tire Photos		
Front Right Tire - Ratio Remaining	70%	



### Inspection Report (On-Highway Flatbed Truck)

Front Right Tire Photos		
Rear Right Tire - Ratio Remaining	10%	
Rear Right Tire Photos		
Rear Left Tire - Ratio Remaining	10%	
Rear Left Tire Photos		

### Brake Components




Brake Shoe Thickness	50%
Comments	Actual brake shoe thickness unknown (covers in place)

### Overall Chassis Condition

Overall Chassis	3
-----------------	---



## Inspection Report (On-Highway Flatbed Truck)

Overall Chassis Comments	Overall chassis in good condition
Overall Chassis & Undercarriage Photos	
	
	
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.




### Additional Inspection Points

#### On-Highway Flatbed Truck

#### Flatbed Additional Inspection Points

Flatbed Body	Check the condition of the flat bed body. Note any damage or wear. Take photos.
--------------	---

## Inspection Report (On-Highway Flatbed Truck)

<b>Bed Details (Deck Type, Additional Features)</b>	Century 16,000LBs. (Capacity)
<b>Flatbed Length (ft and inches)</b>	24'
<b>Flatbed Width (ft and inches)</b>	8'6"
<b>Flatbed Body</b>	3
<b>Flatbed Body Photos</b>	
	
	

Inspection Report (On-Highway Flatbed Truck)





Inspection Report (On-Highway Flatbed Truck)








Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

		
		
<b>Tailgate Latch</b>	0	
<b>Support Frame</b>	3	
<b>Support Frame Photos</b>		

Inspection Report (On-Highway Flatbed Truck)





## Inspection Report (On-Highway Flatbed Truck)



### Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Engine	3 - Normal, Operating as Expected
Controls	3 - Normal, Operating as Expected
Overall Functional Test Comments	Overall all functions on truck work fine
Operating Video	<a href="#">Click to Download</a>

### Inspection Summary

#### Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	Truck is in good condition. Engine and transmission solid with no active leaks found. Truck well maintained and rear bed functions well.
What Needs Work	Most tires need to be replaced. Rear bad body back ribs bent. Minor cosmetic damage to front hood and bumper. Cab could use a detail wash.
Date/Time	12-21-2022