


General Info

Year	1980
Make	Grove
Model	RT980 -80
Serial Number	45308
Hour Meter Reading	2,612 (hours not accurate)
Previous Application (e.g., earth moving, mining, demolition, etc)	Boring Equipment Industry

Dimensions



Features and Configuration

Control Station Type	Enclosed Cab
Heat	No
A/C	No
Radio	No
Backup Camera	No



Telematics	No
Load Movement Indicator (LMI)	Yes
LMI Make/Model	On machine but Inoperable. No power connected, May need calibration (Per Operator)
Boom Type	Hydraulic Telescoping
Jib?	No
Crane Capacity (tn)	80 Tons
Max Reach (ft and inches)	114'
# Boom Sections	3
Winch System	Dual Winch
Outriggers	Yes
OMM (Operator & Maintenance Manual)	Yes


OMM Specifications

OMM Specifications


Detail Specifications
Take photos of the detailed spec pages included in the operator's manual

OMM Spec Photos
Image: Detail Specification Specif
















Exterior 360 Walkaround

Exterior 360 Walkaround	
Instructions	Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components. Must have shots to capture: - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear
	equipment in the background


























General Appearance Inspection Points

General Appearance	
Front	3 - Normal Wear & Tear
Front Condition	No visible damage
Front Photos	




























Rear	3 - Normal Wear & Tear
Rear Condition	No visible damage
Left	3 - Normal Wear & Tear
Left Condition	No visible damage
Right	3 - Normal Wear & Tear
Right Condition	No visible damage
Upper	3 - Normal Wear & Tear
Upper Condition	Large dents or cracks, No visible damage, Other (see comments)
Comments	Only damage seen near air filter panel
Upper Photos	











Body Panels Photos	
Doors / Canopy Latches	2 - Above Average Wear
Doors / Canopy Latches Condition	No visible damage, Intermittent sticking observed on one or more latches/doors, Other (see comments)
Comments	Most latches normal wear and sticking to lock back in place
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound




Glass Condition	3 - Normal Wear & Tear
Glass Condition Notes	Glass intact, no visible damage
Mirrors	3 - Normal Wear & Tear
Mirror Condition Notes	Mirrors present and intact, no visible damage
Lighting System	2 - Above Average Wear
Lighting System Condition	One or more exterior lights are non-operational

Control Station Inspection Points


Control Station

Serial Number Plate Photo	CROVE Hydraulic CRANE MOLE RT-980 SERIAL A6308 CROVE MANUFACTURING CO. SHADY GROVE, PA. U.S.A.
Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling, Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling, Other (see comments)
Comments	Normal wear observed but overall in good condition
Operator Cabin Photos	
























































Operator's Seat & Arm Rests	3 - Normal Wear & Tear
Operator's Seat & Arm Rests Condition	Seat(s) in good condition, no stains or tears in upholstery
Seat Belt	3 - Normal Wear & Tear
Seat Belt Condition	Seat belt secures properly. Nicks, cuts, holes, or fraying observed on belt webbing
Cabin Lights	0
Safety Lock Out / Stop	0
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	Switches have good functionality, minor cosmetic damage observed, One or more switches are inoperative or missing, Other (see comments)
Comments	Most switches operational. LMI inoperable
Hour Meter Activity	2 - Above Average Wear
Hour Meter Condition	Other (see comments), Hour meter is functional, with some minor wear and/or cosmetic damage
Comments	Hour meter may have been replaced, actual hours unknown
Hour Meter Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	Gauges are functional, with some wear and/or cosmetic damage
Heater & A/C	0
Fans / Vents	0
Travel Alarm	2 - Above Average Wear
Travel Alarm Condition	System is configured but not operating correctly




Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Fire Extinguisher	0
First Aid Kit	0
Anti Two Block System	2 - Above Average Wear
Comments	Non operational during inspection
Load Movement Indicator (LMI)	2 - Above Average Wear
Comments	Non operational during inspection

Engine Inspection Points


Engine

спуше	
Engine Type (Make, Model, Cylinders, Hp)	CAT 3306 - 6CYL 230HP
Emissions Tier	Tier 0
Engine Serial Number	N/A
Engine Fuel Type	Diesel
Engine Photos	
















Blow-by (Visual Observation Check)	Yes
Comments	Minor blowby seen
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	Yes
Engine Smoke Notes	Engine smoke observered upon start up, Other (see comments)
Comments	Normal Engine Smoke Observed during startup and under load
Engine Exhaust Color	Black, Other (see comments)
Comments	Normal
Battery	3 - Normal Wear & Tear
Battery Condition	Like new, recently replaced
Battery Condition Photos	



Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Belt Photos	
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear



Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Appropriate oil level, Other (see comments)
Comments	Oil change recommended
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Overall engine seemed okay. No major fluid leaks seen.

Drivetrain Inspection Points

Drivetrain

Drivetrain	
Hydrostatic Transmission?	No
Transmission Info (Make/Model/Speeds)	Powershift 3 speed
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations
Transmission Photos	




Clutch	0
Shift Lever	3 - Normal Wear & Tear
Shift Lever Condition	Good forward and reverse function, Other Comments
Comments	Machine hesitated to move forward (may be associated with voltage drop under 24V)
Foot Brake	3 - Normal Wear & Tear
Foot Brake Condition	Good brake function
Inching Brake	0
Parking Brake	3 - Normal Wear & Tear
Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain in okay condition. Transmission showed minor hesitation to move forward intermittently.


Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Comments	Frame looks solid
Frame Photos	























Stance	3 - Normal Wear & Tear
Turntable Bearing	3 - Normal Wear & Tear
Front Axle Appearance	3 - Normal Wear & Tear
Front Axle Appearance Photos	

















Rear Right Tire Photos	
Outrigger Condition	3 - Normal Wear & Tear
Outrigger Photos	











Wet or Damp Hydraulic Lines / Fittings


Yes

Outrigger Floats/Pads Condition	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Overall, chassis in good condition with no obvious issues seen.
Hydraulics Overall Inspec	tion Points
Hydraulics Overall	




Appearance of Hydraulic Lines / Fittings	2
Hydraulic Lines / Fittings Condition	Twisted, kinked, or flattened hydraulic hoses, Active leaks in hoses or fittings observed, Hydraulic lines & fittings are clean and in good condition, Other (see comments)
Comments	Most hydraulic hoses/lines in good condition. Some twisted and others leaking a bit.
Appearance of Hydraulic Lines / Fittings Photos	































Unusual Noises (Hydraulic Pump)	No
Hydraulic Pump Notes	No unusual noises heard during operation
External Controls / Levers	3
External Controls / Levers Condition	Good function & condition of hydraulic controls
Main Hoist	3 - Normal Wear & Tear
Main Hoist Photos	




Auxiliary Hoist	3 - Normal Wear & Tear
Auxiliary Hoist Photos	
Swing Motor	3 - Normal Wear & Tear

Hydraulics Cylinders Inspection Points

Lift Cylinder(s)	Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Lift Cylinder(s): Mounting Pins	3
Lift Cylinder(s): Oil Leaks	Yes
Comments	Minor leakage observed from rod seals








Telescoping Boom Cylinder(s)	Check the telescoping boom cylinder(s). Note any wear, pitting, discoloration, etc. Take photos.
Telescoping Boom Cylinder(s): Mounting Pins	3
Telescoping Boom Cylinder(s): Oil Leaks	No
Outrigger Cylinders	Check the telescoping boom cylinder(s). Note any wear, pitting, discoloration, etc. Take photos.
Outrigger Cylinders: Mounting Pins	3




Outrigger Cylinders: Oil Leaks	No
Crane Specific	
Counterweight	3 - Normal Wear & Tear
Boom Angle Indicator	3 - Normal Wear & Tear
Comments	Electronic unit installed in cab
Main Boom Sections	3 - Normal Wear & Tear
Main Boom Photos	





























Functional Test

Interior Rating

Forward & Reverse	2 - Operable, but Diagnosis Needed
Comments	Hesitation observed (may be low on trans. fluid or low voltage)
Steering (Front Wheel / All Wheel / Crab Steer)	3 - Normal, Operating as Expected
Swing Table Rotation	3 - Normal, Operating as Expected
Outriggers	3 - Normal, Operating as Expected
Boom Lift	3 - Normal, Operating as Expected
Boom Extension / Retraction	3 - Normal, Operating as Expected
Hoist	3 - Normal, Operating as Expected
Overall Functional Test Comments	Overall most functions operating well. Hydraulics work good and no major obvious problems observed.
Operating Video	Click to Download
Overall Assessment	
Overall Assessment	
Exterior Rating	3

3



Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	For the most part, machine in good shape. Annual certification good through March, 2023. Quad good through 11/2023. Machines main functions working as expected and no major problems observed. Exterior and interior recently repainted. Both winch cables look to be in good shape on outer layers of drums.
What Needs Work	Alternator charging system inoperable. Both boom lift cylinders slightly leaking oil. Possible misfire heard from engine or could be exhaust leak. Small hydraulic leaks observed throughout machine. Transmission functionality should be checked after alternator charge system repaired due to transmission travel hesitation. Engine initial startup also hesitated to start but may be contributed to low voltage. Two block inoperable. LMI inoperable. Travel alarm inoperable.
Date/Time	01-04-2023