

General Info

Year	2015
Make	Bobcat
Model	E45 Mini Excavator
Serial Number	AG3G14390
Hour Meter Reading	2,602 Hrs.
Previous Application (e.g., earth moving, mining, demolition, etc)	Asphalt Paving Construction

Dimensions

Measurement Guide	
A. Length (ft and inches)	17'7"
B. Width (ft and inches)	6'5"
C. Height (ft and inches)	8'4"
Operational Weight (lbs)	10,216LBS.


Features and Configuration

Control Station Type	Сапору
Bucket	No
Blade	Yes
Additional Attachment(s)	No
Hydraulic Coupler	No
Auxiliary Hydraulics	Yes
Hydraulic Thumb	No
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No


OMM Specifications

OMM Specifications
















Set S	Burgit Burgit Burgit Manth Case Case Case Case Case Case Case Case	Ede DC Com Com Com Com Com Com Com Co
Boot Vision V	Provi Eine Provi Eine Varia Gaias Eine Varia Gaias Eine Vadinudio Filler Popass Dann	TO P
a r	2003 PM (200 PM (200 PM (200 PM)) 20000 PM (200 PM (200 PM)) 27000 PM (200 PM (200 PM)) 27000 PM (200 PM (200 PM)) 246 PM (25 PM (25 PM)) 946 PM (25 PM) (25 PM)	Money V2003-WH, 638-66-5 30.2 Kr (40.5 M) 30.2 Kr (40.5 M) 30.2 Kr (40.5 M) 2 K
a secilication and a secolication and a secolicatio		
r ((() () () () () () () () (
		t


Exterior Walkaround Photos

Exterior 360 Walkaround




Instructions	Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components. Must have shots to capture: - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Rear - Rear - 45 degree corner shot of left rear - 45 degree corner shot of left rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear Tips for good photos: - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	equipment in the background











General Appearance Inspection Points General Appearance




















Body Panels Photos	
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	0
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	0
Mirrors	0
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational, Other (see comments)
Exterior Lights Photos	






Control Station Inspection Points


Control Station

Control Station


Take close-up photos of operator control station or cab including the floors, panels, headliner, seat, controls & displays, gauges & meters, and interior lights. Note any damage or wear.




























	FASTEN SEARCH CONTROL ON CONTROL
Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling
Operator Seat	3 - Normal Wear & Tear
Operator Seat Condition	Seat(s) in good condition, no stains or tears in upholstery
Operator Seat Photos	
Cabin Lights	0
Safety Lock Out / Stop	1 - Service Required
Safety Lock Out / Stop Condition	Improper/insufficient safety lock out device is supplied for the machine, Other (see comments)



Comments	Machine starts with hydraulic lock ON (handle down)(SAFETY ISSUE)
Safety Lock Out / Stop Photos	
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Controls & Switches Photos	








	2. Annual Wear & Tear
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Hour Meter Activity Photos	25024
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	0
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	Kubota - 4CYL 2.4L - 42HP
Emissions Tier	Tier 4F
Engine Serial Number	7FC6596
Engine Fuel Type	Diesel







Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	Yes
Engine Smoke Notes	Engine smoke observered upon start up, Other (see comments)



Comments	Engine smoke observed at initial start up and cleared up after 30 seconds. Afterwards, engine did not smoke after being shut off and restarted.
Engine Exhaust Color	White
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	
	DOLD FILL



Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Belt Photos	
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No



Overall Engine Appearance	Clean & dry
Overall Engine Comments	Overall Engine shows a well maintained appearance. Runs well under load and sounds healthy. No active leaks observed.
	ENGINE RUNNING HIGHER THAN NORMAL AT IDLE (Engine Currently Running @1700rpm at idle)

Drivetrain Inspection Points

Drivetrain	
Drivetrain	Take close-up photos of the drivetrain components including transmission housing, drive shaft, drive motors, fittings, and hoses. Note any damage or wear.
Drivetrain Photos	




	<image/>
Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear
Comments	Left side reverse function slower than right side (verified with cycle times)
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain in good condition besides left side track motor noticeably slower travel speed than right side.
Chassis Inspection Points	


Doom	Condition
DUUIII	CONDUCT

3 - Normal Wear & Tear

































Boom to Stick Pin & Bushings	3 - Normal Wear & Tear
Boom to Stick Pin & Bushings Photos	












Turntable Bearing	3 - Normal Wear & Tear
Turntable Bearing Photos	
Bottom Covers	0
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Overall chassis in solid condition with no obvious issues observed.
Undercarriage Inspection	Points
Rubber Track Undercarrie	


Roller Frames

3 - Normal Wear & Tear












Track Belt	3 - Normal Wear & Tear
Comments	2 different styles, both above 70% tread left
Track Belt Photos	









Rubber Belt Drive Lugs Photos	
Track Tensioners	2 - Above Average Wear
Comments	R/S track loose (should be checked to see if it adjust and holds tension)
Front Idlers	3 - Normal Wear & Tear
Front Idlers Photos	











Sprockets	3 - Normal Wear & Tear
Sprockets Photos	


Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System

Take close-up photos of the hydraulic components including the pump, lines, fittings, controls, and levers. Note any damage, wear, or leaks.









Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Appearance of Hydraulic Lines / Fittings Photos	











Unusual Noises (Hydraulic Pump)	No
Hydraulic Pump Notes	No unusual noises heard during operation
External Controls / Levers	3 - Normal Wear & Tear
External Controls / Levers Condition	Good function & condition of hydraulic controls
External Controls / Levers Photos	






Hydraulics Cylinders Inspection Points

Boom Cylinder: Mounting Pin	3 - Normal Wear & Tear
Boom Cylinder: Oil Leaks	No
Boom Cylinder Photos	









Stick Cylinder: Mounting Pin	3 - Normal Wear & Tear
Stick Cylinder: Oil Leaks	No
Stick Cylinder Photos	



















Blade Inspection Points

Blade Condition	3 - Normal Wear & Tear
Blade Edge	3 - Normal Wear & Tear
Blade Hose & Fittings	3 - Normal Wear & Tear
Blade Cylinder	3 - Normal Wear & Tear



Blade Cylinder Photos	

Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Swing Table Rotation	3 - Normal, Operating as Expected
Boom Lift / Angle / Tilt	3 - Normal, Operating as Expected
Blade Functionality	3 - Normal, Operating as Expected
Overall Functional Test Comments	Overall the machines functions operating well during inspection.
Operating Video	Click to Download



Overall Assessment

Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	2 - Above Average Wear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	No excessive play observed in implements. Engine and Hydraulics sound healthy and work well. Undercarriage In good condition. Operator station also in good condition.
What Needs Work	Machine needs a bucket. Engine smoke after initial startup may be indicating possible injection system seeping into cylinders overnight. This may be the reason why excessive smoke observed only at initial startup. (1 or more injectors may need to be serviced/replaced or a simple injection service recommended). Left side armrest hydraulic lockout switch needs to be addressed for safety.
Date/Time	01-11-2023