Date Submitted: 01-12-2023 12:47 PM



Inspection Report (Compact Track Loader)

General Info

Year	2017
Make	Bobcat
Model	T740
Serial Number	B3CA12473
Hour Meter Reading	2,654
Previous Application (e.g., earth moving, mining, demolition, etc)	Asphalt Paving Construction

Dimensions

Measurement Guide	
A. Length (ft and inches)	11'10"
B. Width (ft and inches)	6'8"
C. Height (ft and inches)	6'9"
Operational Weight (lbs)	10,417 Lbs.

Features and Configuration

1 oataroo aria oorinigarati	Toutaroo and Cornigaration	
Control Station Type	Cab	
Bucket	Yes	
Bucket Specs	80"	
Additional Attachment(s)?	No	
Auxiliary Hydraulics	Yes	
Heat	Yes	
A/C	Yes	
Radio	No	
Backup Camera	No	
OMM (Operator & Maintenance Manual)	Yes	
Telematics	No	


OMM Specifications


OMM Specifications

Detail Specifications	Take photos of the detailed spec pages included in the operator's manual	
Dotali Opooliloationo	rate protect of the detailed open pages included in the operator o mandar	





OMM Spec Photos



















Exterior 360 Walkaround

Exterior 360 Walkaround

Date Submitted: 01-12-2023 12:47 PM



Inspection Report (Compact Track Loader)

Instructions

Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.

Must have shots to capture:

- 45 degree corner shot of left front
 45 degree corner shot of right front
- Left side
- Right side
- Rear
- 45 degree corner shot of left rear45 degree corner shot of right rear

Tips for good photos:
- Move the equipment into a open area without any visual distractions or other equipment in the background

Exterior Walkaround Photos






















General Appearance Inspection Points

General Appearance




Close-up Exterior Photos
































































Doors / Canopy Latches Photos



Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Bent or broken steps or rungs

Steps / Ladders Photos



Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	0
Exterior Lights	2 - Above Average Wear
Exterior Lights Condition	Overall lighting system is non-operational

Date Submitted: 01-12-2023 12:47 PM



Inspection Report (Compact Track Loader)

Exterior Lights Photos





Control Station Inspection Points

Control Station


Control Station

Take close-up photos of operator control station or cab including the floors, panels, headliner, seat, controls & displays, gauges & meters, and interior lights. Note any damage or wear.


Serial Number Plate Photo



















































Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling
Operator Seat	3 - Normal Wear & Tear
Operator Seat Condition	Seat(s) in good condition, no stains or tears in upholstery
Operator Seat Photos	




Date Submitted: 01-12-2023 12:47 PM




















Engine Inspection Points

Engine	
Engine Type (Make, Model, Cylinders, Hp)	Bobcat - 4CYL 3.4L - 74HP
Emissions Tier	Tier 4F
Engine Serial Number	N/A
Engine Fuel Type	Diesel





Date Submitted: 01-12-2023 12:47 PM








Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Other (see comments), Belts appear in good condition & alignment with proper tension
Comments	Belts okay, tensioner has surface wear






Date Submitted: 01-12-2023 12:47 PM



Inspection Report (Compact Track Loader)



Drivetrain Inspection Points

Drivetrain	
Drivetrain	Take close-up photos of the drivetrain components including transmission housing, drive shaft, drive motors, fittings, and hoses. Note any damage or wear.

Date Submitted: 01-12-2023 12:47 PM



Inspection Report (Compact Track Loader)

Drivetrain Photos






Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Drivetrain has normal wear for 2,600 hours. Rear sprockets should be changed out soon for optimal track upkeep.


Chassis Inspection Points

Chassis Photos	Take photos of the entire chassis and all relevant components including frame, stance, lift arm, and quick coupler.	
----------------	---------------------------------------------------------------------------------------------------------------------	--













































Overall Chassis Overall Chassis Comments	Normal Wear & Tear Overall chassis in good condition with no obvious problems observed.
Quick Coupler to Arms Pins	3 - Normal Wear & Tear
Quick Coupler	3 - Normal Wear & Tear


Undercarriage Inspection Points

Rubber Track Undercarriage


Undercarriage Photos




































Hydraulics Overall Inspection Points

Hydraulics Overall


Hydraulic System

Take close-up photos of the hydraulic components including the pump, lines, fittings, controls, and levers. Note any damage, wear, or leaks.


Hydraulic System Photos
























Unusual Noises (Hydraulic Pump)

No


Hydraulic Pump Notes

No unusual noises heard during operation


Hydraulics Cylinders Inspection Points

Lift Cylinder	Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Lift Cylinder & Mounting Pin	3
Lift Cylinder: Oil Leaks	No
























Date Submitted: 01-12-2023 12:47 PM



Inspection Report (Compact Track Loader)






Bucket Inspection Points















Bucket Edge / Deflectors	1 - Service Required
Comments	Missing

Functional Test

	<u> </u>	
Forward & Reverse	3 - Normal, Operating as Expected	
Steering	3 - Normal, Operating as Expected	
Lift / Tilt	3 - Normal, Operating as Expected	
Bucket Functionality	3 - Normal, Operating as Expected	

Date Submitted: 01-12-2023 12:47 PM



Inspection Report (Compact Track Loader)

Overall Assessment

Overall Assessment	
Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	Machine has no signs of major active leaks from the power train or hydraulics. This unit was well maintained and it shows. Engine fires right up and sounds healthy under load.
What Needs Work	Undercarriage (specifically sprockets) are worn and becoming too thin for optimal performance. Other undercarriage components may need to be serviced sooner than later. Rear rattle sounds from engine compartment may be loose top covers. Small hairline cracks seen at muffler.
Date/Time	01-11-2023