

Inspection Report (On-Highway Flatbed Truck)

General Info

Year	2014
Make	Trailking
Model	TK80HT-482
Serial Number	1TKA04825EM013367
Truck Odometer Reading	N/A
Current Inspection / State Cert / DOT	Inspected 9/2022 per 49 CFR, Part 396, FMCSR
Previous Application (e.g., earth moving, mining, demolition, etc)	EQUIPMENT RENTAL HAULER

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	47'11"
Width (ft and inches)	8'6"
Height (ft and inches)	4' @5th wheel height (while under load) 58" dock height
Wheelbase (ft and inches)	N/A
GVWR (lbs)	50,000 Lbs.



Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Drive Type	4X6
Overdrive	N/A
Heat	No
A/C	No
Radio	No
Backup Camera	No
Cruise Control	No
PTO	No
Engine Brake	No
Differential Lock	No
OMM (Operator & Maintenance Manual)	No
Telematics	No
Auxiliary Engine	No
Liftgate	No

Exterior 360 Walkaround

Inspection Report (On-Highway Flatbed Truck)

Exterior 360 Walkaround

<p>Instructions</p>	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
<p>Exterior Walkaround Photos</p>	
	

Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



General Appearance Inspection Points

General Appearance

Inspection Report (On-Highway Flatbed Truck)

Close-up Exterior Photos



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)




Inspection Report (On-Highway Flatbed Truck)





Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)

	
	
Body Panels	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment, Other (see comments)
Comments	Front, top deck, storage lids slightly bent
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	0
Glass	0
Mirrors	0
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational, Other (see comments)
Comments	Unable to test lighting system with tractor connected

Inspection Report (On-Highway Flatbed Truck)

Exterior Lights Photos



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)






Cab Inspection Points

On Highway - Cab




VIN/Serial Number Plate Photo






Inspection Report (On-Highway Flatbed Truck)

<p>Odometer Photo</p>	 <p>FEDERAL ANNUAL INSPECTION THIS VEHICLE HAS PASSED AN ANNUAL INSPECTION CONDUCTED IN ACCORDANCE WITH 49 CFR, PART 396, FMCSR</p> <table border="1"><tr><td>MONTH 9</td><td>YEAR 22</td><td>D3833155</td></tr><tr><td>VEHICLE ID (Company No.) 125092</td><td colspan="2">STATE/TAG NO. OR VIN ITKA 048 25EM013363</td></tr></table>	MONTH 9	YEAR 22	D3833155	VEHICLE ID (Company No.) 125092	STATE/TAG NO. OR VIN ITKA 048 25EM013363		
MONTH 9	YEAR 22	D3833155						
VEHICLE ID (Company No.) 125092	STATE/TAG NO. OR VIN ITKA 048 25EM013363							
<p>Cab Interior Photos</p>								
								

Inspection Report (On-Highway Flatbed Truck)

		
Odometer Activity	0	
Controls/Switches/Gauges	3 - Normal Wear & Tear	
Controls/Switches/Gauges Condition	Other (see comments)	
Comments	All control levers look to be in good functioning condition unable to test with tractor and PTO connected	
Controls/Switches/Gauges Photos		
		

Inspection Report (On-Highway Flatbed Truck)

	
	
	
Brake System Type	Air Brakes
Air Brakes Build Correct Pressure	N/A
Clutch	0
Horn	0
Reverse Alarm / Backup Camera	0
Heater & A/C	0
Interior Lights	0




Inspection Report (On-Highway Flatbed Truck)

Seats/Seat Belts	0
Cab Interior Overall Rating	0

Chassis & Drivetrain Inspection Points

On-Highway: Undercarriage Components

Chassis Inspection Points

Chassis Inspection Points	Take photos of all undercarriage and chassis components including frame, suspension, axles, steering, and brake components. Note any damage or wear.	
Chassis & Undercarriage Photos		
		
		

Inspection Report (On-Highway Flatbed Truck)





Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)

		
		
Frame	3 - Normal Wear & Tear	
Suspension	3 - Normal Wear & Tear	
Steer Axle Condition	3 - Normal Wear & Tear	
Comments	*Rear drive axles	
Steering Components	0	
Overall Chassis Condition	3 - Normal Wear & Tear	
Overall Chassis Comments	Trailer chassis has good appearance with no obvious issues observed during the inspection.	

Drivetrain Inspection Points

Transmission Info (Make/Model)	N/A
Transmission	0
PTO	3 - Normal Wear & Tear

Inspection Report (On-Highway Flatbed Truck)

PTO Photos



This is a close-up photo of the hydraulic control valve used to power the rear hydraulic dovetail ramp. Small leakage observed from what could be worn hydraulic hoses.






Inspection Report (On-Highway Flatbed Truck)






Inspection Report (On-Highway Flatbed Truck)





Inspection Report (On-Highway Flatbed Truck)

		
Differential	Check condition of the differential(s). Take photos and notes as relevant.	
Rear Differential	0	
Front Differential	0	
Brake Shoe Thickness	50%	
Comments	Front @40-50% Rear @80%	
Brake Shoe Photos		
		

Inspection Report (On-Highway Flatbed Truck)

		
		
Air Brake System Leaks	N/A	
Air Brake Hose Condition	3 - Normal Wear & Tear	
Comments	Unable to test air system	
Air Brake System Photos		

Inspection Report (On-Highway Flatbed Truck)

	
	
Overall Drivetrain Condition	3 - Normal Wear & Tear
Overall Drivetrain Comments	Overall drivetrain looks solid. Brakes look well kept with signs of brake chambers to have been recently replaced. No wheel seal leaks observed.

Additional Undercarriage Components

Equipped with DPF (Diesel Particulate Filter)	N/A
--	-----


Wheels & Tires Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points

Wheels & Hub Condition	3
-----------------------------------	---




Inspection Report (On-Highway Flatbed Truck)

<p>Wheels & Hub Photos</p>		
		
		




Inspection Report (On-Highway Flatbed Truck)






Inspection Report (On-Highway Flatbed Truck)

		
		
Wheel Seal Leaks	No	
Tire Brand	Sumitomo ST 727	
Tire Size	10R/17.5	
Front Left Tire - Ratio Remaining	70%	
Front Left Tire Photos		



Inspection Report (On-Highway Flatbed Truck)

	
Front Right Tire - Ratio Remaining	10%
Front Right Tire Photos	
	

Inspection Report (On-Highway Flatbed Truck)

		
Rear Right Tire - Ratio Remaining	10%	
Rear Right Tire Photos		
		
Rear Left Tire - Ratio Remaining	70%	

Inspection Report (On-Highway Flatbed Truck)

Rear Left Tire Photos	
	
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.

Functional Test

Forward & Reverse	0
Steering	0
Brakes	0
Engine	0
Controls	0
Overall Functional Test Comments	Unable to test trailer at time of inspection
Operating Video	Click to Download

Inspection Summary

Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	0
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear



Inspection Report (On-Highway Flatbed Truck)

Functionality Rating	0
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	Structurally in good condition. All brakes are visually in well maintained state. No wheel seal leaks or major hydraulic leaks observed. All cylinders look to be leak free and undamaged. Wireless remote for controlling the winch included. The trailer deck in excellent condition with no cracks or major repairs needed.
What Needs Work	Most tires need to be replaced. I recommend all lights and brakes should be properly checked to ensure proper functioning.
Date/Time	01-20-2023