


Inspection Report (Compact Track Loader)

General Info

| | |
|--|----------------------|
| Year | 2007 |
| Make | CAT |
| Model | 287C |
| Serial Number | MAS00561 |
| Hour Meter Reading | 7,614 |
| Previous Application (e.g., earth moving, mining, demolition, etc) | General Construction |

Dimensions

| | |
|---------------------------|--|
| Measurement Guide |  |
| A. Length (ft and inches) | 12'2" |
| B. Width (ft and inches) | 6'5" |
| C. Height (ft and inches) | 7' |
| Operational Weight (lbs) | 9,958 Lbs. |

Features and Configuration

| | |
|-------------------------------------|---|
| Control Station Type | Canopy |
| Bucket | Yes |
| Bucket Specs | Caterpillar 74" - 4 & 1 Multipurpose Bucket |
| Additional Attachment(s)? | No |
| Auxiliary Hydraulics | Yes |
| Heat | No |
| A/C | No |
| Radio | No |
| Backup Camera | No |
| OMM (Operator & Maintenance Manual) | Yes |
| Telematics | No |

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (Compact Track Loader)

| | |
|-----------------------------------|---|
| Instructions | <p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background |
| Exterior Walkaround Photos |  |
| |  |

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



General Appearance Inspection Points

General Appearance

Inspection Report (Compact Track Loader)

Close-up Exterior Photos



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)





Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

| | | |
|----------------------------------|---|--|
| |  | |
| Body Panels | 3 - Normal Wear & Tear | |
| Body Panel Condition | Large dents or cracks, Other (see comments) | |
| Comments | Rear engine door has small dent bottom left side, top of cab front edge panel slightly bent | |
| Doors / Canopy Latches | 3 - Normal Wear & Tear | |
| Doors / Canopy Latches Condition | No visible damage | |
| Steps / Ladders | 3 - Normal Wear & Tear | |
| Steps / Ladders Condition | Steps/ladders are fully intact and appear structurally sound | |
| Handrails | 3 - Normal Wear & Tear | |
| Handrails Condition | Bent or broken railings, Handrails are fully intact and appear structurally sound | |
| Comments | Front left side can handrail slightly bent in | |
| Handrail Photos |  | |

Inspection Report (Compact Track Loader)

| | | |
|---------------------------|--|--|
| |  | |
| Glass | 3 - Normal Wear & Tear | |
| Glass Condition | Glass intact, no visible damage | |
| Mirrors | 0 | |
| Exterior Lights | 3 - Normal Wear & Tear | |
| Exterior Lights Condition | No visible damage, lighting system is operational | |

Control Station Inspection Points

Control Station

| | | |
|---------------------------|--|--|
| Control Station | Take close-up photos of operator control station or cab including the floors, panels, headliner, seat, controls & displays, gauges & meters, and interior lights. Note any damage or wear. | |
| Serial Number Plate Photo |  | |

Inspection Report (Compact Track Loader)



Operator Cabin Photos





Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

| | | |
|----------------------------------|--|--|
| |  | |
| |  | |
| Operator Cabin Overall | 3 - Normal Wear & Tear | |
| Operator Cabin Overall Condition | Good cabin appearance, solid floors, panels, and ceiling, Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling | |
| Operator Seat | 3 - Normal Wear & Tear | |
| Operator Seat Condition | Seat(s) in good condition, no stains or tears in upholstery | |
| Cabin Lights | 3 - Normal Wear & Tear | |
| Cabin Lights Condition | Cabin lights are installed with all light covers in place, bulbs are installed and working properly | |
| Safety Lock Out / Stop | 3 - Normal Wear & Tear | |
| Safety Lock Out / Stop Condition | Safety lock out device is present, in good condition, and functional | |
| Controls & Switches | 3 - Normal Wear & Tear | |
| Controls & Switches Condition | All switches are installed and functional | |
| Hour Meter Activity | 3 - Normal Wear & Tear | |
| Hour Meter Condition | Hour meter is functional and in good condition | |

Inspection Report (Compact Track Loader)



| | |
|----------------------------|---|
| Hour Meter Activity Photos |  |
| |  |
| Other Gauge Activity | 3 - Normal Wear & Tear |
| Other Gauge Condition | All cockpit gauges are functional and in good condition |
| Heater & A/C | 0 |

Inspection Report (Compact Track Loader)

| | |
|------------------------|--|
| Travel Alarm | 2 - Above Average Wear |
| Travel Alarm Condition | System is configured but not operating correctly |
| Comments | Travel alarm inoperable during inspection |
| Horn | 3 - Normal Wear & Tear |
| Horn Condition | Horn is installed and functioning as expected |
| Backup Camera | 0 |

Engine Inspection Points

Engine

| | |
|--|--|
| Engine Type (Make, Model, Cylinders, Hp) | CAT 2236 - 4 CYL. - 83HP - 3.4L |
| Emissions Tier | Tier 2 |
| Engine Serial Number | N/A |
| Engine Fuel Type | Diesel |
| Engine Photos |  |
| |  |




Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

| | | |
|--|--|--|
| |  | |
| |  | |
| |  | |
| Blow-by (Visual Observation Check) | No | |
| Unusual Noises (Upon Start-up, Idle, Shutdown) | No | |
| Unusual Noise Notes | No unusual noises heard | |
| Engine Smoke (Upon Start-up, Idle, Shutdown) | No | |
| Engine Smoke Notes | No engine smoke issues observed | |
| Engine Exhaust Color | Clear | |



Inspection Report (Compact Track Loader)

| | |
|-------------------------------------|--|
| Battery | 3 - Normal Wear & Tear |
| Battery Condition | Other (see comments) |
| Comments | Not visible during inspection |
| Radiator | 3 - Normal Wear & Tear |
| Radiator Condition | Radiator fins & components appear to be in good working order, no signs of damage or leaks |
| Belts | 3 - Normal Wear & Tear |
| Belt Condition | Belts appear in good condition & alignment with proper tension |
| Hoses | 3 - Normal Wear & Tear |
| Hose Condition | Firm, pliant hoses with no signs of wear or leaks |
| Water Pump | 3 - Normal Wear & Tear |
| Water Pump Condition | No unusual pump noises heard |
| Cooling System Leaks | No |
| Coolant Color / Appearance | 3 - Normal Wear & Tear |
| Coolant Color/Appearance Notes | Normal Translucent appearance, no visual signs of contamination |
| Oil Leaks | No |
| Oil Color / Appearance | 3 - Normal Wear & Tear |
| Oil Color / Appearance Notes | Clean oil appearance, no signs of cross contamination, Other (see comments) |
| Comments | Engine service recommended |
| Fuel Leaks | No |
| Requires DEF (Diesel Exhaust Fluid) | No |
| Overall Engine Appearance | Clean & dry |
| Overall Engine Comments | Overall engine in well maintained condition |

Drivetrain Inspection Points

| Drivetrain | |
|------------|--|
| Drivetrain | Take close-up photos of the drivetrain components including transmission housing, drive shaft, drive motors, fittings, and hoses. Note any damage or wear. |

Inspection Report (Compact Track Loader)

| | | |
|-------------------------------------|---|--|
| Drivetrain Photos |  | |
| |  | |
| Hydrostatic Transmission? | Yes | |
| 2 Speed? | N/A | |
| Hydrostatic Drive Configuration | Split Transmission | |
| Drive Motors | 2 - Above Average Wear | |
| Hydrostatic Parking Brake | 3 - Normal Wear & Tear | |
| Hydrostatic Parking Brake Condition | Good brake function | |
| Overall Drivetrain Comments | Drivetrain works well in all directions. No abnormalities observed with hydrostatics during inspection. | |

Chassis Inspection Points

| | |
|----------------|---|
| Chassis Photos | Take photos of the entire chassis and all relevant components including frame, stance, lift arm, and quick coupler. |
|----------------|---|

Inspection Report (Compact Track Loader)




Chassis Photos



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)




| | | |
|----------------------------|--|--|
| |  | |
| |  | |
| |  | |
| Frame | 3 - Normal Wear & Tear | |
| Stance | 3 - Normal Wear & Tear | |
| Lift Arm | 3 - Normal Wear & Tear | |
| Chassis to Arm Pins | 3 - Normal Wear & Tear | |
| Quick Coupler | 3 - Normal Wear & Tear | |
| Quick Coupler to Arms Pins | 3 - Normal Wear & Tear | |
| Overall Chassis | 3 - Normal Wear & Tear | |

Inspection Report (Compact Track Loader)

| | |
|--------------------------|---|
| Overall Chassis Comments | Overall chassis in solid condition. Implements and frame in good working condition. |
|--------------------------|---|

Undercarriage Inspection Points

Rubber Track Undercarriage

| | | |
|----------------------|--|--|
| Undercarriage Photos |  | |
| |  | |
| |  | |

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)





Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

| | | |
|------------------------|---|--|
| |  | |
| |  | |
| Roller Frames | 3 - Normal Wear & Tear | |
| Track Belt | 3 - Normal Wear & Tear | |
| Rubber Belt Drive Lugs | 3 - Normal Wear & Tear | |
| Track Tensioners | 3 - Normal Wear & Tear | |
| Front Idlers | 3 - Normal Wear & Tear | |
| Rear Idlers | 3 - Normal Wear & Tear | |
| Track Rollers | 3 - Normal Wear & Tear | |
| Sprockets | 3 - Normal Wear & Tear | |

Hydraulics Overall Inspection Points

Hydraulics Overall

| | |
|------------------|--|
| Hydraulic System | Take close-up photos of the hydraulic components including the pump, lines, fittings, controls, and levers. Note any damage, wear, or leaks. |
|------------------|--|

Inspection Report (Compact Track Loader)

Hydraulic System Photos






Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)

| | | |
|--|--|--|
| |  | |
| |  | |
| |  | |
| Wet or Damp Hydraulic Lines / Fittings | No | |
| Appearance of Hydraulic Lines / Fittings | 3 - Normal Wear & Tear | |
| Hydraulic Lines / Fittings Condition | Hydraulic lines & fittings are clean and in good condition | |
| Unusual Noises (Hydraulic Pump) | No | |
| Hydraulic Pump Notes | No unusual noises heard during operation | |

Hydraulics Cylinders Inspection Points



Inspection Report (Compact Track Loader)

| | |
|---------------------------------------|--|
| Lift Cylinder | Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos. |
| Lift Cylinder & Mounting Pin | 2 |
| Lift Cylinder: Oil Leaks | Yes |
| Comments | Both cylinders seeping out oil at rod seal |
| Lift Cylinder & Mounting Pin Photos |  |
| |  |
| Bucket Cylinder | Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos. |
| Bucket Cylinder & Mounting Pin | 3 |
| Bucket Cylinder: Oil Leaks | No |
| Bucket Cylinder & Mounting Pin Photos |  |




Inspection Report (Compact Track Loader)



Bucket Inspection Points

| | |
|---------------|--|
| Bucket | 3 - Normal Wear & Tear |
| Comments | 74" 4&1 Multipurpose CAT Bucket |
| Bucket Photos |  |
| |  |

Inspection Report (Compact Track Loader)

| | | |
|--------------------------|--|--|
| |  | |
| |  | |
| |  | |
| Bucket Edge / Deflectors | 3 - Normal Wear & Tear | |

Functional Test

| | |
|----------------------------------|--|
| Forward & Reverse | 3 - Normal, Operating as Expected |
| Steering | 3 - Normal, Operating as Expected |
| Lift / Tilt | 3 - Normal, Operating as Expected |
| Bucket Functionality | 3 - Normal, Operating as Expected |
| Overall Functional Test Comments | Overall machines functions operating well. No operational issues observed in machines core powertrain. |

Inspection Report (Compact Track Loader)

| | |
|-----------------|-----------------------------------|
| Operating Video | Click to Download |
|-----------------|-----------------------------------|

Overall Assessment

Overall Assessment

| | |
|--------------------------------|--|
| Exterior Rating | 3 - Normal Wear & Tear |
| Interior Rating | 3 - Normal Wear & Tear |
| Safety Rating | 3 - Normal Wear & Tear |
| Quality Rating | 3 - Normal Wear & Tear |
| Functionality Rating | 3 - Normal, Operating as Expected |
| Overall Rating | 3 - Normal Wear & Tear |
| What's Great About the Machine | Machine is well maintained inside and out. Engine and hydraulics operating great. Front bucket in great condition and is a 2021 4&1 model. Tracks have plenty of life left. |
| What Needs Work | Some Undercarriage idlers and bogies may need to be replaced soon. Cosmetic scuff marks and some dents observed. Front cab handrail bent in and travel alarm inoperable. Both lift cylinders leaking a bit and should be resealed. |
| Date/Time | 01-31-2023 |