


Inspection Report (Telehandler)

General Info

Year	2006
Make	Genie
Model	GTH-5519
Serial Number	14977
Hour Meter Reading	2,708
Previous Application (e.g., earth moving, mining, demolition, etc)	General Construction

Dimensions

Measurement Guide	
A. Length (ft and inches)	12'3" (without forks)
B. Width (ft and inches)	5'11"
C. Height (ft and inches)	6'6"
Operational Weight (lbs)	10,360 Lbs.

Features and Configuration

Control Station Type	Canopy
Max Lift Height	18'10"
Max Lift Capacity	5,500 Lbs.
Coupler Type	Hydraulic Actuated Quick Coupler
Forks / Work Tool Specs	48" Long - 4" Wide - 2" Thick
Side Shift	No
Tilt Carriage	No
Frame Leveling	No
Outriggers	No
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	No
A/C	No
Radio	No
Backup Camera	No

Inspection Report (Telehandler)

OMM (Operator & Maintenance Manual)	Yes
Telematics	No

Exterior 360 Walkaround

Exterior 360 Walkaround

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (Telehandler)



Inspection Report (Telehandler)



General Appearance Inspection Points



General Appearance

Inspection Report (Telehandler)

Close-up Exterior Photos



Inspection Report (Telehandler)

	
	
Body Panels	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	0
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	0

Control Station Inspection Points

Control Station

Control Station	Take close-up photos of operator control station or cab including the floors, panels, headliner, seat, controls & displays, gauges & meters, and interior lights. Note any damage or wear.
------------------------	--

Inspection Report (Telehandler)

Serial Number Plate Photo




Operator Cabin Photos



Inspection Report (Telehandler)





Inspection Report (Telehandler)



Inspection Report (Telehandler)



Inspection Report (Telehandler)


	
Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling, Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling
Operator Seat	2 - Above Average Wear
Operator Seat Condition	Seat(s) in good condition, no stains or tears in upholstery, Seat(s) have minor surface staining or small tears
Cabin Lights	0
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Hour Meter Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	0
Travel Alarm	3 - Normal Wear & Tear

Inspection Report (Telehandler)

Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0

Engine Inspection Points




Engine

Engine Type (Make, Model, Cylinders, Hp)	Deutz - 4 Cyl. - 2.5L - 62HP
Emissions Tier	Tier 2
Engine Serial Number	11 0 16 9 3 4 1
Engine Fuel Type	Diesel
Engine Photos	

Inspection Report (Telehandler)



Inspection Report (Telehandler)

	
	
	
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Radiator	3 - Normal Wear & Tear

Inspection Report (Telehandler)

Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Engine In good condition. Fires right up, sounds healthy at idle and under load. Engine recently serviced.

Drivetrain Inspection Points

Drivetrain

Drivetrain	Take close-up photos of the drivetrain components including transmission housing, drive shaft, drive motors, fittings, and hoses. Note any damage or wear.
Drivetrain Photos	

Inspection Report (Telehandler)



Inspection Report (Telehandler)





Inspection Report (Telehandler)



Inspection Report (Telehandler)



Inspection Report (Telehandler)

	
	
Hydrostatic Transmission?	Yes
2 Speed?	No
Hydrostatic Drive Configuration	Other (see comments)
Comments	Hydraulic Drive to 4x4 Transfer Case, 2 Axle Configuration
Drive Motors	0
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Drivetrain in good looking condition with no active leaks observed during inspection.

Chassis Inspection Points



Frame	3 - Normal Wear & Tear
--------------	------------------------

Inspection Report (Telehandler)

Frame Photos






Inspection Report (Telehandler)

		
		
Stance	3 - Normal Wear & Tear	
Front Axle Appearance	3 - Normal Wear & Tear	
Rear Axle Appearance	3 - Normal Wear & Tear	
Oscillating Pin Appearance	3 - Normal Wear & Tear	
Wheels & Tires	3 - Normal Wear & Tear	
Comments	Foam Filled	
Wheels & Tires Photos		

Inspection Report (Telehandler)






Inspection Report (Telehandler)

		
		
Tire Brand	Titan HF	
Tire Size	N/A	
Front Left Tire - Ratio Remaining	50%	
Rear Left Tire - Ratio Remaining	50%	
Front Right Tire - Ratio Remaining	50%	
Rear Right Tire - Ratio Remaining	50%	
Boom Condition	3 - Normal Wear & Tear	
Boom Condition Photos		



Inspection Report (Telehandler)



Inspection Report (Telehandler)


		
		
Chain / Tensioners	3 - Normal Wear & Tear	
Rollers & Guides	3 - Normal Wear & Tear	
Boom Wear Guides	2 - Above Average Wear	
Comments	Minor uneven wear at rear r/s of boom wear pads	
Boom Wear Guides Photos		

Inspection Report (Telehandler)

	
	
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Chassis in good condition with only wear at rear pads observed as a minor wear item.

Hydraulics Overall Inspection Points


Hydraulics Overall

Hydraulic System	Take close-up photos of the hydraulic components including the pump, lines, fittings, controls, and levers. Note any damage, wear, or leaks.
Hydraulic System Photos	


Inspection Report (Telehandler)



Inspection Report (Telehandler)



Inspection Report (Telehandler)




	
Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Unusual Noises (Hydraulic Pump)	No
Hydraulic Pump Notes	No unusual noises heard during operation

Hydraulics Cylinders Inspection Points

Boom Lift Cylinders	Check the boom lift cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Boom Lift Cylinders: Mounting Pin	3 - Normal Wear & Tear
Boom Lift Cylinders: Oil Leaks	No
Telescopic Boom Cylinders	Check the telescopic boom cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Telescopic Boom Cylinders: Mounting Pin	3 - Normal Wear & Tear
Telescopic Boom Cylinders: Oil Leaks	No
Frame Leveling Cylinders	Check the frame leveling cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Carriage Tilt Cylinder	Check the carriage tilt cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Carriage Tilt Cylinder: Mounting Pin	3 - Normal Wear & Tear
Carriage Tilt Cylinder: Oil Leaks	No
Side Shift Cylinder	Check the side shift cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Outrigger Cylinders	Check the outrigger cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinders	Check the steering cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinders: Mounting Pin	3 - Normal Wear & Tear
Steering Cylinders: Oil Leaks	No

Inspection Report (Telehandler)

Forks Inspection Points

Forks / Work Tool Condition	3 - Normal Wear & Tear
Comments	L/S Fork Slightly Bent
Forks / Work Tool Photos	
	
	

Inspection Report (Telehandler)



Back Rest Condition	3 - Normal Wear & Tear
---------------------	------------------------

Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Boom Lift / Tilt / Extend / Retract	3 - Normal, Operating as Expected
Overall Functional Test Comments	All machines core functions work well.
Operating Video	Click to Download

Overall Assessment

Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	Machine has low use hours for a 2006. Machine has been well kept and all functions operating well. No active leaks observed during the inspection. Tires are foam filled.
What Needs Work	Rear boom wear pads should be adjusted or replaced. Operator seat slightly worn.
Date/Time	02-06-2023