


Inspection Report (Compact Track Loader)

General Info

Year	2015
Make	Bobcat
Model	T740
Serial Number	B3CA11018
Hour Meter Reading	2,281
Previous Application (e.g., earth moving, mining, demolition, etc)	Masonry General Construction

Dimensions

Measurement Guide	
A. Length (ft and inches)	11'10"
B. Width (ft and inches)	6'6"
C. Height (ft and inches)	6'9"
Operational Weight (lbs)	10,130Lbs



Features and Configuration

Control Station Type	Canopy
Bucket	Yes
Bucket Specs	CAT 80" GP Bucket
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (Compact Track Loader)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



General Appearance Inspection Points

General Appearance

Inspection Report (Compact Track Loader)

Close-up Exterior Photos



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

	
Body Panels	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Bent or broken steps or rungs, Other (see comments)
Comments	Front step slightly bent
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	0
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational

Control Station Inspection Points

Control Station

Control Station	Take close-up photos of operator control station or cab including the floors, panels, headliner, seat, controls & displays, gauges & meters, and interior lights. Note any damage or wear.
------------------------	--

Inspection Report (Compact Track Loader)

Serial Number Plate Photo




Operator Cabin Photos



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)

	
Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling
Operator Seat	3 - Normal Wear & Tear
Operator Seat Condition	Seat(s) have minor surface staining or small tears
Cabin Lights	0
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	0
Travel Alarm	2 - Above Average Wear
Travel Alarm Condition	System is configured but not operating correctly, Other (see comments)
Comments	Travel alarm on machine but not operating during inspection
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0


Engine Inspection Points

Engine	
Engine Type (Make, Model, Cylinders, Hp)	Bobcat - 4Cyl.- D34NAP - 3.4L - 74HP
Emissions Tier	Tier 4F

Inspection Report (Compact Track Loader)

Engine Serial Number	5005627
Engine Fuel Type	Diesel
Engine Photos	
	
	



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

		
		
Blow-by (Visual Observation Check)	No	
Unusual Noises (Upon Start-up, Idle, Shutdown)	Yes	
Unusual Noise Notes	No unusual noises heard, Other (see comments)	
Comments	Starter solenoid not engaging (intermittently) causing starter motor to spin and not turnover engine	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke Notes	No engine smoke issues observed	
Engine Exhaust Color	Clear	
Battery	3 - Normal Wear & Tear	
Battery Condition	Like new, recently replaced	
Radiator	3 - Normal Wear & Tear	
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks	
Belts	3 - Normal Wear & Tear	
Belt Condition	Belts appear in good condition & alignment with proper tension	
Hoses	3 - Normal Wear & Tear	

Inspection Report (Compact Track Loader)

Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Engine sounds healthy at idle and under load. No leaks observed and engine appearance in well maintained condition. Only small issue is starter starting to fail intermittently and will not engage to turn engine.

Drivetrain Inspection Points




Drivetrain

Drivetrain	Take close-up photos of the drivetrain components including transmission housing, drive shaft, drive motors, fittings, and hoses. Note any damage or wear.
Drivetrain Photos	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)




	
	
	
Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function

Inspection Report (Compact Track Loader)

Overall Drivetrain Comments	Overall drivetrain in good working condition. No operational travel issues observed during its movements in all directions.
-----------------------------	---

Chassis Inspection Points

Chassis Photos	Take photos of the entire chassis and all relevant components including frame, stance, lift arm, and quick coupler.
----------------	---

Chassis Photos	
	
	

Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)





Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

	
Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Lift Arm	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Quick Coupler	3 - Normal Wear & Tear
Quick Coupler to Arms Pins	2 - Above Average Wear
Comments	Minor wear at bucket cylinder to quick coupler pin bores
Quick Coupler to Arms Pins Photos	
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Overall chassis in good condition with Normal wear observed throughout the implements. Some excess play seen in front bucket coupler to cylinder pins.

Undercarriage Inspection Points




Rubber Track Undercarriage

Inspection Report (Compact Track Loader)

Undercarriage Photos



Inspection Report (Compact Track Loader)

	
Track Width (inches)	17&1/2"
Roller Frames	3 - Normal Wear & Tear
Roller Frames Photos	
	
Track Belt	3 - Normal Wear & Tear
Rubber Belt Drive Lugs	3 - Normal Wear & Tear

Inspection Report (Compact Track Loader)




Rubber Belt Drive Lugs Photos






Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)

		
Track Tensioners	3 - Normal Wear & Tear	
Front Idlers	3 - Normal Wear & Tear	
Front Idlers Photos		
		




Inspection Report (Compact Track Loader)

		
		
<p>Rear Idlers</p>	<p>3 - Normal Wear & Tear</p>	
<p>Rear Idlers Photos</p>		


Inspection Report (Compact Track Loader)

		
		
<p>Track Rollers</p>	<p>3 - Normal Wear & Tear</p>	
<p>Track Rollers Photos</p>		

Inspection Report (Compact Track Loader)

		
Sprockets	3 - Normal Wear & Tear	
Comments	Normal wear on sprocket for the hours	
Sprockets Photos		
		

Inspection Report (Compact Track Loader)




Hydraulics Overall Inspection Points


Hydraulics Overall

Hydraulic System	Take close-up photos of the hydraulic components including the pump, lines, fittings, controls, and levers. Note any damage, wear, or leaks.
Hydraulic System Photos	


Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

	
Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Unusual Noises (Hydraulic Pump)	No
Hydraulic Pump Notes	No unusual noises heard during operation




Hydraulics Cylinders Inspection Points

Lift Cylinder	Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Lift Cylinder & Mounting Pin	3
Lift Cylinder: Oil Leaks	Yes
Comments	Both lift cylinders showing signs of minor leakage at rod seals
Lift Cylinder & Mounting Pin Photos	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

		
		
Bucket Cylinder	Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.	
Bucket Cylinder & Mounting Pin	3	
Bucket Cylinder: Oil Leaks	No	
Comments	No active leaks observed, left side bucket cylinder has signs of seepage buildup	
Bucket Cylinder & Mounting Pin Photos		



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Bucket Inspection Points

Bucket	3 - Normal Wear & Tear
Comments	Bucket slightly worn more in bottom front center area
Bucket Photos	 A photograph showing the bucket of the loader being lifted into the air by its hydraulic arm. The bucket is dark and shows some wear, particularly at the bottom edge. The background is a clear blue sky.
	 A close-up photograph of the bottom edge of the bucket, showing significant wear and rust. The bucket is resting on a concrete surface, and the wear is most prominent in the center and front areas.

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

	
Bucket Edge / Deflectors	3 - Normal Wear & Tear
Comments	Cutting edge broken at center and should be replaced

Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Lift / Tilt	3 - Normal, Operating as Expected
Bucket Functionality	3 - Normal, Operating as Expected
Overall Functional Test Comments	Overall machine works well with no major issues observed during the inspection. The starter may have to be replaced soon due to intermittent no start. Engine and hydraulics work well and undercarriage in good condition.
Operating Video	Click to Download

Overall Assessment

Overall Assessment	
Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	This compact track loader is in well maintained condition all the way around. No major active leaks observed and machine operating normal. The tracks are like new with over 80% of track tread left.
What Needs Work	Starter needs to be further inspected but may be as simple as replacing it.
Date/Time	02-16-2023