


Inspection Report (Compact Track Loader)

General Info

Year	2016
Make	Bobcat
Model	T550
Serial Number	AJZV15768
Hour Meter Reading	2,366
Previous Application (e.g., earth moving, mining, demolition, etc)	masonry general construction

Dimensions

Measurement Guide	
-------------------	--



Features and Configuration

Control Station Type	Canopy
Bucket	No
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (Compact Track Loader)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



General Appearance Inspection Points

General Appearance

Inspection Report (Compact Track Loader)

Close-up Exterior Photos






Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



	
	
	
Body Panels	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear

Inspection Report (Compact Track Loader)

Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	0
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational

Control Station Inspection Points

Control Station

Control Station	Take close-up photos of operator control station or cab including the floors, panels, headliner, seat, controls & displays, gauges & meters, and interior lights. Note any damage or wear.
Serial Number Plate Photo	 <p>A close-up photograph of a black metal serial number plate for a Bobcat. The plate features the Bobcat logo at the top center. Below the logo, it reads 'COMPACT SKID STEER TRACK LOADER MODEL'. To the right, there is a box containing 'T550'. In the center, a box contains the serial number '*AJZV15768*'. Below the serial number is a barcode. To the right of the barcode, it says 'PRODUCT IDENTIFICATION NUMBER'. At the bottom left, it says 'MADE IN USA'. At the bottom center, there is a box containing '2016' and 'MODEL YEAR' to its right. At the bottom, it reads 'Bobcat Company West Fargo, ND 58078 USA www.bobcat.com'. There is also a small 'PATENTS' logo at the bottom right.</p>
Operator Cabin Photos	 <p>A photograph showing the interior of the operator's cabin. The view is looking upwards towards a black metal grid ceiling. The floor appears to be a light-colored, possibly rubber or plastic mat. The overall lighting is somewhat dim, and the cabin appears to be in good condition.</p>

Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

	
	
	
Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling
Operator Seat	3 - Normal Wear & Tear
Operator Seat Condition	Seat(s) in good condition, no stains or tears in upholstery, Seat(s) have minor surface staining or small tears
Cabin Lights	0
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional

Inspection Report (Compact Track Loader)

Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Hour Meter Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	0
Travel Alarm	2 - Above Average Wear
Travel Alarm Condition	System is configured but not operating correctly
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0



Engine Inspection Points

Engine



Engine Type (Make, Model, Cylinders, Hp)	Bobcat - 4Cyl. - 2.4L - 66HP -
Emissions Tier	Tier 4F
Engine Serial Number	N/A
Engine Fuel Type	Diesel

Inspection Report (Compact Track Loader)

Engine Photos





Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



	
	
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections, Other (see comments)
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks

Inspection Report (Compact Track Loader)

Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Engine in good condition with no active leaks observed during the inspection.

Drivetrain Inspection Points



Drivetrain

Drivetrain	Take close-up photos of the drivetrain components including transmission housing, drive shaft, drive motors, fittings, and hoses. Note any damage or wear.	
Drivetrain Photos		
		

Inspection Report (Compact Track Loader)

Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain in solid condition. Tracks about 50 to 60% of life left.

Chassis Inspection Points

Chassis Photos	Take photos of the entire chassis and all relevant components including frame, stance, lift arm, and quick coupler.
Chassis Photos	
	

Inspection Report (Compact Track Loader)





Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

		
		
Frame	3 - Normal Wear & Tear	
Stance	3 - Normal Wear & Tear	
Lift Arm	3 - Normal Wear & Tear	
Chassis to Arm Pins	3 - Normal Wear & Tear	
Quick Coupler	3 - Normal Wear & Tear	
Quick Coupler to Arms Pins	3 - Normal Wear & Tear	
Overall Chassis	3 - Normal Wear & Tear	
Overall Chassis Comments	Overall chassis in good shape with no excessive play seen during operation.	

Undercarriage Inspection Points

Rubber Track Undercarriage

Inspection Report (Compact Track Loader)

Undercarriage Photos




Inspection Report (Compact Track Loader)





Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)


		
		
		
Roller Frames	3 - Normal Wear & Tear	
Track Belt	3 - Normal Wear & Tear	
Rubber Belt Drive Lugs	3 - Normal Wear & Tear	
Track Tensioners	3 - Normal Wear & Tear	
Front Idlers	3 - Normal Wear & Tear	
Rear Idlers	3 - Normal Wear & Tear	
Track Rollers	3 - Normal Wear & Tear	

Inspection Report (Compact Track Loader)


Sprockets	3 - Normal Wear & Tear
Comments	sprockets worn down in relation to hours worked (noticeable where sprockets meet drive lugs on tracks)
Sprockets Photos	 <p data-bbox="531 931 1129 976">sprockets will need to be replaced soon for optimal performance</p>
	

Hydraulics Overall Inspection Points



Hydraulics Overall

Hydraulic System	Take close-up photos of the hydraulic components including the pump, lines, fittings, controls, and levers. Note any damage, wear, or leaks.
Hydraulic System Photos	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

		
		
Wet or Damp Hydraulic Lines / Fittings	No	
Appearance of Hydraulic Lines / Fittings	3 - Normal Wear & Tear	
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition	
Unusual Noises (Hydraulic Pump)	No	
Hydraulic Pump Notes	No unusual noises heard during operation	
Comments	Hydraulics are In solid condition with no active leaks seen.	

Hydraulics Cylinders Inspection Points




Lift Cylinder	Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos.	
Lift Cylinder & Mounting Pin	3	
Lift Cylinder: Oil Leaks	Yes	
Comments	left side cylinder leaking at rid seal	

Inspection Report (Compact Track Loader)


Lift Cylinder & Mounting Pin
Photos



Inspection Report (Compact Track Loader)

		
		
Bucket Cylinder	Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.	
Bucket Cylinder & Mounting Pin	3	
Bucket Cylinder: Oil Leaks	No	
Comments	bucket cylinders not leaking but showing signs of seepage at rod seals	
Bucket Cylinder & Mounting Pin Photos		

Inspection Report (Compact Track Loader)



Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Lift / Tilt	3 - Normal, Operating as Expected
Bucket Functionality	0
Operating Video	Click to Download

Overall Assessment

Inspection Report (Compact Track Loader)

Overall Assessment	
Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	All core functions work great and machine is well maintained inside and out.
What Needs Work	Some cylinders need to be resealed soon. Sprockets segments need to be replaced soon.
Date/Time	02-16-2023