



ELECTRICAL	(Lighting System Condition)							N/A
	(Reverse Alarm / Backup Signal)							N/A
	(Battery Condition)		X	X				Above Average
	(Other Electric Device Condition)							No issues noted
SWING TABLE	Swivel Bearing Condition		X					Smooth and Quiet 360 Rotation both directions
	Swivel Motor Condition		X					Quiet Good performance
	Swivel Joint Condition		X					Good appearance
	(Other Remarks)		X					Swing table bolts solid Good appearance
TRANSMISSION	(Clutch Noise / Function)		X					No noises or vibrations
	(Transmission Noise / Function)		X					Good forward and reverse
	(Shift Lever Condition & Function)		X					Good shifter response
	( Other Remarks)		X					Good transmission function
HYDRAULICS CYLINDERS	BOOM	(Oil Leak from Cylinder)	X	X				Some surface wear spots of discoloration on rams
		(Mounting Pin Condition)	X	X				Some panel discoloration + wear
	DIPPER	(Oil Leak from Cylinder)	X	X				Some surface wear spots of discoloration on rams
		(Mounting Pin Condition)	X	X				Some panel discoloration + wear
	BUCKET	(Oil Leak from Cylinder)	X	X				Some surface wear spots of discoloration on rams
		(Mounting Pin Condition)						BUCKET COUPLER REQUIRES SERVICE - PARTS ON ORDER
(Other Remarks)		X	X				Typical Condition for age and hours	
CRAWLER & WHEEL ASSEMBLIES	(Transom / Boom / Arm Function / Noise )		X					Above Average Some squeaking and noisy travel
	(Slack in Pins / Loose Pins / Soft Bushings)		X	X				Above Average Some Surface wear No damage seen Muddy appearance
	LEFT SIDE Link Bush / Drive Sprocket / Shoe Condition		X	X				Above Average Some Surface wear No damage seen Muddy appearance
	RIGHT SIDE Link Bush / Drive Sprocket / Shoe Condition		X	X				Above Average Some Surface wear No damage seen Muddy appearance
	LEFT SIDE Upper & Lower Roller / Front Idler Condition		X	X				Above Average Some Surface wear No damage seen Muddy appearance
	RIGHT SIDE Upper & Lower Roller / Front Idler Condition		X	X				Above Average Some squeaking and noisy travel
	(Track Condition)		X	X				Above Average Shoes + Tracks No broken, chipped, or missing shoes
BUCKET	( Bucket Edge)							N/A
	(Bucket Bottom / Reinforced / Plate Condition)							N/A
	(Bucket Link Condition)							N/A
	(Side Cutter Condition)							N/A
BRAKES	(Tooth Condition)							N/A
	(Foot Brake)		X					Good brake function
	(Inching Brake)		X					Good
	(Parking Brake)		X					Good function
Chassis/Frame APPEARANCE	Front		X	X				Above Aveage Some wear+tear normal for age and hours
	Rear		X	X				Above Aveage Some wear+tear normal for age and hours
	Center		X	X				Above Aveage Some wear+tear normal for age and hours
	Frame rails		X	X				Above Aveage Some wear+tear normal for age and hours
OPERATION	FORWARD & REVERSE		X					Good Forward and Reverse
	SWING TABLE ROTATION		X					Good 360 rotation both directions
	BOOM LIFT / ANGLE / TILT		X					Good Lift / Tilt / Angle
	OVERALL FUNCTIONALITY		X					Good Functionality and Performance
RATINGS	OVERALL VISUAL INSPECTION			X	X			Areas of heavy wear+tear, weld repair on stick, dented+bent panels+ gaps
	COMMENTS			X				Overall dry machine, no rust issues, interior controls+switches complete
	OVERALL PERFORMANCE INSPECTION			X				Engine Good performance, Hydraulics Good Function, U/C about average
	COMMENTS			X	X			Bucket Coupler needs parts+repair

OVERALL EXTERIOR RATING:   C-        QUALITY:   C-    
 OVERALL INTERIOR RATING:   C/C-        SAFETY:   C    
 OVERALL PERFORMANCE:   C        FUNCTIONALITY:   C/C-    
**OVERALL EVALUATION GRADE: C -**  
 FLUID SAMPLE REQUEST (Y/N)   n   OIL   n   COOLANT   n  

**Shipping Dimensions:**

Length: 36.3 Ft  
 Width: 11.1 Ft  
 Height: 11.4 Ft (Top of cab)  
 Weight: 72,900 lbs

\*A:Remaining Ratio      90% or more  
 \*B:Remaining Ratio      70% or more  
 \*C:Remaining Ratio      50% or more  
 \*D:Remaining Ratio      20% or more  
 \*E:Remaining Ratio      20% or less