

Inspection Report (On-Highway Truck Cab + Chassis)

General Info

Year	2013
Make	Chevrolet
Model	2500HD
Serial Number	1GC2CXCG8DZ289731
Truck Odometer Reading	195,618
Previous Application (e.g., earth moving, mining, demolition, etc)	Equipment Rental

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	Tbd
Width (ft and inches)	Tbd
Height (ft and inches)	Tbd
Wheelbase (ft and inches)	Tbd
GVWR (lbs)	9,500Lbs.

Features and Configuration



Features	Enter in and/or verify the following information regarding the features of this equipment.
Drive Type	4X2
Overdrive	Yes
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	No
Engine Brake	No
Differential Lock	No
OMM (Operator & Maintenance Manual)	No
Telematics	No
Auxiliary Engine	No
Liftgate	Yes
Liftgate Make & Model	Tommy Gate
Liftgate Capacity (lbs)	1,000 Lbs.

Inspection Report (On-Highway Truck Cab + Chassis)

Other Configuration Details / Features / Notes	Aftermarket, Steel, Tie Down Bed Frame Installed. Running Boards Installed.
--	---

Exterior 360 Walkaround

Exterior 360 Walkaround

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



General Appearance Inspection Points

General Appearance

Inspection Report (On-Highway Truck Cab + Chassis)

Close-up Exterior Photos




Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Small Chrome Film Peeling Off




Inspection Report (On-Highway Truck Cab + Chassis)



Small dent at pointed area






Inspection Report (On-Highway Truck Cab + Chassis)

		
	Small Dent at Pointed Area	
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	3 - Normal Wear & Tear	
Glass Condition	Glass intact, no visible damage	
Mirrors	3 - Normal Wear & Tear	
Mirror Condition	Mirrors present and intact, no visible damage, Other (see comments)	
Comments	Driver Side Mirror may have an electric motor problem (Mirror adjustment hesitation observed)	
Exterior Lights	3 - Normal Wear & Tear	
Exterior Lights Condition	No visible damage, lighting system is operational	

Cab Inspection Points

On Highway - Cab

Inspection Report (On-Highway Truck Cab + Chassis)

<p>VIN/Serial Number Plate Photo</p>	 <p> GM MFD BY GENERAL MOTORS LLC 02/13 GVWR 4309 KG GAWR FRT 1996 KG GAWR RR 2812 KG 9500 LB 4400 LB 6200 LB THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE SAFETY STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE. 1GC2CXCG8DZ289731 TYPE: TRUCK MODEL: C20953 CB32 TIRE SIZE SPEED RTG RIM COLD TIRE PRESSURE FRT LT265/70R18E R 18X8J 420 KPA(60 PSI) RR LT265/70R18E R 18X8J 480 KPA(70 PSI) SPA LT265/70R18E S 18X8J 550 KPA(80 PSI) SEE OWNER'S MANUAL FOR MORE INFORMATION. </p>
<p>Odometer Photo</p>	 <p> RPM x1000 ODOMETER 195618 MI SE 53°F </p>
<p>Cab Interior Photos</p>	

Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)




Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)






Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)


	
	
	
Odometer Activity	3 - Normal Wear & Tear
Odometer Condition	Odometer is working and in good condition
Controls/Switches/Gauges	3 - Normal Wear & Tear
Controls/Switches/Gauges Condition	All switches/gauges are in good condition and functioning
Brake System Type	Hydraulic
Clutch	0
Horn	3 - Normal Wear & Tear

Inspection Report (On-Highway Truck Cab + Chassis)

Horn Condition	Horn is functioning as expected
Reverse Alarm / Backup Camera	3 - Normal Wear & Tear
Reverse Alarm / Backup Camera Condition	Reverse alarm working as expected
Heater & A/C	3 - Normal Wear & Tear
Heat & A/C Condition	Heater and A/C work as expected
Interior Lights	3 - Normal Wear & Tear
Interior Lights Condition	All interior lights are installed and functioning
Seats/Seat Belts	3 - Normal Wear & Tear
Seats/Seat Belt Condition	Seat belt secures properly, Seat(s) has major surface staining or tears
Cab Interior Overall Rating	3 - Normal Wear & Tear
Comments	Most of Cab Interior structurally in good condition. Left side of driver seat edge torn. Interior detail recommended.

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	Chevy Vortec - 6.0L - V8 - 360HP
Emissions Tier	Other (see comments)
Comments	Engine setup for FlexFuel Gasoline/E85
Engine Serial Number	N/A
Engine Fuel Type	Gasoline
Engine Photos	

Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)





Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)

		
		
Blow-by (Visual Observation Check)	N/A	
Unusual Noises (Upon Start-up, Idle, Shutdown)	Yes	
Unusual Noise Notes	Other (see comments)	
Comments	Front engine sound observed at initial startup and went away after a few minutes of running. This may be related to front serpentine belt and/or pulley system and should be further inspected for proper diagnosis.	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke Notes	No engine smoke issues observed	
Engine Exhaust Color	Clear	
Battery	3 - Normal Wear & Tear	
Battery Condition	Dusty & dirty appearance, Clean & dry appearance, tight connections	
Radiator	3 - Normal Wear & Tear	
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks	
Belts	3 - Normal Wear & Tear	
Belt Condition	Belts appear in good condition & alignment with proper tension	

Inspection Report (On-Highway Truck Cab + Chassis)

Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Overall engine sounds healthy and no active leaks observed.

Chassis & Drivetrain Inspection Points

On-Highway: Undercarriage Components

Chassis Inspection Points

Chassis Inspection Points	Take photos of all undercarriage and chassis components including frame, suspension, axles, steering, and brake components. Note any damage or wear.
Chassis & Undercarriage Photos	

Inspection Report (On-Highway Truck Cab + Chassis)



Inspection Report (On-Highway Truck Cab + Chassis)




Inspection Report (On-Highway Truck Cab + Chassis)




Inspection Report (On-Highway Truck Cab + Chassis)






Inspection Report (On-Highway Truck Cab + Chassis)




Inspection Report (On-Highway Truck Cab + Chassis)




Inspection Report (On-Highway Truck Cab + Chassis)

		
Frame	3 - Normal Wear & Tear	
Suspension	3 - Normal Wear & Tear	
Comments	Rear shocks oil seepage observed and should be replaced for optimal performance.	
Steer Axle Condition	3 - Normal Wear & Tear	
Steering Components	3 - Normal Wear & Tear	
Steering Component Photos		
		

Inspection Report (On-Highway Truck Cab + Chassis)

		
Overall Chassis Condition	3 - Normal Wear & Tear	
Overall Chassis Comments	Chassis in good shape and no major obvious issues observed.	

Drivetrain Inspection Points

Transmission Info (Make/Model)	Automatic - 6 Speed	
Transmission	3 - Normal Wear & Tear	
Transmission Condition	No unusual noises or vibrations	
PTO	0	
Differential	Check condition of the differential(s). Take photos and notes as relevant.	
Rear Differential	3 - Normal Wear & Tear	
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation	
Rear Differential Photos		
Front Differential	0	
Brake Shoe Thickness	70%	
Comments	Front brake pads/rotors recently replaced. Rear brake pads between 40-50%.	
Air Brake System Leaks	N/A	
Air Brake Hose Condition	0	
Overall Drivetrain Condition	3 - Normal Wear & Tear	

Inspection Report (On-Highway Truck Cab + Chassis)

Overall Drivetrain Comments	Overall drivetrain in good condition
-----------------------------	--------------------------------------



Additional Undercarriage Components

Equipped with DPF (Diesel Particulate Filter)	No
---	----



Wheels & Tires Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points

Wheels & Hub Condition	3
Wheel Seal Leaks	No
Tire Brand	Michelin
Tire Size	LT265/70R18
Front Left Tire - Ratio Remaining	90%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	90%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	90%

Inspection Report (On-Highway Truck Cab + Chassis)

Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	90%
Rear Left Tire Photos	
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.

Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Brakes	3 - Normal, Operating as Expected
Comments	Front brakes recently replaced
Engine	3 - Normal, Operating as Expected
Controls	3 - Normal, Operating as Expected
Overall Functional Test Comments	All main systems working well. Engine and transmission in good shape and Cab controls operating okay.
Operating Video	Click to Download
Additional Video	Click to Download

Inspection Summary

Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
-----------------	------------------------

Inspection Report (On-Highway Truck Cab + Chassis)

Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	Truck has been well maintained and no major issues observed. Truck equipped with Tommy Lift Gate and industrial bed tie down frame. Tires are like new and of top quality. Front brakes recently replaced.
What Needs Work	Interior could use a detail wash and driver seat upholstery repair. Minor dents and scuff marks present all around.
Date/Time	04-14-2023