

ELECTRICAL	(Lighting System Condition)							Not installed	
	(Reverse Alarm / Backup Signal)		X					Travel alarm working	
	(Battery Condition)		X					Above Average appearance	
	(Other Electric Device Condition)		X	X				Some loose and dangling wires	
TOWER	Swivel Bearing Condition		X					Good appearance and function	
	Swivel Motor Condition		X					Good appearance and function	
	Swivel Joint Condition		X					Good appearance and function	
	(Other Remarks)		X						
TRANSMISSION	(Clutch Noise / Function)		X					No clutch noise No banging No excess vibrations	
	(Transmission Noise / Function)		X					No noises going into forward or into reverse	
	(Shift Lever Condition & Function)		X					Good shifter response	
	(Other Remarks)								
HYDRAULICS	BOOM	(Oil Leak from Cylinder)	X					No active leaks seen	
		(Mounting Pin Condition)	X					Good appearance	
	CABLE	(Appearance)	X					Good appearance	
		(Condition)	X					No damage No Fraying seen	
	HOOK	(Swivel Function)	X					Good swivel function	
		(Twist Function)	X					Good twist function	
		(Other Remarks)	X					Hydraulics Good Function	
CRAWLER & WHEEL ASSEMBLIES	(Transom / Boom / Arm Function / Noise)		X					No unusual noises Good function	
	(Slack in Pins / Loose Pins / Soft Bushings)		X					No excess slack No excess squeaking	
	LEFT SIDE Link Bush / Drive Sprocket / Shoe Condition		X					Sprockets look good No chips or cracks 1 Shoe corner chipped	
	RIGHT SIDE Link Bush / Drive Sprocket / Shoe Condition		X					Sprockets look good No chips or cracks Shoes overall Good appearance	
	LEFT SIDE Upper & Lower Roller / Front Idler Condition		X					Rollers look good No damage seen No cuts into tracks seen	
	RIGHT SIDE Upper & Lower Roller / Front Idler Condition		X					Rollers look good No damage seen No cuts into tracks seen	
	(Roller Condition)	(Track Rollers)	Right Front *(A)to(E)	X					B- Good / Above Average
			Left Front *(A)to(E)	X					B- Good / Above Average
		(Carrier Rollers)	Right Rear	X					B- Good / Above Average
			Left Rear	X					B- Good / Above Average
(Track Condition)		X					Tracks minimal wear B-		
M A I N B O O M	(Lift Cylinder)		X					Good appearance	
	(Wire Rope End)		X					Good appearance	
	(Extend Cylinder Condition)		X					Good appearance	
	(Boom Alignment)		X					Good	
LOAD BLOCK & HOOK	(Boom Head Section)		X					Good appearance	
	(Wire Rope Retainer)		X					Good appearance	
	(Tower and Lift Cylinder Pins)		X					Good	
	(Sheave / Wear Pads)		X					Good appearance	
	(Hook Appearance)		X					Good appearance	
B R A K E S	(Foot Brake)		X					Working	
	(Inching Brake)		X					Working	
A U X	(Front / Fast Line Hoist + Brake)		X				Good function		
CHASSIS APPEARANCE	Front		X					Good appearance No damage No weld repairs or patches seen	
	Rear		X					Good appearance No damage No weld repairs or patches seen	
	Deck		X					Good appearance No damage No weld repairs or patches seen	
	Overall Appearance		X					Except for roof panel Overall Good Appearance	
OPERATION	FORWARD & REVERSE		X					Good Forward and Reverse	
	SWING TABLE ROTATION		X					Good 360 rotation No Grinding Noises	
	BOOM LIFT / ANGLE / TILT		X					Good Lift and Angle + Tilt Function	
	OVERALL FUNCTIONALITY		X					Good Functionality	
RATINGS	OVERALL VISUAL INSPECTION		X	X				Recent RePaint Some repaint over rust Door frame precancer and lower	
	COMMENTS		X	X				window frame cancer rot panel missing Good appearance of panel gaps	
	OVERALL PERFORMANCE INSPECTION		X	X				Good travel+Hydraulic function Cert Inspect dated 4/28/2020	
	COMMENTS							Not weight or load tested	

OVERALL EXTERIOR RATING: C/C+ QUALITY: C/C+

DIMENSIONS: (Reference only)

*A:Remaining Ratio

90% or more

OVERALL INTERIOR RATING: B-/C+ SAFETY: C+
OVERALL PERFORMANCE: C+ FUNCTIONALITY: C+
OVERALL EVALUATION GRADE: C / C+
FLUID SAMPLE REQUEST (Y/N) n_ OIL n_ COOLANT n_

Transport Width:
Transport Height:
Tail Swing:
Ground Clearance:
WILL REQUIRE CUSTOM BUILT RIG

*B:Remaining Ratio 70% or more
*C:Remaining Ratio 50% or more
*D:Remaining Ratio 20% or more
*E:Remaining Ratio 20% or less