


Inspection Report (Telehandler)

General Info

Year	2012
Make	skytrack
Model	8042
Serial Number	0160044925
Hour Meter Reading	4523
Previous Application (e.g., earth moving, mining, demolition, etc)	Rental Equipment

Dimensions

Measurement Guide	
A. Length (ft and inches)	222.3 in
B. Width (ft and inches)	99.25 in
C. Height (ft and inches)	99.4
Operational Weight (lbs)	27100

Features and Configuration

Control Station Type	Cab
Max Lift Height	42ft
Max Lift Capacity	8,000
Forks / Work Tool Specs	2.36in x 4in x 48in
Side Shift	No
Tilt Carriage	Yes
Frame Leveling	Yes
Outriggers	No
Additional Attachment(s)?	No
Auxiliary Hydraulics	No
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes

Inspection Report (Telehandler)

Exterior Walkaround Photos



Inspection Report (Telehandler)



Inspection Report (Telehandler)



General Appearance Inspection Points

General Appearance

Close-up Exterior Photos



Inspection Report (Telehandler)



Inspection Report (Telehandler)






Inspection Report (Telehandler)



Inspection Report (Telehandler)



Inspection Report (Telehandler)

		
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents, Areas of surface rust observed	
Comments	body panels have areas of rust and missing paint but are in good condition	
Body Panels Photos		areas of rust and missing paint
		small area of rust

Inspection Report (Telehandler)



small amounts of rust



areas of rust and scrapes



areas of scratches and rust

Inspection Report (Telehandler)



area of rust and missing paint



Inspection Report (Telehandler)



scratches and rust



areas of scratches and rust



areas of scratches and rust

Doors / Canopy Latches	0
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound

Inspection Report (Telehandler)

Glass	0
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	0

Control Station Inspection Points

Control Station

Serial Number Plate Photo



Control Station Photos



Inspection Report (Telehandler)



Inspection Report (Telehandler)



controls appear wet due to light drizzle



controls are wet due to minor rain

Control Station Overall Rating

3 - Normal Wear & Tear

Inspection Report (Telehandler)




Control Station Overall Condition	Good cabin appearance, solid floors, panels, and ceiling
Operator Seat	3 - Normal Wear & Tear
Operator Seat Condition	Seat(s) in good condition, no stains or tears in upholstery
Operator Seat Photos	
	
Cabin Lights	0
Safety Lock Out / Stop	0
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	Switches have good functionality, minor cosmetic damage observed

Inspection Report (Telehandler)


Controls & Switches Photos



Inspection Report (Telehandler)


	
	
	
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition

Inspection Report (Telehandler)

Hour Meter Activity Photos	
Other Gauge Activity	0
Heater & A/C	0
Travel Alarm	0
Horn	0
Backup Camera	0

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	Cummins, QSF, 3.8L, 4 cylinder, 110hp
Emissions Tier	Tier 4F
Engine Serial Number	60132186
Engine Fuel Type	Diesel
Engine Photos	 <p>old dirt and gunk but in good condition</p>



Inspection Report (Telehandler)





some rust on surface area



Inspection Report (Telehandler)

	 <p>Warning: improper use may result and warranty is voided. Always use proper operation.</p> <p>Engine Serial No. 6013-7166</p> <p>Remanufactured by: Engine Components Technology Limited Cummins No. 200 Epi 122 Industrial Code: 72309 Serial Unit Prefix: 4018419</p> <p>DR6348-RX 4018419</p> <p>Timing Valve L Fitted LOW M E 03</p>
Blow-by (Visual Observation Check)	N/A
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Dusty & dirty appearance
Battery Condition Photos	

Inspection Report (Telehandler)

	
	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No


Inspection Report (Telehandler)

Overall Engine Appearance	Very dirty
---------------------------	------------

Drivetrain Inspection Points

Drivetrain

Drivetrain	Take close-up photos of the drivetrain components including transmission housing, drive shaft, drive motors, fittings, and hoses. Note any damage or wear.
------------	------------------------------------------------------------------------------------------------------------------------------------------------------------

Drivetrain Photos	
-------------------	-------------------------------------------------------------------------------------

Inspection Report (Telehandler)



Inspection Report (Telehandler)






Hydrostatic Transmission?	No
2 Speed?	No
Hydrostatic Drive Configuration	Other (see comments)
Transmission Info (Make/Model/Speeds)	ZF, 4660013001, 4speed
Transmission Components	3 - Normal Wear & Tear
Transmission Condition	Good forward and reverse function, No unusual noises or vibrations
Drive Motors	3 - Normal, Operating as Expected
Parking Brake	3 - Normal, Operating as Expected
Parking Brake Function	Good brake function

Chassis Inspection Points

Frame	3 - Normal Wear & Tear
-------	------------------------




Inspection Report (Telehandler)

<p>Frame Photos</p>		
		
		


Inspection Report (Telehandler)






Inspection Report (Telehandler)

		
<p>Stance</p>	<p>3 - Normal Wear & Tear</p>	
<p>Stance Photos</p>		
		

Inspection Report (Telehandler)



Inspection Report (Telehandler)




		
		
		
<p>Front Axle Appearance</p>	<p>3 - Normal Wear & Tear</p>	

Inspection Report (Telehandler)




Front Axle Appearance Photos



Inspection Report (Telehandler)

		
<p>Rear Axle Appearance</p>	<p>3 - Normal Wear & Tear</p>	
<p>Rear Axle Appearance Photos</p>		
		

Inspection Report (Telehandler)

	
	
	
Oscillating Pin Appearance	0
Wheels & Tires	3 - Normal Wear & Tear

Inspection Report (Telehandler)

Wheels & Tires Photos






Inspection Report (Telehandler)



Inspection Report (Telehandler)



Inspection Report (Telehandler)

		
Tire Brand	Advance	
Tire Size	15.5 - 25	
Front Left Tire - Ratio Remaining	50%	
Rear Left Tire - Ratio Remaining	30%	
Front Right Tire - Ratio Remaining	30%	
Rear Right Tire - Ratio Remaining	30%	
Boom Condition	3 - Normal Wear & Tear	
Boom Condition Photos		
		

Inspection Report (Telehandler)






Inspection Report (Telehandler)






Inspection Report (Telehandler)






Inspection Report (Telehandler)

		
		
Chain / Tensioners	3 - Normal Wear & Tear	
Rollers & Guides	3 - Normal Wear & Tear	
Boom Wear Guides	3 - Normal Wear & Tear	
Boom Wear Guides Photos		


Inspection Report (Telehandler)

	
	
	
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Chassis is in good condition
Hydraulics Overall Inspection Points	
Hydraulics Overall	
Hydraulic System	Take close-up photos of the hydraulic components including the pump, lines, fittings, controls, and levers. Note any damage, wear, or leaks.

Inspection Report (Telehandler)

<p>Hydraulic System Photos</p>	
	
	

Inspection Report (Telehandler)



Inspection Report (Telehandler)






Inspection Report (Telehandler)



Inspection Report (Telehandler)




Inspection Report (Telehandler)

Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition, Cracking, stiff, or charred hydraulic hoses
Appearance of Hydraulic Lines / Fittings Photos	
	
	



Inspection Report (Telehandler)






Inspection Report (Telehandler)

		
Unusual Noises (Hydraulic Pump)	No	
Hydraulic Pump Notes	No unusual noises heard during operation	

Hydraulics Cylinders Inspection Points

Boom Lift Cylinders	Check the boom lift cylinders. Note any wear, pitting, discoloration, etc. Take photos.	
Boom Lift Cylinders: Mounting Pin	3 - Normal Wear & Tear	
Boom Lift Cylinders: Oil Leaks	No	
Boom Lift Cylinders Photos		
		

Inspection Report (Telehandler)

	
	
	
Telescopic Boom Cylinders	Check the telescopic boom cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Telescopic Boom Cylinders: Mounting Pin	3 - Normal Wear & Tear
Telescopic Boom Cylinders: Oil Leaks	No

Inspection Report (Telehandler)

Telescopic Boom Cylinders
Photos




Inspection Report (Telehandler)




Frame Leveling Cylinders	Check the frame leveling cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Frame Leveling Cylinders: Mounting Pin	3 - Normal Wear & Tear
Frame Leveling Cylinders: Oil Leaks	No

Inspection Report (Telehandler)



Inspection Report (Telehandler)

	
Carriage Tilt Cylinder	Check the carriage tilt cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Carriage Tilt Cylinder: Mounting Pin	3 - Normal Wear & Tear
Carriage Tilt Cylinder: Oil Leaks	No
Side Shift Cylinder	Check the side shift cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Outrigger Cylinders	Check the outrigger cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinders	Check the steering cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinders: Mounting Pin	3 - Normal Wear & Tear
Steering Cylinders: Oil Leaks	No

Inspection Report (Telehandler)


Steering Cylinders Photos




Inspection Report (Telehandler)




Forks Inspection Points

Forks / Work Tool Condition	3 - Normal Wear & Tear
Forks / Work Tool Photos	 <p>20230515_112001.mp4</p> <p>7:27 5G 39%</p> <p>0:33 1:18</p>

Inspection Report (Telehandler)



Inspection Report (Telehandler)



Back Rest Condition	0
---------------------	---

Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Boom Lift / Tilt / Extend / Retract	3 - Normal, Operating as Expected
Overall Functional Test Comments	The machine was in good working order
Operating Video	Click to Download
Additional Video	Click to Download

Overall Assessment

Overall Assessment	
Exterior Rating	2 - Above Average Wear

Inspection Report (Telehandler)

Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	This machine is in good working condition and the seat looks almost new!
What Needs Work	There are some cosmetic issues like rust and missing paint from scratches.
Date/Time	05-15-2023