

General Info

Conordi IIIIC	
Category	Skid Steer
Travel System	Track Undercarriage
Comments	
Year	2017
Make	Bobcat
Model	T450
Serial Number	AUVP13481
Serial Number Plate	Bobcat. COMPACT SKID STEER TRACK LOADER MODEL *AUVP13481* PRODUCT IDENTIFICATION NUMBER MADE N CZECH REPUBLC Bobcat Company West Fargo, ND 58078 USA www.bobcat.com FOR A LIST OF UNITED STATES PATENTS THAT COVER THIS PRODUCT, GO TO:
Hour Meter Reading	1,448
-	

Powered by *** fastfield**



Hour Meter Photo



Previous Application	Rental
Location / GPS	Theatre One mapbox Dear Dr. Railroad Polic Mapbox © OpenStreetMap
	Lat: 38.7504061 Long: -77.4900178

Features & Configuration

Control Station Type	Open Cab (OROPS)
Comments	
A/C	
Heat	
Radio	
Reverse Camera	

Powered by *** fastfield**



High Flow	No
Pilot Controls	No
Auxiliary Hydraulics	Yes
Quick Coupler	No
Hydraulic Thumb	No
Bucket	No
Blade	No
Forks	No
Outriggers	No
OMM (Operator & Maintenance Manual)	Yes
Other Configuration Details / Attachment Specs	

360 Walkaround Photos

Exterior Walkaround Photos









Powered by 🍫 fastfield Page 4 of 56







Powered by 🍫 fastfield Page 5 of 56







Powered by 🍫 fastfield Page 6 of 56





Inspection Rating Criteria

Rating Scale	Explanation
1 - Service Required	Requires immediate repairs to function as expected.
2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.

General Appearance

Powered by 🍫 fastfield Page 7 of 56



Close-Up Exterior Photos





Powered by 🍫 fastfield Page 8 of 56







Powered by 🍫 fastfield Page 9 of 56








Powered by 🍫 fastfield Page 10 of 56





Powered by 🍫 fastfield Page 11 of 56





Powered by 🍫 fastfield Page 12 of 56







Powered by 🍫 fastfield Page 13 of 56








Powered by 🍫 fastfield Page 14 of 56





Control Station

Control Station



Powered by 🍫 fastfield Page 15 of 56





Powered by 🍫 fastfield Page 16 of 56







Powered by 🍫 fastfield Page 17 of 56








Powered by 🍫 fastfield Page 18 of 56






Powered by 🍫 fastfield Page 19 of 56





Powered by 🍫 fastfield Page 20 of 56





Engine

Powered by 🍫 fastfield Page 21 of 56



Engine Compartment





Powered by 🍫 fastfield Page 22 of 56







Powered by 🍫 fastfield Page 23 of 56







Powered by 🍫 fastfield Page 24 of 56







Powered by 🍫 fastfield Page 25 of 56





Powered by 🍫 fastfield Page 26 of 56







Powered by 🍫 fastfield Page 27 of 56







Powered by 🍫 fastfield Page 28 of 56







Powered by 🍫 fastfield Page 29 of 56





Engine Rating	3 - Normal Wear & Tear
Engine Overall Comments	Engine has well maintained appearance. Engine warning light comes on at initial startup but goes away after 30 seconds.

Drivetrain Components

Powered by 🍫 fastfield Page 30 of 56




Drivetrain Photos





Powered by 🍫 fastfield Page 31 of 56





Hydraulics

Hydraulic Pump/Fittings/Hoses







Powered by 🍫 fastfield Page 33 of 56





Hydraulic Cylinders & Mounting Pins



Powered by 🍫 fastfield Page 34 of 56







Powered by 🍫 fastfield Page 35 of 56









Powered by 🍫 fastfield Page 36 of 56





Powered by 🍫 fastfield Page 37 of 56





Chassis

Chassis Photos









Powered by 🍫 fastfield Page 39 of 56







Powered by 🍫 fastfield Page 40 of 56







Powered by 🍫 fastfield Page 41 of 56








Powered by 🍫 fastfield Page 42 of 56










Powered by 🍫 fastfield Page 44 of 56





Powered by 🍫 fastfield Page 45 of 56







Chassis Rating	3 - Normal Wear & Tear	
Comments	Loaders arms, Tilt linkage and main frame in great shape.	

Track Undercarriage Inspection Points

Powered by 🍫 fastfield Page 46 of 56



Undercarriage Photos





Powered by 🍫 fastfield Page 47 of 56









Powered by 🍫 fastfield Page 48 of 56





Powered by 🍫 fastfield Page 49 of 56







Powered by 🍫 fastfield Page 50 of 56








Powered by 🍫 fastfield Page 51 of 56






Powered by 🍫 fastfield Page 52 of 56






Powered by 🍫 fastfield Page 53 of 56





Powered by 🍫 fastfield Page 54 of 56





Undercarriage Inspection Points

Underbody Photos	
Underbody Rating	0
Underbody Comments	

Attachments

Attachment Photos	
Attachment Rating	0
Attachment Comments	

Functionality Assessment

Operating Video	Click to Download
Additional Video	
Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear

Powered by 🍫 fastfield Page 55 of 56



Attachments	0	
Overall Functional Test Comments	nments All functions operate well with no major issues observed.	

Overall Assessment

_		- 4
Overal	Accacemai	nt.

Overall Assessment	-		
Rating Scale	Rating Scale	Explanation	
	1 - Service Required	Requires immediate repairs to function as expected.	
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	
Exterior Rating	3 - Normal Wear & Tear		
Interior Rating	3 - Normal Wear & Tear		
Safety Rating	3 - Normal Wear & Tear		
Quality Rating	3 - Normal Wear & Tear		
Functionality Rating	3 - Normal Wear & Tear		
Overall Rating	3 - Normal Wear & Tear		
What's Great About the Machine	Machine has low hours and no major active leaks. Engine and hydraulics sound healthy and work well. Undercarriage also in good condition		
What Needs Work	All cylinders will need to be resealed soon. Minor cosmetic damage to rear radiator guard. Operator seat won't slide forward.		
Any Additional Info from the Seller?			
Date/Time	05-16-2023		

Powered by 🍫 fastfield Page 56 of 56