



General Info







Features & Configuration

1 Catalog & Configuration	
Control Station Type	Enclosed Cab
Comments	
Drive Type	
Comments	
A/C	Yes
Heat	Yes

Lat: 38.7467328 Long: -77.5437057

Powered by 🍫 fastfield Page 2 of 59



Radio	Yes
Reverse Camera	Yes
High Flow	No
Pilot Controls	Yes
Auxiliary Hydraulics	Yes
Quick Coupler	Yes
Hydraulic Thumb	No
Bucket	Yes
Blade	No
Forks	No
Outriggers	No
OMM (Operator & Maintenance Manual)	No
Other Configuration Details / Attachment Specs	

360 Walkaround Photos

Exterior Walkaround Photos



Powered by *** fastfield**







Powered by 🍫 fastfield Page 4 of 59







Powered by 🍫 fastfield Page 5 of 59







Powered by 🍫 fastfield Page 6 of 59





Inspection Rating Criteria

Rating Scale	Explanation
1 - Service Required	Requires immediate repairs to function as expected.
2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.

General Appearance

Powered by 🍫 fastfield Page 7 of 59



Close-Up Exterior Photos





Powered by 🍫 fastfield Page 8 of 59







Powered by 🍫 fastfield Page 9 of 59







Powered by 🍫 fastfield Page 10 of 59







Powered by 🍫 fastfield Page 11 of 59







Powered by 🍫 fastfield Page 12 of 59






Impact Damaged




Powered by 🍫 fastfield Page 13 of 59






Powered by 🍫 fastfield Page 14 of 59





Powered by 🍫 fastfield Page 15 of 59





Powered by 🍫 fastfield Page 16 of 59









Powered by 🍫 fastfield Page 17 of 59










Control Station

Control Station



Powered by 🍫 fastfield Page 19 of 59








Powered by 🍫 fastfield Page 20 of 59





Powered by 🍫 fastfield Page 21 of 59








Powered by 🍫 fastfield Page 22 of 59





Powered by 🍫 fastfield Page 23 of 59





Powered by 🍫 fastfield Page 24 of 59







Powered by 🍫 fastfield Page 25 of 59







Control Station Rating	3 - Normal Wear & Tear
Control Station Overall Comments	Operator Station in good condition. Operator seat has cover and did not remove.

Engine

Powered by 🍫 fastfield Page 26 of 59



Engine Compartment





Powered by 🍫 fastfield Page 27 of 59






Powered by 🍫 fastfield Page 28 of 59





Powered by 🍫 fastfield Page 29 of 59





Powered by 🍫 fastfield Page 30 of 59








Powered by 🍫 fastfield Page 31 of 59





Drivetrain Components

Drivetrain Photos




Powered by 🍫 fastfield Page 32 of 59





Powered by 🍫 fastfield Page 33 of 59





Hydraulics

Powered by 🍫 fastfield Page 34 of 59



Hydraulic Pump/Fittings/Hoses





Powered by 🍫 fastfield Page 35 of 59








Powered by 🍫 fastfield Page 36 of 59





Hydraulic Cylinders & Mounting Pins



Powered by 🍫 fastfield Page 37 of 59









Powered by 🍫 fastfield Page 38 of 59





Powered by 🍫 fastfield Page 39 of 59





Hydraulic System Rating

Hydraulic System Comments

Hydraulic System in good working condition.

Chassis

Chassis Photos









Powered by 🍫 fastfield Page 41 of 59





Powered by 🍫 fastfield Page 42 of 59







Powered by 🍫 fastfield Page 43 of 59







Powered by 🍫 fastfield Page 44 of 59








Powered by 🍫 fastfield Page 45 of 59





Powered by 🍫 fastfield Page 46 of 59







Powered by 🍫 fastfield Page 47 of 59







Chassis Rating	3 - Normal Wear & Tear	
Comments	Excess play on boom to stick and bucket coupler. Further inspection recommende to determine proper repairs.	

Track Undercarriage Inspection Points

Powered by 🍫 fastfield Page 48 of 59



Undercarriage Photos





Powered by 🍫 fastfield Page 49 of 59







Powered by 🍫 fastfield Page 50 of 59







Powered by 🍫 fastfield Page 51 of 59







Powered by 🍫 fastfield Page 52 of 59







Powered by 🍫 fastfield Page 53 of 59





Undercarriage Rating	3 - Normal Wear & Tear	
Undercarriage Comments	Undercarriage in good shape and no obvious issues observed.	

Undercarriage Inspection Points

Underbody Photos	
Underbody Rating	0
Underbody Comments	

Attachments

Attachment Photos



Powered by 🍫 fastfield Page 54 of 59





Powered by 🍫 fastfield Page 55 of 59








Powered by 🍫 fastfield Page 56 of 59





Powered by 🍫 fastfield Page 57 of 59





Attachment Rating	3 - Normal Wear & Tear
Attachment Comments	36"

Functionality Assessment

Operating Video	Click to Download	
Additional Video	Click to Download	
Engine	3 - Normal Wear & Tear	
Transmission/Drivetrain	3 - Normal Wear & Tear	
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear	
Brakes	3 - Normal Wear & Tear	
Hydraulic System	3 - Normal Wear & Tear	
Controls	3 - Normal Wear & Tear	
Safety Systems	3 - Normal Wear & Tear	
Attachments	3 - Normal Wear & Tear	
Overall Functional Test Comments	Overall all machine's main functions operating well. No major operational functions observed.	

Overall Assessment

Overall Assessment

Powered by 🍫 fastfield Page 58 of 59



Rating Scale	Rating Scale	Explanation	
	1 - Service Required	Requires immediate repairs to function as expected.	
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	
Exterior Rating	3 - Normal Wear & Tear		
Interior Rating	3 - Normal Wear & Tear		
Safety Rating	3 - Normal Wear & Tear		
Quality Rating	3 - Normal Wear & Tear		
Functionality Rating	3 - Normal Wear & Tear		
Overall Rating	3 - Normal Wear & Tear		
What's Great About the Machine	Machine is in good condition and all main core functions operating as expected. Machine is equipped with quick coupler and auxiliary hydraulics.		
What Needs Work	Minor cosmetic work all around. Seat should be further inspected for above normal wear. Excess play observed in stick to boom connections.		
Any Additional Info from the Seller?			
Date/Time	05-16-2023		

Powered by 🍫 fastfield Page 59 of 59