


#### **General Info**

Category	Paver
Travel System	Track Undercarriage
Comments	
Year	2017
Make	weiler
Model	2408
Fleet ID	3236
Serial Number	1W90P385KHB0002408
Serial Number Plate	WEILER Note:  Weiler 815 Weiler Dr. Knoxville, lowa 50138 USA  Model:  P385/B  Product Identification Number:  *1W90P385KHB002408*  38975
Hour Meter Reading	2138.3

Powered by **\* fastfield** 





#### **Features & Configuration**

reatures & Corniguration	
Control Station Type	Platform
Comments	
Drive Type	
Comments	
A/C	
Heat	

Powered by 🍫 fastfield Page 2 of 43



Radio	
Reverse Camera	
High Flow	No
Pilot Controls	Yes
Auxiliary Hydraulics	No
Quick Coupler	No
Hydraulic Thumb	No
Bucket	No
Blade	No
Forks	No
Outriggers	No
OMM (Operator & Maintenance Manual)	No
Other Configuration Details / Attachment Specs	

#### 360 Walkaround Photos

**Exterior Walkaround Photos** 














Powered by 🍫 fastfield Page 5 of 43







Powered by 🍫 fastfield Page 6 of 43







**Inspection Rating Criteria** 

Powered by 🍫 fastfield Page 7 of 43



Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.

#### **General Appearance**

Close-Up Exterior Photos



left and right side hoppers have damaged rubber wings. center rubber lip has above normal wear and tear.







Powered by 🍫 fastfield Page 9 of 43





small dent on left hand side screed













Exterior Rating	3 - Normal Wear & Tear
Exterior Comments	Exterior is in good condition has some small areas of rust/missing paint

#### **Control Station**

Powered by 🍫 fastfield Page 12 of 43




**Control Station** 










Powered by 🍫 fastfield Page 14 of 43





Powered by 🍫 fastfield Page 15 of 43






#### **Engine**

Powered by 🍫 fastfield Page 16 of 43





Powered by 🍫 fastfield Page 17 of 43








Powered by 🍫 fastfield Page 18 of 43






#### **Drivetrain Components**

**Drivetrain Photos** 



Powered by 🍫 fastfield Page 19 of 43





Powered by 🍫 fastfield Page 20 of 43







Powered by 🍫 fastfield Page 21 of 43








Powered by 🍫 fastfield Page 22 of 43





#### **Hydraulics**



Hydraulic Pump/Fittings/Hoses











Powered by 🍫 fastfield Page 25 of 43









Powered by 🍫 fastfield Page 26 of 43





Powered by 🍫 fastfield Page 27 of 43





Powered by 🍫 fastfield Page 28 of 43






Hydraulic Cylinders & Mounting Pins









Powered by 🍫 fastfield Page 30 of 43






Powered by 🍫 fastfield Page 31 of 43





Powered by 🍫 fastfield Page 32 of 43





Powered by 🍫 fastfield Page 33 of 43








Powered by 🍫 fastfield Page 34 of 43





#### **Chassis**

Powered by 🍫 fastfield Page 35 of 43




Chassis Photos





Powered by **\* fastfield** 





#### **Track Undercarriage Inspection Points**

Powered by 🍫 fastfield Page 37 of 43



**Undercarriage Photos** 









dried asphalt on tracks







Powered by 🍫 fastfield Page 40 of 43





old asphalt



caked up asphalt

Undercarriage Rating	3 - Normal Wear & Tear
Undercarriage Comments	

# **Undercarriage Inspection Points**

Underbody Photos	
Underbody Rating	0
Underbody Comments	

#### **Attachments**

Attachment Photos	
Attachment Rating	0

Powered by 🍫 fastfield Page 41 of 43



|--|

#### **Functionality Assessment**

Turiotionality Assessment	
Operating Video	Click to Download
Additional Video	Click to Download
Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Attachments	0
Overall Functional Test Comments	The machine is in good working order

#### **Overall Assessment**

#### **Overall Assessment**

Rating Scale	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	
Interior Rating	3 - Normal Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
What's Great About the Machine	It is a good machine in good working concare all in good shape.	lition. Hoses, engine, seats and controls

Powered by 🍫 fastfield Page 42 of 43



What Needs Work	There are some small areas of rust and missing paint.	
Any Additional Info from the Seller?		
Date/Time	05-16-2023	

Powered by **\* fastfield**