


General Info

General Info		
Category	Bulldozer	
Travel System	Track Undercarriage	
Comments		
Year	1987	
Make	CAT	
Model	D3B	
Fleet ID	N/A	
Serial Number	23Y02174	
Serial Number Plate	MODEL NUMBER ARRANGEMENT NUMBER MACHINE P SERIAL ENGINE TRANSMISSION CATERPILLAR MITSUBISHI LTD. SAGAMIHARA, KANAGAWA. ADE IN JAPAN SVS847	
Hour Meter Reading	32070	





Features & Configuration

Control Station Type	Open Cab (OROPS)
Comments	
Drive Type	
Comments	
A/C	
Heat	

Powered by 🍫 fastfield Page 2 of 68



Radio	
Reverse Camera	
High Flow	No
Pilot Controls	No
Auxiliary Hydraulics	No
Quick Coupler	No
Hydraulic Thumb	No
Bucket	No
Blade	Yes
Forks	No
Outriggers	No
OMM (Operator & Maintenance Manual)	No
Other Configuration Details / Attachment Specs	

360 Walkaround Photos

Exterior Walkaround Photos





















Powered by 🍫 fastfield Page 6 of 68







Powered by 🍫 fastfield Page 7 of 68







Powered by 🍫 fastfield Page 8 of 68











Inspection Rating Criteria

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.

General Appearance

Powered by 🍫 fastfield Page 10 of 68



Close-Up Exterior Photos





area of rust







small scratch/missing paint

Powered by 🍫 fastfield Page 12 of 68







Powered by 🍫 fastfield Page 13 of 68







small scratches/area of rust

Powered by 🍫 fastfield Page 14 of 68





minor misalignment/small dent



Estados Ballas	0 N 1W 0.T
Exterior Rating	3 - Normal Wear & Tear
Exterior Comments	Exterior is in good condition with minor cosmetic issues

Control Station

Powered by 🍫 fastfield Page 15 of 68



Control Station



missing paint/minor rust





missing paint/the operators seat is old and has rips/tears

Powered by 🍫 fastfield Page 17 of 68





electrical tape on arm rest



area is cracked down the middle, causing control levers to move side to side

Powered by 🍫 fastfield Page 18 of 68






area is cracked down the middle, causing control levers to move side to side



missing paint

Powered by *** fastfield** Page 19 of 68





Engine

Engine Compartment











Powered by 🍫 fastfield Page 21 of 68






Powered by 🍫 fastfield Page 22 of 68





Powered by 🍫 fastfield Page 23 of 68





Powered by 🍫 fastfield Page 24 of 68





Powered by 🍫 fastfield Page 25 of 68







Powered by 🍫 fastfield Page 26 of 68








exposed wires on negative battery cable

Powered by 🍫 fastfield Page 27 of 68





Drivetrain Components



Powered by 🍫 fastfield Page 28 of 68





Powered by 🍫 fastfield Page 29 of 68






Powered by 🍫 fastfield Page 30 of 68






Powered by 🍫 fastfield Page 31 of 68





Powered by 🍫 fastfield Page 32 of 68





Hydraulics

Drivetrain Comments

Powered by 🍫 fastfield Page 33 of 68



Hydraulic Pump/Fittings/Hoses




dry/cracked hoses



dry/cracked hose


Powered by 🍫 fastfield Page 34 of 68





Powered by 🍫 fastfield Page 35 of 68





Powered by 🍫 fastfield Page 36 of 68





there is a hydraulic leak under the guard



old cracked hoses

Powered by 🍫 fastfield Page 37 of 68








leak from under hose guard on left hand side arm cylinder

Powered by 🍫 fastfield Page 38 of 68









Powered by 🍫 fastfield Page 40 of 68





cracked hose



dry/cracked hose

Powered by 🍫 fastfield Page 41 of 68






Hydraulic Cylinders & Mounting Pins








Powered by 🍫 fastfield Page 43 of 68






Powered by 🍫 fastfield Page 44 of 68






Powered by 🍫 fastfield Page 45 of 68





Powered by 🍫 fastfield Page 46 of 68





Hydraulic System Rating

Hydraulic System Comments

2 - Above Average Wear & Tear


Chassis

Chassis Photos




Powered by *** fastfield** Page 47 of 68






Powered by 🍫 fastfield Page 48 of 68





Powered by 🍫 fastfield Page 49 of 68





Powered by 🍫 fastfield Page 50 of 68








Powered by 🍫 fastfield Page 51 of 68






Powered by 🍫 fastfield Page 52 of 68






Powered by 🍫 fastfield Page 53 of 68





Powered by 🍫 fastfield Page 54 of 68





Track Undercarriage Inspection Points

Powered by 🍫 fastfield Page 55 of 68



Undercarriage Photos



dirt build up







dirt build up







worn tracks



above normal wear and tear on tracks

Powered by 🍫 fastfield Page 58 of 68





above normal wear and tear on the tracks



dirt build up

Powered by 🍫 fastfield Page 59 of 68





Powered by 🍫 fastfield Page 60 of 68





above normal wear and tear on the tracks









Undercarriage Rating	2 - Above Average Wear & Tear
Undercarriage Comments	Tracks have above normal wear and tear but the system works just fine

Undercarriage Inspection Points

Underbody Photos	
Underbody Rating	0
Underbody Comments	

Attachments

Powered by 🍫 fastfield Page 62 of 68



Attachment Photos



damaged area on blade



area has some play

Powered by 🍫 fastfield Page 63 of 68





area is a little lose



damaged area on blade

Powered by 🍫 fastfield Page 64 of 68





minor dents



minor dents

Powered by 🍫 fastfield Page 65 of 68





area has some play



Powered by 🍫 fastfield Page 66 of 68





Attachment Rating	2 - Above Average Wear & Tear	
Attachment Comments	Attachment has minor dents and shows above normal wear and tear	

Functionality Assessment

Operating Video	Click to Download
Additional Video	Click to Download
Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	0
Hydraulic System	2 - Above Average Wear & Tear
Controls	2 - Above Average Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Attachments	2 - Above Average Wear & Tear
Overall Functional Test Comments	This is a solid machine that works well.

Overall Assessment

Overall Assessment

Powered by 🍫 fastfield Page 67 of 68



Inspection Rating Criteria	Rating Scale	Explanation		
	1 - Service Required	Requires immediate repairs to function as expected.		
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.		
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.		
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.		
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.		
Exterior Rating	3 - Normal Wear & Tear			
Interior Rating	2 - Above Average Wear & Tear			
Safety Rating	2 - Above Average Wear & Tear	2 - Above Average Wear & Tear		
Quality Rating	3 - Normal Wear & Tear	3 - Normal Wear & Tear		
Functionality Rating	3 - Normal Wear & Tear			
Overall Rating	3 - Normal Wear & Tear			
What's Great About the Machine	This is a good machine that works well. It comes with a blade and a safety cage for the cab			
What Needs Work	Several hoses are dry/cracked. The tracks have above normal wear and tear. The lever controls to turn have a crack in the center of both of them.			
Any Additional Info from the Seller?				
Date/Time	05-18-2023			

Powered by 🍫 fastfield Page 68 of 68