Location:	Boom and	Bucket
Location.		

TRUCK AND EQUIPMENT CONSULTING LLC - HYDRAULIC TAIL TRAILER CHECKLIST

Date (Y/M/D

Inspector Initials M.L.

6/6/2023

(Basic Information)				
(Make)	Trail King			
(Model)	TK80HT Tandem Axle 4X8 5th Wheel			
(Serial Number)	1TKA04825EM062326			
(Year of Manufacturing)	2014 (built 8/2013)			
(DOT/Inspection)	Arizona Perm Cert Insp 1/10/2023			
(Type)	Front Folding + Rear Hydraulic Dove Tail			
(Dimensions)	L =47 Ft 11 in / W =102 in			
(Fifth Wheel Height/King Pin)	49 in (loaded) / 14 in setting			
(Load Capacity)	Main Deck 50,000 lbs / Max 80,000 lbs			

Length x Width	
Wheels / Tires	
Axles	
Brakes/Suspension	
Landing Legs	
GVWR	
Upper/Lower Deck	9 Ft U
Hydraulic Tail Capacity	
Hydraulic Tail / Load Angle	1
Fold Under Tail dimensions	Ì

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
 C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

Specification and Dimensions			
47 Ft 11 in / 102 in			
Sumitomo 10R 17.5-16 PR			
17,640 lb axles			
ABS / Air Ride			
2 front mount			
97,080 lbs			
9 Ft Upper deck / 27 Ft Main deck (incl ramp)			
25,000 lbs			
11 Ft 10 in hydraulic tail / 10 degree			
46 in fold under tail hinge			
Winch 20,000 lbs / 80 Ft cable, Air Weigh Scale			
Dual Hydraulic Controls (1 per side), 2 toolboxes			
86 in swing clearance, Front Deck Hydraulic Lift			

Ī	(Check List)	Α	В	С	D	Е	(Remarks)
GENERAL	(General Appearance-Front)		Х				Good appearance Front Gooseneck, front frame+crossmembers
APPEARANCE	(General Appearance-Rear)		Χ				Good appearance rear panels, rear frame+crossmembers
	(General Appearance-Right)		Χ				Good appearance right side frame, panels, crossmembers
	(General Appearance-Left)		Χ				Good appearance left side frame, panels, crossmembers
	(General Appearance-Upper)		Χ				Good appearance decking, upper surfaces, upper panels
	(Major / Minor Surface Rust)		Χ				No rust seen on suspension or chassis components
	(Deck Surface)		Х				Wood over Steel, Steel Tail Good Appearance No damage No wear issues
	(Lights - Front+Rear)		Χ				Working Good appearance
	(Cabinets / Fenders / Splash Guards)		Χ				Good appearance No damage seen
	(Front Section)		Χ				Front platform surfaces, boards and panels Good appearance
PLATFORM	(Rear Section)		Χ				Rear platform surfaces, boards and panels Good appearance
APPEARANCE	(UPPER DECK)	1	Х				Upper Deck platform surfaces, boards and panels Good appearance
	(MAIN DECK)		Χ				Main Deck platform surfaces, boards and panels Good appearance
	(Tail Ramp)		Χ				Tail Ramp Good appearance No damage seen
FOLDING	(Fold Under Deck)		Χ				Fold Under Platform Good appearance No damage seen
RAMP	(Right Side Appearance)		Х				Right Side Panels Good appearance No damage seen
	(Left Side Appearance)	1	Х				Left Side Panels Good appearance No damage seen
	(Front Frame Appearance)		Х				Front Frame+Crossmembers Good appearance No damage seen
	(Rear Frame Appearance)		Х				Rear Frame +Crossmembers Good appearance No damage seen
CHASSIS	(Right Frame Appearance)		Х				Right Chassis +Crossmembers Good appearance No damage seen
	(Left Frame Appearance)	1	Х				Left Chassis+Crossmembers Good appearance No damage seen
	(Air Bag Appearance)		Х				Suspension Components Good appearance No damage seen
SUSPENSION	(Front Axle)	1	Х				Front Axles X2 Dry, Good appearance No damage seen
	(Rear Axle)	1	Х				Rear Axles X2 Dry, Good appearance No damage seen
	(Rust / Overall appearance)	1	Х				No rust seen on suspension or chassis components
	(Right Front Wheel Hub+Tire)		X				Tires = B Good appearance Hubs = B Dry No dings or dents
WHEELS+	(Left Front Wheel Hub +Tire)		Х				Tires = B Good appearance Hubs = B Dry No dings or dents
TIRES	(Right Rear Wheel Hub+Tire)		Х				Tires = B Good appearance Hubs = B Dry No dings or dents
	(Left Rear Wheel Hub+Tire)	1	Х				Tires = B Good appearance Hubs = B Dry No dings or dents
PERMITS	AS POSTED	1	X				Yes
Landing Legs	LANDING LEGS APPEARANCE						Landing Legs panels+base Straight No panel damage No cracks or rust
	TAIL HINGE	1	Х				Good Appearance and Function
	HYDRAULIC HOSES+FITTINGS	1	Х				Good Hydraulic hoses+Fittings Clean +Dry No Seepages or dampness
	WINCHES		Х				Good Appearance of Winch (not weight tested)
HYDRAULICS	HYDRAULIC CYLINDERS	1	Х				Good appearnace of hydraulic cylinders No pitting No discoloration
	CONTROLS+SWITCHES	1	Х				Good functionality all levers and controls
	PLATFORM FOLDING+UNFOLDING	1	Х	Х			Good Function Some Noise during rear panel lift
RATINGS	OVERALL VISUAL INSPECTION		X				Good appearance deck, structural crossmembers, hubs+axles,ramps
l	COMMENTS	1	X				Good appearance of underside panels, chassis and frame No damage
	OVERALL PERFORAMNCE	1	Х				Good hydraulic function Front deck, Rear Dove tail folding+unfolding
	COMMENTS	1	X				Good response and cycle time, Some noise during rear lift then quiet

OVERALL EXTERIOR RATING: <u>B</u>	QUALITY: <u>B</u>
OVERALL PLATFORM: _B	SAFETY: <u>B</u>
OVERALL TIRES+HUBS: B	CHASSIS+FRAME: _B_
HYDRAULIC FUNCTIONB	