



Inspection Report (Telehandler)

General Info

B&B Stock Number	A3420657
Year	2013
Make	Genie
Model	GTH-5519
Serial Number	GTH5514 B-237
Hour Meter Reading	3283.0
Previous Application (e.g., earth moving, mining, demolition, etc)	Rental equipment

Dimensions

A. Length (ft and inches)	16' 10"
B. Width (ft and inches)	6'
C. Height (ft and inches)	6' 9"
Operational Weight (lbs)	10,540 lb

Features and Configuration

Control Station Type	Cab
Max Lift Height	19'
Max Lift Capacity	5,500 lb
Coupler Type	Pin-in
Forks / Work Tool Specs	4'
Side Shift	No
Tilt Carriage	Yes
Frame Leveling	No
Outriggers	No
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

360 Walkaround & Operating Video



Inspection Report (Telehandler)


Walkaround Photos & Operating Video

Exterior Walkaround Photos					
Operating Video	Click to Download				

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos					
		Boom rest pad damaged	Surface rust		
					
					
		Surface rust on front right fender			
					
	Paint chipped and surface rust		Surface rust on tail light guard		
					

General Appearance Inspection Points



Inspection Report (Telehandler)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	2 - Above Average Wear & Tear	
Body Panel Condition	Visible chipped paint or dents, Areas of surface rust observed	
Comments	Visible scratches, dents and paint chips	
Doors / Canopy Latches	2 - Above Average Wear & Tear	
Doors / Canopy Latches Condition	Intermittent sticking observed on one or more latches/doors	
Comments	Entry door latch stick intermittently when trying to open or close	
Steps / Ladders	0	
Handrails	0	
Glass	3 - Normal Wear & Tear	
Glass Condition	Glass intact, no visible damage	
Mirrors	3 - Normal Wear & Tear	
Mirror Condition	Mirrors present and intact, no visible damage	
Exterior Lights	3 - Normal Wear & Tear	
Exterior Lights Condition	No visible damage, lighting system is operational	
Overall Exterior	3 - Normal Wear & Tear	
Comments	Normal wear and tear. No major issues to report	

Control Station Inspection Points

Control Station

Control Station Photos

Control Station Photos				



Inspection Report (Telehandler)

				Hardware to door handle loose	Surface rust on brake pedal
					Parking brake icon faded



Inspection Report (Telehandler)

Serial Number Plate	 A close-up photograph of a metal serial number plate. The plate is rectangular with rounded corners and a dark, slightly textured surface. It features the 'Genie' logo at the top, followed by 'A TEREX BRAND'. Below the logo, the text is organized into several lines: 'MODEL: GTH5519', 'SERIAL NUMBER: GTH5514 B-237', 'ATTACHMENT', 'MANUFACTURE DATE: 11/08/13', 'TOTAL TRUCK WEIGHT (LBS): 10,540 LBS / 4,780 KG', 'MAX LIFT CAPACITY (LBS): 5,500 LBS', 'LIFT CAPACITY (LBS) AT MAX LIFT HEIGHT: 4,400 LBS', 'OUTRIGGERS UP: N/A', 'OUTRIGGERS DOWN: N/A', 'COUNTRY OF MANUFACTURE: Italy', 'MANUFACTURER: Terexlift srl, z.i. Buzzacchero, 06019 Umbertide, Italy', and 'THIS FORKLIFT TRUCK COMPLIES WITH ANSI/ITSDF B56.6-2011 CSA B335-04'.
Hour Meter/Odometer	 A close-up photograph of the instrument cluster in the cab of a Genie telehandler. The cluster is silver and features a digital display in the center showing '0' and '3233.4'. On either side of the digital display are two analog gauges with red and green scales. The left gauge has markings for '100' and '150', and the right gauge has markings for '00' and '100'. There are also several smaller indicator lights and buttons on the cluster.
Seat	3 - Normal Wear & Tear
Seat Condition	Seat(s) in good condition, no stains or tears in upholstery
Cabin Lights	0
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	Switches have good functionality, minor cosmetic damage observed, All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition



Inspection Report (Telehandler)

Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	0
Travel Alarm	0
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Control Station Overall Rating	2 - Above Average Wear & Tear
Control Station Overall Condition	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling
Comments	Surface rust on floor panel and break pedal

Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate	
Engine Compartment Photos	



Inspection Report (Telehandler)

			Hood mounting hardware broken off hood
Engine Type (Make, Model, Cylinders, Hp)	Deutz , TD 2.9 L4 , 4 cyl, 74 Hp		
Emissions Tier	Tier 4i		
Engine Serial Number	11511426		
Engine Fuel Type	Diesel		
Blow-by (Visual Observation Check)	No		
Unusual Noises (Upon Start-up, Idle, Shutdown)	No		
Engine Smoke (Upon Start-up, Idle, Shutdown)	No		
Engine Exhaust Color	Clear		
Battery	1 - Service Required		
Battery Condition	Dusty & dirty appearance, Other (see comments)		
Comments	Battery hold down missing		
Radiator	3 - Normal Wear & Tear		
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks		
Belts	3 - Normal Wear & Tear		
Belt Condition	Belts appear in good condition & alignment with proper tension		
Hoses	3 - Normal Wear & Tear		
Hose Condition	Firm, pliant hoses with no signs of wear or leaks		
Water Pump	3 - Normal Wear & Tear		
Water Pump Condition	No unusual pump noises heard		
Cooling System Leaks	No		
Coolant Appearance	3 - Normal Wear & Tear		
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination		
Oil Leaks	No		
Oil Appearance	3 - Normal Wear & Tear		
Oil Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level		
Fuel Leaks	No		



Inspection Report (Telehandler)

Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry, Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Normal wear and tear. No major issues to report

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points

Drivetrain Photos					
					
					
					

Hydrostatic Transmission?

Yes

2 Speed?

N/A

Hydrostatic Drive Configuration

Close Coupled Transmission

Transmission Components

3 - Normal Wear & Tear

Transmission Condition

Good forward and reverse function, No unusual noises or vibrations

Drive Motors

0

Parking Brake

3 - Normal Wear & Tear

Overall Drivetrain Rating

3 - Normal Wear & Tear

Overall Drivetrain Comments

Normal wear and tear. No major issues to report

Front Axle

3 - Normal Wear & Tear

Rear Axle

3 - Normal Wear & Tear

Wheels & Tires

Wheels & Tires Inspection Points

Wheels & Hubs	3
---------------	---



Inspection Report (Telehandler)

Wheel Seal Leaks	No
Tire Brand	Camso
Tire Size	305/70-16.5
Front Left Tire - Ratio Remaining	30%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	30%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	30%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	30%
Rear Left Tire Photos	

Chassis Inspection Points

Chassis Photos	
Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Oscillating Pin Appearance	0
Boom Condition	3 - Normal Wear & Tear
Chain / Tensioners	0
Rollers & Guides	3 - Normal Wear & Tear
Boom Wear Guides	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear. No major issues to report



Inspection Report (Telehandler)

Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos					
Wet or Damp Hydraulic Lines / Fittings	No				
Hydraulic Lines/Fittings	3 - Normal Wear & Tear				
Hydraulic Lines / Fittings Condition	Dried seepages observed				
Hydraulic Pump(s)	3 - Normal Wear & Tear				
Unusual Noises	No				
Hydraulic Pump Notes	No unusual noises heard during operation				

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos					
Mounting Pins	3 - Normal Wear & Tear				
Cylinder Oil Leaks	No				
Hydraulic System Overall	3 - Normal Wear & Tear				
Comments	Normal wear and tear. No major issues to report				

Additional Attachments

Additional Attachment(s)

Additional Attachments

Attachment Type	4' forks with carriage
Attachment Make	Unable to verify
Attachment Size / Specs	48" carriage
Attachment Condition	3 - Normal Wear & Tear



Inspection Report (Telehandler)

Attachment Photos	 A photograph showing the front view of a telehandler's fork lift attachment, which is a blue metal frame with a basket-like top and two hydraulic forks at the bottom.	
-------------------	--	--

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Normal wear and tear.no major issues to report

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	2 - Above Average Wear & Tear	
Interior Rating	2 - Above Average Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	



Inspection Report (Telehandler)

What's Great About the Machine	<ul style="list-style-type: none">-Engine start right up-No error codes/ alarms-No active leaks-No abnormal noises heard
What Needs Work	<ul style="list-style-type: none">-Surface rust throughout machine-Hood mounting hardware broken-door handle loose
Date/Time	09-14-2023
Inspector Name	Javier Bocanegra