

Inspection Report (Compact Track Loader)

General Info

B&B Stock Number	A0701461
Year	2012
Make	CAT
Model	259B-3
Serial Number	YYZ02070
Hour Meter Reading	3,624 Hrs.
Previous Application (e.g., earth moving, mining, demolition, etc)	General Construction

Features and Configuration

Control Station Type	Cab
Bucket	Yes
Bucket Specs	68" GP
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
High Flow	No
Heat	No
A/C	Yes
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	
	
Operating Video	Click to Download

General Appearance Inspection Points

General Appearance

Inspection Report (Compact Track Loader)

General Appearance Photos



General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	
3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	
4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	No visible damage, good paint condition and panel fitment, Other (see comments)	
Comments	Front cab door glass broken	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	1 - Service Required	
Glass Condition	Glass is broken or shattered	
Mirrors	3 - Normal Wear & Tear	
Mirror Condition	Mirrors present and intact, no visible damage	
Exterior Lights	3 - Normal Wear & Tear	




Inspection Report (Compact Track Loader)

Exterior Lights Condition	No visible damage, lighting system is operational
Overall Exterior	3 - Normal Wear & Tear
Comments	Machines exterior is in good shape.

Control Station Inspection Points

Control Station

Control Station Photos

Control Station Photos	
Serial Number Plate	
Hour Meter/Odometer	
Seat	2 - Above Average Wear & Tear
Seat Condition	Seat(s) has major surface staining or tears

Inspection Report (Compact Track Loader)






Cabin Lights	3 - Normal Wear & Tear
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition, Hour meter is functional, with some minor wear and/or cosmetic damage
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	3 - Normal Wear & Tear
Heater & A/C Condition	Other (see comments)
Comments	None of the A/C, heater and fan functions were operating correctly during the inspection.
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling, Other (see comments)
Comments	Besides the seat and Cab door window missing, the rest of the cab interior in descent condition .

Engine Inspection Points

Engine

Engine Compartment Photos

Inspection Report (Compact Track Loader)

Engine Data Plate	
Engine Compartment Photos	
	
	
	
Engine Type (Make, Model, Cylinders, Hp)	CAT - 3.3L - 4Cyl. - 74HP
Emissions Tier	Tier 4i
Engine Serial Number	TBD
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No


Inspection Report (Compact Track Loader)

Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Dusty & dirty appearance
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Oil Appearance Notes	Appropriate oil level, Clean oil appearance, no signs of cross contamination
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	Engine runs normal and sounds healthy under load.

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points

Drivetrain Photos	
Hydrostatic Transmission?	Yes
2 Speed?	Yes


























Inspection Report (Compact Track Loader)

Hydrostatic Drive Configuration	Split Transmission
Transmission Components	3 - Normal Wear & Tear
Transmission Condition	Good forward and reverse function, No unusual noises or vibrations
Drive Motors	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Drive motors have good exterior appearance (outer side of frame area) with no leaks seen. Drive motors work well in all speeds and in all directions.

Undercarriage Inspection Points

Rubber Track Undercarriage

Undercarriage Photos

Undercarriage Photos					
					
					
					
					
				Track roller frames/axles should be further inspected due to noticeable gap from tracks to frame	


Inspection Points

Track Width (inches)	16"
Track Length (inches)	72"
Roller Frames	3 - Normal Wear & Tear

Inspection Report (Compact Track Loader)

Track Belt	3 - Normal Wear & Tear
Rubber Belt Drive Lugs	3 - Normal Wear & Tear
Track Tensioners	3 - Normal Wear & Tear
Front Idlers	3 - Normal Wear & Tear
Rear Idlers	3 - Normal Wear & Tear
Track Rollers	3 - Normal Wear & Tear
Sprockets	3 - Normal Wear & Tear
Overall Undercarriage Rating	3 - Normal Wear & Tear
Left Track Belt - Percent Remaining Estimate	50%
Right Track Belt - Percent Remaining Estimate	50%
Overall Comments	Tracks are in good shape with about half of their life left. Roller frames and undercarriage components have a healthy appearance.

Chassis Photos

Chassis Photos	
----------------	--

Chassis Inspection Points












Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Lift Arm	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Quick Coupler	3 - Normal Wear & Tear
Quick Coupler to Arms Pins	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Main frame and implements are in good condition.

Inspection Report (Compact Track Loader)







Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos	 Minor residual oil around bottom of L/H Pilot Joystick				
					
					
Wet or Damp Hydraulic Lines / Fittings	No				
Hydraulic Lines/Fittings	3 - Normal Wear & Tear				
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition				
Hydraulic Pump(s)	3 - Normal Wear & Tear				
Unusual Noises	No				
Hydraulic Pump Notes	No unusual noises heard during operation				

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos					
					
Mounting Pins	3 - Normal Wear & Tear				
Cylinder Oil Leaks	No				
Comments	No active leak seen. Residual oil at R/S lift cylinder				
Hydraulic System Overall	3 - Normal Wear & Tear				
Comments	Hydraulics were working well during inspection. Unable to get clear view of hydraulics underneath can but no signs of oil leaks seen from underneath frame.				

Bucket Inspection Points

Inspection Report (Compact Track Loader)

Bucket Photos	
	
Bucket	2 - Above Average Wear & Tear
Comments	Rear side of GP bucket outer layer cracked and split.
Bucket Edge / Deflectors	3 - Normal Wear & Tear

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	2 - Above Average Wear & Tear
Comments	Quick coupler attachment working great. Bucket okay to use but has some rear damage and.
Overall Functional Test Comments	Machine fired right up with no issues and hydraulics were operating well. Two speed and self leveling controls were operating as they should. A/C not operating at time of inspection.

Overall Assessment

Overall Assessment

Inspection Report (Compact Track Loader)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	
Interior Rating	3 - Normal Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
Summary Video	Click to Download	
What's Great About the Machine	Machines appearance shows it's been well maintained. No major active leaks seen from any of the major, exterior components. The engine sounds healthy and the hydraulics are working great.	
What Needs Work	A/C & Heater assembly inoperable. Front windshield missing. Front bucket damaged at rear. Minor seepage at L/H Joystick and R/S Lift cylinder rod seal. The operator seat is damaged and one exterior light inoperable.	
Date/Time	09-26-2023	
Inspector Name	Mario Ramirez	