

# Inspection Report (Skid Steer)

#### **General Info**

Control at time	
B&B Stock Number	A0438988
Year	2011
Make	Vermeer
Model	Rt45
Serial Number	1VRX0721161001237
Hour Meter Reading	1342.9
Previous Application (e.g., earth moving, mining, demolition, etc)	Earth moving

## **Features and Configuration**

reatures and Configuration	
Control Station Type	Canopy
Bucket	No
Additional Attachment(s)?	No
Auxiliary Hydraulics	No
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

#### **Exterior Walkaround Photos**

### 360 Walkaround & Operating Video

#### Walkaround Photos & Operating Video

Walkarourid Friolos & C	pordung video
Exterior Walkaround Photos	
Operating Video	Click to Download

# **General Appearance Inspection Points**

# **General Appearance**

## **General Appearance Photos**



# Inspection Report (Skid Steer)

Close-up Exterior Photos	Vermeer Vermee

### **General Appearance Inspection Points**

Inspection Poting Criteria	Rating Scale	Explanation
Inspection Rating Criteria	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	2 - Above Average Wear &	Tear
Body Panel Condition	Visible chipped paint or de	nts
Doors / Canopy Latches	0	
Steps / Ladders	3 - Normal Wear & Tear	
Handrails	0	
Glass	0	
Mirrors	0	
Exterior Lights	0	
Overall Exterior	3 - Normal Wear & Tear	




# Inspection Report (Skid Steer)

Comments Normal wear and tear

# **Control Station Inspection Points**

## **Control Station**





Hour Meter/Odometer



Seat	1 - Service Required
Seat Condition	Seat(s) has major surface staining or tears
Cabin Lights	0
Safety Lock Out / Stop	3 - Normal Wear & Tear




# Inspection Report (Skid Steer)

Controls & Switches	3 - Normal Wear & Tear
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	2 - Above Average Wear & Tear
Other Gauge Condition	Gauges are functional, with some wear and/or cosmetic damage
Heater & A/C	0
Travel Alarm	0
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling

# **Engine Inspection Points**

# **Engine**





# Inspection Report (Skid Steer)

Engine Type (Make, Model, Cylinders, Hp)	Deutz
Emissions Tier	Undetermined
Engine Serial Number	10162636
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	2 - Above Average Wear & Tear
Battery Condition	Dusty & dirty appearance
Radiator	3 - Normal Wear & Tear
Belts	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Water Pump	3 - Normal Wear & Tear
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Normal wear and tear. No major issues to report

# **Drivetrain Inspection Points**

#### **Drivetrain**

# **Drivetrain Inspection Points**



# Inspection Report (Skid Steer)

Drivetrain Photos		
Hydrostatic Transmission?	Yes	
2 Speed?	N/A	
Hydrostatic Drive Configuration	Close Coupled Transmission	
Drive	2WD	
Transmission Components	3 - Normal Wear & Tear	
Drive Motors	0	
Parking Brake	2 - Above Average Wear & Tear	
Overall Drivetrain Rating	3 - Normal Wear & Tear	
Overall Drivetrain Comments	Normal wear and tear. Dried seepage around drivetrain components	

**Chassis Inspection Points** 

Chassis Photos	
Frame	3 - Normal Wear & Tear
Lift Arms	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Quick Coupler	3 - Normal Wear & Tear
Quick Coupler to Arms Pins	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear no major issues to report



# Inspection Report (Skid Steer)

## Wheels & Tires

## Wheels & Tires

## Wheels & Tires Inspection Points

vineels & Tiles inspection Folitis	
Wheels & Hubs	3
Wheel Seal Leaks	No
Tire Brand	Deestone
Tire Size	26x12.00-12
Front Left Tire - Ratio Remaining	90%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	90%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	90%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	90%
Rear Left Tire Photos	

# **Hydraulics Overall Inspection Points**

# **Hydraulics Overall**

# **Hydraulic System Inspection Points**


Hydraulic System Photos	
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear



# Inspection Report (Skid Steer)

Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

# **Hydraulic Cylinder Inspection Points**



## **Functional Test**

# **Overall Functionality Assessment**

#### **Functionality Assessment**

Turiodioriality / tooodoriiori	
Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Normal wear and tear. No major issues to report

# **Inspection Summary**

#### **Overall Assessment**



# Inspection Report (Skid Steer)

Inspection Rating Criteria	Rating Scale	Explanation		
	1 - Service Required	Requires immediate repairs to function as expected.		
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.		
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.		
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.		
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.		
Exterior Rating	2 - Above Average Wear & Tear			
Interior Rating	3 - Normal Wear & Tear			
Safety Rating	3 - Normal Wear & Tear			
Quality Rating	3 - Normal Wear & Tear			
Functionality Rating	3 - Normal Wear & Tear			
Overall Rating	3 - Normal Wear & Tear			
What's Great About the Machine	-machine started right up with no abnormal nosies while operating			
What Needs Work	-dried seepage on drivetrain components			
Date/Time	09-27-2023			
Inspector Name	Javier Bocanegra			