

## Inspection Report (Skid Steer)

### General Info

B&B Stock Number	A6678184
Year	2010
Make	Caterpillar
Model	289C
Serial Number	CAT0289CHJMP01467
Hour Meter Reading	3438.4


### Features and Configuration

Control Station Type	Cab
Bucket	Yes
Bucket Specs	74"
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	Yes
A/C	Yes
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

### Exterior Walkaround Photos

#### 360 Walkaround & Operating Video

#### Walkaround Photos & Operating Video


Exterior Walkaround Photos	
Operating Video	<a href="#">Click to Download</a>

### General Appearance Inspection Points

#### General Appearance

#### General Appearance Photos

## Inspection Report (Skid Steer)



## General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents	
Doors / Canopy Latches	1 - Service Required	
Doors / Canopy Latches Condition	Other (see comments)	
Comments	Front entry door missing	
Steps / Ladders	3 - Normal Wear & Tear	

































## Inspection Report (Skid Steer)

Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Glass	3 - Normal Wear & Tear
Mirrors	0
Exterior Lights	3 - Normal Wear & Tear
Overall Exterior	3 - Normal Wear & Tear
Comments	Normal wear and tear no major issues to report

## Control Station Inspection Points



### Control Station

### Control Station Photos

Control Station Photos					
					
					
					
					
					
					



## Inspection Report (Skid Steer)

Serial Number Plate	
Hour Meter/Odometer	
Seat	3 - Normal Wear & Tear
Seat Condition	Seat(s) have minor surface staining or small tears, Seat adjustment controls have limited range of motion
Cabin Lights	3 - Normal Wear & Tear
Safety Lock Out / Stop	2 - Above Average Wear & Tear
Safety Lock Out / Stop Condition	Other (see comments)
Comments	Left side safety lock out loose
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	Switches have good functionality, minor cosmetic damage observed
Hour Meter Activity	3 - Normal Wear & Tear
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	1 - Service Required
Heater & A/C Condition	Fan vents are very dirty, Fan vents are damaged, Fan vents are not blowing air
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	1 - Service Required





## Inspection Report (Skid Steer)

Horn Condition	One or more elements of the horn assembly are missing
Comments	Horn inoperative
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling

## Engine Inspection Points

### Engine

### Engine Compartment Photos

Engine Data Plate					
Engine Compartment Photos					
Engine Type (Make, Model, Cylinders, Hp)	Cat, c3.4				
Emissions Tier	Undetermined				
Engine Serial Number	Unable to verify				
Engine Fuel Type	Diesel				
Blow-by (Visual Observation Check)	No				
Unusual Noises (Upon Start-up, Idle, Shutdown)	No				
Engine Smoke (Upon Start-up, Idle, Shutdown)	No				

## Inspection Report (Skid Steer)

Engine Exhaust Color	Heavy black smoke at start up
Battery	3 - Normal Wear & Tear
Battery Condition	Inaccessible, unable to determine condition
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Fuel Leaks	Yes
Fuel Leak Notes	Wet spots & streaking on fuel lines indicate an active leak
Comments	Fuel leak near bottom of engine
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	2 - Above Average Wear & Tear
Overall Engine Appearance	Active leaks/pooling observed in & around engine compartment
Overall Engine Comments	Fuel leak near bottom of engine

## Drivetrain Inspection Points

### Drivetrain


### Drivetrain Inspection Points

Drivetrain Photos	
Hydrostatic Transmission?	N/A
2 Speed?	N/A
Hydrostatic Drive Configuration	Other (see comments)
Comments	Drive motor

## Inspection Report (Skid Steer)

Drive	N/A
Transmission Components	0
Drive Motors	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear. No major issues to report

## Chassis Inspection Points

Chassis Photos	
Frame	3 - Normal Wear & Tear
Lift Arms	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Quick Coupler	3 - Normal Wear & Tear
Quick Coupler to Arms Pins	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear no major issues to report

## Wheels & Tires







## Wheels & Tires

## Wheels & Tires Inspection Points

Wheels & Hubs	0
Wheel Seal Leaks	No
Tire Brand	Tracks















## Inspection Report (Skid Steer)

Tire Size	Tracks
Front Left Tire - Ratio Remaining	10%
Front Left Tire Photos	  
Front Right Tire - Ratio Remaining	10%
Front Right Tire Photos	  
Rear Right Tire - Ratio Remaining	N/A
Rear Left Tire - Ratio Remaining	N/A






## Hydraulics Overall Inspection Points

### Hydraulics Overall

### Hydraulic System Inspection Points

Hydraulic System Photos	    
	    
	 
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

### Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	    
---------------------------	--

## Inspection Report (Skid Steer)

	   
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear
Comments	Normal wear tear no major issues to report

## Bucket Inspection Points

Bucket	3 - Normal Wear & Tear
Bucket Edge / Deflectors	3 - Normal Wear & Tear

## Functional Test

### Overall Functionality Assessment

### Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Normal wear and tear no major issues to report

## Inspection Summary

### Overall Assessment

Inspection Rating Criteria	<b>Rating Scale</b>	<b>Explanation</b>
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	

## Inspection Report (Skid Steer)

<b>Interior Rating</b>	2 - Above Average Wear & Tear
<b>Safety Rating</b>	3 - Normal Wear & Tear
<b>Quality Rating</b>	2 - Above Average Wear & Tear
<b>Functionality Rating</b>	3 - Normal Wear & Tear
<b>Overall Rating</b>	3 - Normal Wear & Tear
<b>What's Great About the Machine</b>	-Engine started right up with no abnormal noise heard
<b>What Needs Work</b>	-fuel leak at engine compartment -ripper wiring at auxiliary hydraulics -Worn tracks -missing front entry door
<b>Date/Time</b>	09-28-2023
<b>Inspector Name</b>	Javier Bocanegra