

Inspection Report (Telehandler)

General Info

B&B Stock Number	A4111496
Year	2015
Make	JLG
Model	G-10-55A
Serial Number	0160064621
Hour Meter Reading	7274.3
Previous Application (e.g., earth moving, mining, demolition, etc)	used as rental equipment

Dimensions

A. Length (ft and inches)	25ft 11in
B. Width (ft and inches)	8ft 5.5in
C. Height (ft and inches)	8ft 2in
Operational Weight (lbs)	uk

Features and Configuration

Control Station Type	Canopy
Max Lift Height	55ft
Max Lift Capacity	10,000lbs
Coupler Type	no
Forks / Work Tool Specs	Forks
Side Shift	Yes
Tilt Carriage	Yes
Frame Leveling	Yes
Outriggers	Yes
Additional Attachment(s)?	No
Auxiliary Hydraulics	No
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

360 Walkaround & Operating Video



Inspection Report (Telehandler)

Walkaround Photos & Operating Video

Exterior Walkaround Photos	
Operating Video	Click to Download

General Appearance Inspection Points

General Appearance

General Appearance Photos

General Appearance File	UlUS			
Close-up Exterior Photos				Hold
			SE SE C	
		TOS		

General Appearance Inspection Points

	Rating Scale	Explanation	
Inspection Rating Criteria	1 - Service Required	Requires immediate repairs to function as expected.	
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	
Body Panels	3 - Normal Wear & Tear		
Body Panel Condition	No visible damage, good paint condition and panel fitment		
Doors / Canopy Latches	3 - Normal Wear & Tear		
Doors / Canopy Latches Condition	No visible damage		
Steps / Ladders	3 - Normal Wear & Tear		
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound		
Handrails	3 - Normal Wear & Tear		
Handrails Condition	Handrails are fully intact and appear structurally sound		
Glass	3 - Normal Wear & Tear		



Inspection Report (Telehandler)

Glass Condition	Glass intact, no visible damage
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	One or more exterior lights are non-operational
Overall Exterior	3 - Normal Wear & Tear
Comments	The exterior is in good condition

Control Station Inspection Points

Control Station

Control Station Photos







Hour Meter/Odometer



Seat 3 - Normal Wear & Tear



Inspection Report (Telehandler)

Seat Condition	Seat(s) in good condition, no stains or tears in upholstery, Seat adjustment controls have limited range of motion, Seat belt secures properly, Seat belt is intact and in good condition
Cabin Lights	0
Safety Lock Out / Stop	0
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	Switches have good functionality, minor cosmetic damage observed, One or more switches are inoperative or missing
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	0
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Good cabin appearance, solid floors, panels, and ceiling

Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate



Engine Compartment Photos













Inspection Report (Telehandler)

Engine Type (Make, Model, Cylinders, Hp)	Cummings, QSB4.5 130,		
Emissions Tier	Undetermined		
Engine Serial Number	73742578		
Engine Fuel Type	Diesel		
Blow-by (Visual Observation Check)	No		
Unusual Noises (Upon Start-up, Idle, Shutdown)	No		
Engine Smoke (Upon Start-up, Idle, Shutdown)	No		
Engine Exhaust Color	Clear		
Battery	3 - Normal Wear & Tear		
Battery Condition	Dusty & dirty appearance		
Radiator	3 - Normal Wear & Tear		
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks		
Belts	2 - Above Average Wear & Tear		
Belt Condition	Frayed belt edges observed		
Hoses	2 - Above Average Wear & Tear		
Hose Condition	Cracking, stiff, or charred hoses, Other (see comments)		
Comments	Cracked hoses were seen in the engine bay. There are only two of them		
Water Pump	3 - Normal Wear & Tear		
Water Pump Condition	No unusual pump noises heard		
Cooling System Leaks	No		
Coolant Appearance	3 - Normal Wear & Tear		
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination		
Oil Leaks	No		
Oil Appearance	3 - Normal Wear & Tear		
Oil Appearance Notes	Appropriate oil level, Clean oil appearance, no signs of cross contamination		
Fuel Leaks	No		
Equipped with DPF (Diesel Particulate Filter)	No		



Inspection Report (Telehandler)

Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	The engine is in good working order

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points

Drivetrain Photos			
Hydrostatic Transmission?	No		
2 Speed?	No		
Hydrostatic Drive Configuration	Other (see comments)		
Comments	unable to verify		
Transmission Info (Make/Model/Speeds)	unable to verify		
Drive	4WD		
Transmission Components	3 - Normal Wear & Tear		
Transmission Condition	Good forward and reverse function, No unusual noises or vibrations		
Drive Motors	3 - Normal Wear & Tear		
Parking Brake	3 - Normal Wear & Tear		
Parking Brake Function	Good brake function		
Overall Drivetrain Rating	3 - Normal Wear & Tear		
Overall Drivetrain Comments	The drivtrain is in good condition		
Front Axle	3 - Normal Wear & Tear		
Rear Axle	3 - Normal Wear & Tear		

Wheels & Tires

Wheels & Tires Inspection Points

Wheels & Hubs	3
Wheel Seal Leaks	No



Inspection Report (Telehandler)

Tire Brand	Firestone
Tire Size	400/75-28
Front Left Tire - Ratio Remaining	90%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	90%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	90%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	90%
Rear Left Tire Photos	

Chassis Inspection Points

Chassis Photos			
Frame	3 - Normal Wear & Tear		
Stance	3 - Normal Wear & Tear		
Oscillating Pin Appearance	0		
Boom Condition	3 - Normal Wear & Tear		
Chain / Tensioners	3 - Normal Wear & Tear		
Rollers & Guides	3 - Normal Wear & Tear		
Boom Wear Guides	3 - Normal Wear & Tear		
Outriggers	3 - Normal Wear & Tear		
Overall Chassis	3 - Normal Wear & Tear		
Overall Chassis Comments	The chassis is in good condition		



Inspection Report (Telehandler)

Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos			
Wet or Damp Hydraulic Lines / Fittings	No		
Hydraulic Lines/Fittings	3 - Normal Wear & Tear		
Hydraulic Lines / Fittings Condition	Cracking, stiff, or charred hydraulic hoses		
Comments	several cracked hoses have been seen throughout the machine.		
Hydraulic Pump(s)	3 - Normal Wear & Tear		
Unusual Noises	No		
Hydraulic Pump Notes	No unusual noises heard during operation		

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Comments	The cylinders are in good shape
Hydraulic System Overall	3 - Normal Wear & Tear
Comments	The hydraulic system is fully functional

Additional Attachments



Inspection Report (Telehandler)

Additional Attachment(s)

Additional Attachments

Attachment Type	Forks
Attachment Make	unable to determine
Attachment Size / Specs	Forks are 3ft 11in long and 6ft 2in wide
Attachment Condition	3 - Normal Wear & Tear
Comments	minor dents
Attachment Photos	

Functional Test

Functionality Assessment

Functionality Assessment

Functionality Assessment	
Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	The machine is fully functional

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	



Inspection Report (Telehandler)

Interior Rating	3 - Normal Wear & Tear		
Safety Rating	3 - Normal Wear & Tear		
Quality Rating	2 - Above Average Wear & Tear		
Functionality Rating	3 - Normal Wear & Tear		
Overall Rating	3 - Normal Wear & Tear		
Summary Video	Click to Download		
What's Great About the Machine	The tires are great on the machine, like new, and the machine is fully operational		
What Needs Work	Some cracked hoses were seen, the engine bay latch does not lock in place.		
Any Additional Info from the Seller?	This machine was used in a rental company		
Date/Time	11-07-2023		
Inspector Name	Steven Mesa		