

Inspection Report (Boom Lift)

General Info

B&B Stock Number	A8315419
Year	2002
Make	Genie
Model	S-60
Serial Number	MO6005
Hour Meter Reading	7414
Previous Application (e.g., earth moving, mining, demolition, etc)	used in rental equipment

Dimensions


A. Length (ft and inches)	28ft 5in
B. Width (ft and inches)	8ft 2in
C. Height (ft and inches)	8ft 11in
Operational Weight (lbs)	unable to verify

Features and Configuration

Max Lift Height	60ft
Max Lift Capacity	750lbs
Electric Powertrain	No
Jib	No
Hydraulic Leveling	Yes
Power to Platform	Yes
Outriggers	No
Additional Attachment(s)?	Yes
OMM (Operator & Maintenance Manual)	Yes
Telematics	No

OMM Specifications

OMM Specifications









Detail Specifications	Take photos of the detailed spec pages included in the operator's manual
OMM Spec Photos	

Inspection Report (Boom Lift)

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	    
Operating Video	Click to Download
Additional Video	Click to Download

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos	    
	    

General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	0	
Handrails	0	
Glass	0	
Mirrors	0	




Inspection Report (Boom Lift)

Exterior Lights	0
Overall Exterior	3 - Normal Wear & Tear
Comments	Some minor chipping of paint can be seen but is considered normal wear and tear

Control Station Inspection Points

Control Station

Control Station Photos

Control Station Photos	
Serial Number Plate	
Hour Meter/Odometer	
Seat	0
Cabin Lights	0
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition



Inspection Report (Boom Lift)

Other Gauge Activity	3 - Normal Wear & Tear
Heater & A/C	0
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Other (see comments)

Powertrain Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate				
Engine Compartment Photos				
Engine Type (Make, Model, Cylinders, Hp)	Deutz, F4L 1011			
Emissions Tier	Undetermined			
Engine Serial Number	unable to verify			
Engine Fuel Type	Diesel			
Blow-by (Visual Observation Check)	No			
Unusual Noises (Upon Start-up, Idle, Shutdown)	No			
Engine Smoke (Upon Start-up, Idle, Shutdown)	No			
Engine Exhaust Color	Clear			
Battery	3 - Normal Wear & Tear			


Inspection Report (Boom Lift)

Battery Condition	Dusty & dirty appearance
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Oil Appearance Notes	Appropriate oil level, Clean oil appearance, no signs of cross contamination
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Clean & dry
Overall Engine Comments	The engine is in good working condition

Drivetrain Inspection Points

Drivetrain


Drivetrain Inspection Points

Drivetrain Photos						
Hydrostatic Transmission?	Yes					
2 Speed?	No					
Hydrostatic Drive Configuration	Other (see comments)					
Comments	unable to determine					

Inspection Report (Boom Lift)

Drive	4WD
Transmission Components	3 - Normal Wear & Tear
Drive Motors	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Parking Brake Function	Good brake function
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	The drivetrain is in good operating condition

Chassis Inspection Points









Chassis Photos					
Frame	3 - Normal Wear & Tear				
Stance	3 - Normal Wear & Tear				
Swing Table	3 - Normal Wear & Tear				
Boom	3 - Normal Wear & Tear				
Boom Wear Guides	3 - Normal Wear & Tear				
Jib	0				
Front Axle Appearance	3 - Normal Wear & Tear				
Rear Axle Appearance	3 - Normal Wear & Tear				

Wheels & Tires

Wheels & Tires Inspection Points

Wheels & Hubs	3
Wheel Seal Leaks	No
Tire Brand	Blackstone-OTR
Tire Size	15-9.5
Front Left Tire - Ratio Remaining	90%







Inspection Report (Boom Lift)

Front Left Tire Photos	 	
Front Right Tire - Ratio Remaining	90%	
Front Right Tire Photos	 	
Rear Right Tire - Ratio Remaining	70%	
Rear Right Tire Photos	 	
Rear Left Tire - Ratio Remaining	70%	
Rear Left Tire Photos	 	
Overall Chassis	3 - Normal Wear & Tear	




Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos	    	
		
Wet or Damp Hydraulic Lines / Fittings	No	
Hydraulic Lines/Fittings	3 - Normal Wear & Tear	
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition	
Hydraulic Pump(s)	3 - Normal Wear & Tear	
Unusual Noises	No	
Hydraulic Pump Notes	No unusual noises heard during operation	

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	    	
		









Inspection Report (Boom Lift)

Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear
Comments	The hydraulic system is in good working order

Additional Attachments

Additional Attachment(s)

Additional Attachments

Attachment Type	Platform				
Attachment Make	Genie				
Attachment Size / Specs	8ft wide, 3ft 7.5in high, 2ft 9.5in long				
Attachment Condition	3 - Normal Wear & Tear				
Attachment Photos					
					

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	The machines operates well and is fully functional

Overall Assessment

Overall Assessment

Inspection Report (Boom Lift)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	
Interior Rating	3 - Normal Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
Summary Video	Click to Download	
What's Great About the Machine	The machine works good and is fully operational	
What Needs Work	The machine is a little dirty	
Any Additional Info from the Seller?	This machine was used as rental equipment	
Date/Time	11-08-2023	
Inspector Name	Steven Mesa	