

Inspection Report (Boom Lift)

General Info

B&B Stock Number	M06003
Year	2002
Make	Genie
Model	S-60
Serial Number	M06003
Hour Meter Reading	7056
Previous Application (e.g., earth moving, mining, demolition, etc)	This machine was used as rental equipment

Dimensions

A. Length (ft and inches)	28ft 5in
B. Width (ft and inches)	8ft 2in
C. Height (ft and inches)	8ft 11in
Operational Weight (lbs)	unable to verify



Features and Configuration

Max Lift Height	60ft
Max Lift Capacity	750lbs
Electric Powertrain	Yes
Jib	No
Hydraulic Leveling	Yes
Power to Platform	Yes
Outriggers	No
Additional Attachment(s)?	Yes
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	 
Operating Video	Click to Download

Inspection Report (Boom Lift)

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos					
					

General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	0	
Handrails	0	
Glass	0	
Mirrors	0	
Exterior Lights	0	
Overall Exterior	3 - Normal Wear & Tear	
Comments	The exterior is in good condition	



Control Station Inspection Points

Control Station

Control Station Photos

Control Station Photos					
------------------------	---	---	--	---	--

Inspection Report (Boom Lift)

Serial Number Plate	
Hour Meter/Odometer	
Seat	0
Cabin Lights	0
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	1 - Service Required
Hour Meter Condition	Hour meter is unreadable or not functioning
Last Known Hour Meter Reading	7056
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	0
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn installed but functioning improperly, Other (see comments)











Inspection Report (Boom Lift)

Comments	The horn does not work
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Good cabin appearance, solid floors, panels, and ceiling

Powertrain Inspection Points

Electric Operating System

Electric Operating System Photos

Electric Operating System Photos	    
	    
Battery Condition	3 - Normal Wear & Tear
Battery Charger	3 - Normal Wear & Tear
Cables & Connections	3 - Normal Wear & Tear
Tight Connections?	Yes
Solenoids	3 - Normal Wear & Tear
Wire Harness	3 - Normal Wear & Tear
Fuse Panel(s)	3 - Normal Wear & Tear
Computer Appearance	3 - Normal Wear & Tear
Screen Discoloration?	No
Functional Check	3 - Normal Wear & Tear
Electric Operating System Overall Rating	3 - Normal Wear & Tear
Overall Electric Operating System Comments	The system is fully functional

Drivetrain Inspection Points

Drivetrain


Drivetrain Inspection Points

Drivetrain Photos	    
	
Hydrostatic Transmission?	Yes

Inspection Report (Boom Lift)

2 Speed?	No
Hydrostatic Drive Configuration	Other (see comments)
Comments	unable to verify
Drive	4WD
Transmission Components	3 - Normal Wear & Tear
Transmission Condition	Good forward and reverse function
Drive Motors	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Parking Brake Function	Good brake function
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	The drivetrain is in good working order

Chassis Inspection Points





Chassis Photos					
Frame	3 - Normal Wear & Tear				
Stance	3 - Normal Wear & Tear				
Swing Table	3 - Normal Wear & Tear				
Boom	3 - Normal Wear & Tear				
Boom Wear Guides	3 - Normal Wear & Tear				
Jib	0				
Front Axle Appearance	3 - Normal Wear & Tear				
Rear Axle Appearance	3 - Normal Wear & Tear				

Wheels & Tires

Wheels & Tires Inspection Points

Tire Brand	Blackstone-OTR
Tire Size	15-19.5
Front Left Tire - Ratio Remaining	70%



Inspection Report (Boom Lift)

Front Left Tire Photos		
Front Right Tire - Ratio Remaining	70%	
Front Right Tire Photos		
Rear Right Tire - Ratio Remaining	70%	
Rear Right Tire Photos		
Rear Left Tire - Ratio Remaining	70%	
Rear Left Tire Photos		
Overall Chassis	3 - Normal Wear & Tear	
Overall Chassis Comments	The chassis is in good working order.	

Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos		
		
Wet or Damp Hydraulic Lines / Fittings	No	
Hydraulic Lines/Fittings	3 - Normal Wear & Tear	
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition	
Hydraulic Pump(s)	3 - Normal Wear & Tear	
Unusual Noises	No	
Hydraulic Pump Notes	No unusual noises heard during operation	

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos		
---------------------------	--	--









Inspection Report (Boom Lift)

	  	
Mounting Pins	3 - Normal Wear & Tear	
Cylinder Oil Leaks	No	
Hydraulic System Overall	3 - Normal Wear & Tear	
Comments	The hydraulic system is good	

Additional Attachments

Additional Attachment(s)

Additional Attachments

Attachment Type	Platform				
Attachment Make	Genie				
Attachment Size / Specs	8ft wide, 3ft 8in tall, 2ft 9in long				
Attachment Condition	3 - Normal Wear & Tear				
Attachment Photos	    				
	   				

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	The machine is fully functional

Overall Assessment

Inspection Report (Boom Lift)

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	
Interior Rating	3 - Normal Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
Summary Video	Click to Download	
What's Great About the Machine	The machine works good and is fully functional	
What Needs Work	The right side rear tire is low, and the hour meter doesn't work properly	
Any Additional Info from the Seller?	This machine was used for rental equipment	
Date/Time	11-08-2023	
Inspector Name	Steven Mesa	