

## Inspection Report (Skid Steer)

### General Info

B&B Stock Number	A2175007
Year	2012
Make	Caterpillar
Model	259B3
Serial Number	CAT0259BJYYZ03372
Hour Meter Reading	3312.9
Previous Application (e.g., earth moving, mining, demolition, etc)	Earth moving


### Features and Configuration

Control Station Type	Cab
Bucket	Yes
Bucket Specs	.52 yd
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	Yes
A/C	Yes
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

### Exterior Walkaround Photos

#### 360 Walkaround & Operating Video

#### Walkaround Photos & Operating Video


Exterior Walkaround Photos	
Operating Video	<a href="#">Click to Download</a>

### General Appearance Inspection Points

#### General Appearance

#### General Appearance Photos

## Inspection Report (Skid Steer)



## General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	2 - Above Average Wear & Tear	
Body Panel Condition	Visible chipped paint or dents, Areas of surface rust observed	
Doors / Canopy Latches	1 - Service Required	
Doors / Canopy Latches Condition	Other (see comments)	
Comments	Missing cab door	
Steps / Ladders	3 - Normal Wear & Tear	
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	1 - Service Required	









































## Inspection Report (Skid Steer)

Glass Condition	Other (see comments)
Comments	Missing both side glass windows
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational
Overall Exterior	2 - Above Average Wear & Tear
Comments	Above average wear and tear to exterior paint with areas of surface rust




## Control Station Inspection Points

### Control Station

### Control Station Photos

Control Station Photos					
					
					
					
					
					
					
					

## Inspection Report (Skid Steer)

	
<b>Serial Number Plate</b>	
<b>Hour Meter/Odometer</b>	
<b>Seat</b>	3 - Normal Wear & Tear
<b>Seat Condition</b>	Seat(s) in good condition, no stains or tears in upholstery, Seat belt secures properly
<b>Cabin Lights</b>	1 - Service Required
<b>Cabin Lights Condition</b>	Cabin light system is not operational
<b>Comments</b>	Can dome light inoperable
<b>Safety Lock Out / Stop</b>	3 - Normal Wear & Tear
<b>Safety Lock Out / Stop Condition</b>	Safety lock out device is present, in good condition, and functional
<b>Controls &amp; Switches</b>	2 - Above Average Wear & Tear
<b>Controls &amp; Switches Condition</b>	Switches have good functionality, minor cosmetic damage observed
<b>Comments</b>	Minor cosmetic damage
<b>Hour Meter Activity</b>	3 - Normal Wear & Tear
<b>Hour Meter Condition</b>	Hour meter is functional and in good condition
<b>Other Gauge Activity</b>	3 - Normal Wear & Tear



## Inspection Report (Skid Steer)

Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	1 - Service Required
Heater & A/C Condition	Fan only, heating and A/C components inoperative
Travel Alarm	1 - Service Required
Travel Alarm Condition	System is configured but not operating correctly
Comments	No backup alarm
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Control Station Overall Rating	2 - Above Average Wear & Tear
Control Station Overall Condition	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling
Comments	Missing side glass windows on both sides. Missing cab door. A/C inoperative













## Engine Inspection Points

### Engine

### Engine Compartment Photos

<p>Engine Data Plate</p>	
<p>Engine Compartment Photos</p>	

## Inspection Report (Skid Steer)

	    
	    
	 
<b>Engine Type (Make, Model, Cylinders, Hp)</b>	MITSUBISHI , S4S-DTDPB
<b>Emissions Tier</b>	Tier 4i
<b>Engine Serial Number</b>	G23AE-119
<b>Engine Fuel Type</b>	Diesel
<b>Blow-by (Visual Observation Check)</b>	No
<b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b>	No
<b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>	Yes
<b>Engine Smoke Notes</b>	Engine smoke observed upon start up
<b>Comments</b>	Black smoke out the exhaust pipe upon start up
<b>Engine Exhaust Color</b>	Black
<b>Battery</b>	2 - Above Average Wear & Tear
<b>Battery Condition</b>	Dusty & dirty appearance
<b>Radiator</b>	3 - Normal Wear & Tear
<b>Radiator Condition</b>	Radiator fins & components appear to be in good working order, no signs of damage or leaks
<b>Belts</b>	3 - Normal Wear & Tear
<b>Belt Condition</b>	Belts appear in good condition & alignment with proper tension
<b>Hoses</b>	3 - Normal Wear & Tear
<b>Hose Condition</b>	Firm, pliant hoses with no signs of wear or leaks
<b>Water Pump</b>	3 - Normal Wear & Tear
<b>Water Pump Condition</b>	No unusual pump noises heard
<b>Cooling System Leaks</b>	No


## Inspection Report (Skid Steer)

Coolant Appearance	3 - Normal Wear & Tear
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	Yes
Oil Leak Notes	Wetness & discoloration observed, Wet areas with drops forming due to oil leakage
Comments	Leak near bottom of engine
Oil Appearance	3 - Normal Wear & Tear
Oil Appearance Notes	Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components, Active leaks/pooling observed in & around engine compartment
Overall Engine Comments	Normal wear and tear. Dried seepage and wetness near the bottom can of the engine

## Drivetrain Inspection Points

### Drivetrain


### Drivetrain Inspection Points

Drivetrain Photos	
Hydrostatic Transmission?	No
2 Speed?	No
Hydrostatic Drive Configuration	Other (see comments)
Comments	Drive motors
Drive	Other (see comments)
Other Drive Type	Rubber tracks
Transmission Components	0
Drive Motors	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Overall Drivetrain Rating	3 - Normal Wear & Tear

## Inspection Report (Skid Steer)

Overall Drivetrain Comments	No nowhere in tear no major issues report
-----------------------------	---

### Chassis Inspection Points

Chassis Photos	
Frame	3 - Normal Wear & Tear
Lift Arms	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Quick Coupler	3 - Normal Wear & Tear
Quick Coupler to Arms Pins	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear no major issues to report

### Wheels & Tires


### Wheels & Tires

### Wheels & Tires Inspection Points

Wheels & Hubs	3
Wheel Seal Leaks	No
Tire Brand	Cat
Tire Size	320x53x86
















## Inspection Report (Skid Steer)

Front Left Tire - Ratio Remaining	50%
Front Left Tire Photos	 
Front Right Tire - Ratio Remaining	50%
Front Right Tire Photos	 
Rear Right Tire - Ratio Remaining	N/A
Rear Left Tire - Ratio Remaining	N/A

## Hydraulics Overall Inspection Points


### Hydraulics Overall

### Hydraulic System Inspection Points

Hydraulic System Photos	    
	    
	  
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

## Hydraulic Cylinder Inspection Points

## Inspection Report (Skid Steer)

Hydraulic Cylinder Photos					
Mounting Pins	3 - Normal Wear & Tear				
Cylinder Oil Leaks	No				
Hydraulic System Overall	3 - Normal Wear & Tear				
Comments	Normal wear and tear no major issues to report				

## Bucket Inspection Points

Bucket	3 - Normal Wear & Tear				
Bucket Edge / Deflectors	3 - Normal Wear & Tear				

## Functional Test

### Overall Functionality Assessment

### Functionality Assessment

Engine	3 - Normal Wear & Tear				
Transmission/Drivetrain	3 - Normal Wear & Tear				
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear				
Brakes	0				
Hydraulic System	3 - Normal Wear & Tear				
Electric Operating System	3 - Normal Wear & Tear				
Controls	3 - Normal Wear & Tear				
Safety Systems	3 - Normal Wear & Tear				
Core Functions	3 - Normal Wear & Tear				
Attachments	3 - Normal Wear & Tear				
Overall Functional Test Comments	Normal wear and tear no major issues to report				

## Inspection Summary

### Overall Assessment

## Inspection Report (Skid Steer)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	2 - Above Average Wear & Tear	
Interior Rating	2 - Above Average Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	2 - Above Average Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
Summary Video	<a href="#">Click to Download</a>	
What's Great About the Machine	-stated right up with no abnormal noises heard	
What Needs Work	-A/C system inoperative -minor leak at bottom of engine	
Date/Time	11-09-2023	
Inspector Name	Javier Bocanegra	