

# Inspection Report (Telehandler)

#### **General Info**

B&B Stock Number	A6577409
Year	2013
Make	Caterpillar
Model	TH514C
Serial Number	unknown
Hour Meter Reading	5095
Previous Application (e.g., earth moving, mining, demolition, etc)	rental equipment

#### **Dimensions**

A. Length (ft and inches)	27ft 7in
B. Width (ft and inches)	8ft 5in
C. Height (ft and inches)	9ft
Operational Weight (lbs)	24890lbs

## **Features and Configuration**

Control Station Type	Canopy
Max Lift Height	45ft
Max Lift Capacity	3000lbs at max reach with stabilizers down
Forks / Work Tool Specs	5ft 11in long
Side Shift	Yes
Tilt Carriage	Yes
Frame Leveling	Yes
Outriggers	Yes
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	Yes
A/C	Yes
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

## **Exterior 360 Walkaround**

# 360 Walkaround & Operating Video

Walkaround Photos & Operating Video



# Inspection Report (Telehandler)

Exterior Walkaround Photos	
Operating Video	Click to Download

# **General Appearance Inspection Points**

# **General Appearance**

## **General Appearance Photos**

Close-up Exterior Photos			

# **General Appearance Inspection Points**

Inspection Rating Criteria	Rating Scale	Explanation	
	1 - Service Required	Requires immediate repairs to function as expected.	
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	
Body Panels	3 - Normal Wear & Tear		
Body Panel Condition	Other (see comments)		
Comments	In the engine bay panel/door there is a crack		
Doors / Canopy Latches	3 - Normal Wear & Tear		
Doors / Canopy Latches Condition	Other (see comments)		
Comments	The operator door does not close all the way shut		
Steps / Ladders	3 - Normal Wear & Tear		
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound		
Handrails	3 - Normal Wear & Tear		
Handrails Condition	Handrails are fully intact and appear structurally sound		
Glass	3 - Normal Wear & Tear		
Glass Condition	Glass intact, no visible damage		




# Inspection Report (Telehandler)

Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	One or more exterior lights are non-operational
Overall Exterior	3 - Normal Wear & Tear
Comments	The exterior is in good condition

# **Control Station Inspection Points**

#### **Control Station**





# Inspection Report (Telehandler)

Seat	3 - Normal Wear & Tear
Seat Condition	Seat(s) in good condition, no stains or tears in upholstery, Seat adjustment controls move through full range of travel, Seat belt shows limited functionality or does not secure properly
Cabin Lights	0
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	3 - Normal Wear & Tear
Heater & A/C Condition	Other (see comments)
Comments	The AC works, but it's not as cold as it should be
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Good cabin appearance, solid floors, panels, and ceiling

# **Engine Inspection Points**

# **Engine**

# **Engine Compartment Photos**

**Engine Data Plate** 





# Inspection Report (Telehandler)

Engine Compartment Photos			
Engine Type (Make, Model, Cylinders, Hp)	Cat, C3.4B		
Emissions Tier	Tier 4i		
Engine Serial Number	376-2072-CJG01437		
Engine Fuel Type	Diesel		
Blow-by (Visual Observation Check)	No		
Unusual Noises (Upon Start-up, Idle, Shutdown)	Yes		
Unusual Noise Notes	High-pitched metallic pinging heard		
Engine Smoke (Upon Start-up, Idle, Shutdown)	No		
Engine Exhaust Color	Clear		
Battery	3 - Normal Wear & Tear		
Battery Condition	Clean & dry appearance, tight connections		
Radiator	3 - Normal Wear & Tear		
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks		
Belts	2 - Above Average Wear & Tear		
Belt Condition	Belts appear in good condition & alignment with proper tension		
Hoses	3 - Normal Wear & Tear		
Hose Condition	Firm, pliant hoses with no signs of wear or leaks		
Water Pump	3 - Normal Wear & Tear		
Water Pump Condition	No unusual pump noises heard		
Cooling System Leaks	No		
Coolant Appearance	3 - Normal Wear & Tear		
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination		
Oil Leaks	No		
Oil Appearance	3 - Normal Wear & Tear		
Oil Appearance Notes	Appropriate oil level, Clean oil appearance, no signs of cross contamination		



# Inspection Report (Telehandler)

Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	A high-pitched squeaking sound is present when the machine starts

# **Drivetrain Inspection Points**

#### **Drivetrain**

**Drivetrain Inspection Points** 

Drivetrain Photos			
Lhydroctotic Transmission?	Yes		
Hydrostatic Transmission? 2 Speed?	No		
•			
Hydrostatic Drive Configuration	Other (see comments)		
Comments	unable to verify		
Drive	4WD		
Transmission Components	3 - Normal Wear & Tear		
Transmission Condition	Good forward and reverse function		
Drive Motors	3 - Normal Wear & Tear		
Parking Brake	3 - Normal Wear & Tear		
Parking Brake Function	Good brake function		
Overall Drivetrain Rating	3 - Normal Wear & Tear		
Overall Drivetrain Comments	The drivetrain is in good operating condition		
Front Axle	3 - Normal Wear & Tear		



# Inspection Report (Telehandler)

Rear Axle	3 - Normal Wear & Tear
VA/In a alla O Tima a	

#### Wheels & Tires

Wheels & Tires Inspection	n Points
Wheels & Hubs	3
Wheel Seal Leaks	No
Tire Brand	Gamso
Tire Size	14.00-24
Front Left Tire - Ratio Remaining	30%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	50%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	30%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	10%
Rear Left Tire Photos	

## **Chassis Inspection Points**

Chassis Photos	
Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Oscillating Pin Appearance	0



## Inspection Report (Telehandler)

Boom Condition	3 - Normal Wear & Tear
Chain / Tensioners	3 - Normal Wear & Tear
Rollers & Guides	3 - Normal Wear & Tear
Boom Wear Guides	3 - Normal Wear & Tear
Outriggers	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	The chassis is in good condition

# **Hydraulics Overall Inspection Points**

# **Hydraulics Overall**

# **Hydraulic System Inspection Points**

Hydraulic System Photos	AND
	10225 The second of the second
Wet or Damp Hydraulic Lines / Fittings	Yes
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

# **Hydraulic Cylinder Inspection Points**

Hydraulic Cylinder inspection Points				
Hydraulic Cylinder Photos				
Mounting Pins	3 - Normal Wear & Tear			
Cylinder Oil Leaks	No			



# Inspection Report (Telehandler)

Comments	The hydraulic cylinders are in good working order
Hydraulic System Overall	3 - Normal Wear & Tear
Comments	The hydraulic system is fully operational

#### **Additional Attachments**

# Additional Attachment(s)

#### **Additional Attachments**

/ taattorial / titaoriii lorito	
Attachment Type	Forks
Attachment Make	Arrow
Attachment Condition	3 - Normal Wear & Tear
Attachment Photos	

## **Functional Test**

## **Functionality Assessment**

## **Functionality Assessment**

Engine .	
Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	The machine is fully functional and operational

## **Overall Assessment**

#### **Overall Assessment**



# Inspection Report (Telehandler)

Inspection Rating Criteria	Rating Scale	Explanation		
moposition realing of the transfer of the tran	1 - Service Required	Requires immediate repairs to function as expected.		
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.		
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.		
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.		
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.		
Exterior Rating	3 - Normal Wear & Tear			
Interior Rating	3 - Normal Wear & Tear	3 - Normal Wear & Tear		
Safety Rating	3 - Normal Wear & Tear			
Quality Rating	3 - Normal Wear & Tear			
Functionality Rating	3 - Normal Wear & Tear			
Overall Rating	3 - Normal Wear & Tear			
Summary Video	Click to Download			
What's Great About the Machine	The machine is fully functional and operational			
What Needs Work	The door closes but a gap remains, a high pitched squeaking sound can be heard coming from the engine.			
Any Additional Info from the Seller?	No			
Date/Time	11-06-2023			
Inspector Name	Steven Mesa			