

Inspection Report (On-Highway Service Truck)

General Info

| | |
|--|-------------------|
| B&B Stock Number | A1838822 |
| Year | 2006 |
| Make | Frightliner |
| Model | M2 |
| Serial Number | 1FVACXCS46HX05951 |
| Odometer Reading | 42028.4 |
| Current Inspection / State Cert / DOT | Unable to verify |
| Previous Application (e.g., earth moving, mining, demolition, etc) | Hi-rail truck |

Dimensions

| | |
|---------------------------|--------|
| Length (ft and inches) | 33'5" |
| Width (ft and inches) | 8'4" |
| Height (ft and inches) | 11'6" |
| Wheelbase (ft and inches) | 240" |
| GVWR (lbs) | 33,000 |

Features and Configuration

| | |
|----------------------------|------------------|
| Drive Type | 4X2 |
| Overdrive | Yes |
| Heat | Yes |
| A/C | Yes |
| Radio | Yes |
| Backup Camera | No |
| Cruise Control | Yes |
| PTO | Yes |
| PTO Details | Unable to verify |
| Engine Brake Configuration | N/A |
| Differential Lock | No |
| Auxiliary Engine | No |
| Liftgate | No |
| Generator | No |
| Welder | No |
| Air Compressor | No |
| Crane | Yes |

Inspection Report (On-Highway Service Truck)

| | |
|-------------------------------------|--------------------|
| Crane Make & Model | Palfinger psc 6000 |
| Lifting Capacity (lbs) | Unable to verify |
| Max Vertical Lift (ft and inches) | Unable to verify |
| Stabilizer Jacks | Yes |
| Telematics | No |
| OMM (Operator & Maintenance Manual) | Yes |

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

| | |
|----------------------------|--|
| Exterior Walkaround Photos |      |
| |    |
| Operating Video | Click to Download |
| Additional Video | Click to Download |


General Appearance Inspection Points

General Appearance

General Appearance Photos

| | |
|--------------------------|--|
| Close-up Exterior Photos |      |
| |      |
| |      |
| |      |
| |      |

Inspection Report (On-Highway Service Truck)



General Appearance Inspection Points

| Inspection Rating Criteria | Rating Scale | Explanation |
|---|--|---|
| | 1 - Service Required | Requires immediate repairs to function as expected. |
| | 2 - Above Average Wear & Tear | Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed. |
| | 3 - Normal Wear & Tear | Exhibits wear that is consistent with age and usage. Operation is normal, and as expected. |
| | 4 - Very Light or Minimal Wear | Exhibits very minimal wear. Operation is better than expected given age and usage. |
| | 5 - Like New, Recently Replaced | Excellent condition, free of visible wear or damage. Operation is within factory specifications. |
| Body Panels | 2 - Above Average Wear & Tear | |
| Body Panel Condition | Some panel misalignment observed, Visible chipped paint or dents, Areas of surface rust observed | |
| Comments | Chipped paint/ surface rust | |
| Doors / Canopy Latches | 2 - Above Average Wear & Tear | |
| Doors / Canopy Latches Condition | Intermittent sticking observed on one or more latches/doors, Loose or missing latches, hinges or handles | |

Inspection Report (On-Highway Service Truck)

| | |
|---------------------------|--|
| Comments | Latching mechanism to tool boxes loose and sticking |
| Steps / Ladders | 2 - Above Average Wear & Tear |
| Steps / Ladders Condition | Bent or broken steps or rungs |
| Comments | Bent steps at rear |
| Handrails | 3 - Normal Wear & Tear |
| Handrails Condition | Handrails are fully intact and appear structurally sound |
| Glass | 3 - Normal Wear & Tear |
| Mirrors | 3 - Normal Wear & Tear |
| Exterior Lights | 3 - Normal Wear & Tear |
| Overall Exterior | 3 - Normal Wear & Tear |
| Comments | Normal wear and tear no major issues to report |

Cab Inspection Points

On Highway - Cab

Cab Interior Photos

| | | | | | |
|---------------------|---|---|--|---|---|
| Cab Interior Photos |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |
| |  |  |  |  |  |

Inspection Report (On-Highway Service Truck)

| | |
|---|--|
| |  |
| VIN/Serial Number Plate Photo |  |
| Odometer Photo |  |
| Odometer Activity | 3 - Normal Wear & Tear |
| Odometer | Odometer is working and in good condition |
| Controls/Switches/Gauges | 2 - Above Average Wear & Tear |
| Controls/Switches/Gauges | Minor cosmetic wear to switches/gauges, good functionality, One or more switches/gauges are inoperative or missing |
| Brake System Type | Air Brakes |
| Air Brakes Build Correct Pressure | Yes |
| Clutch | 2 - Above Average Wear & Tear |
| Clutch Function | Some play or friction detected |
| Horn | 3 - Normal Wear & Tear |
| Horn Function | Horn is functioning as expected |
| Reverse Alarm / Backup Camera | 3 - Normal Wear & Tear |
| Reverse Alarm / Backup Camera Condition | Reverse alarm working as expected |


Inspection Report (On-Highway Service Truck)

| | |
|----------------------|---|
| Heater & A/C | 1 - Service Required |
| Heat & A/C | Fan only, heating and A/C components inoperative |
| Interior Lights | 1 - Service Required |
| Interior Lights | Interior light system is inoperative |
| Seats/Seat Belts | 3 - Normal Wear & Tear |
| Cab Interior Overall | 2 - Above Average Wear & Tear |
| Comments | Above average wear and tear to the seats and floor paneling |

Engine Inspection Points

Engine

Engine Compartment Photos

| | | | | | |
|--|--|--|--|--|--|
| Engine Data Plate |  | | | | |
| Engine Compartment Photos |  | | | | |
| Engine Type (Make, Model, Cylinders, Hp) | Mercedes MBE 900-230 6.4L 230Hp | | | | |
| Emissions Tier | Tier 4F | | | | |
| Engine Serial Number | 0906524255 | | | | |

Inspection Report (On-Highway Service Truck)

| | |
|--|--|
| Engine Fuel Type | Diesel |
| Blow-by (Visual Observation Check) | No |
| Unusual Noises (Upon Start-up, Idle, Shutdown) | No |
| Engine Smoke (Upon Start-up, Idle, Shutdown) | No |
| Engine Exhaust Color | Clear |
| Battery | 3 - Normal Wear & Tear |
| Radiator | 3 - Normal Wear & Tear |
| Belts | 3 - Normal Wear & Tear |
| Hoses | 3 - Normal Wear & Tear |
| Water Pump | 3 - Normal Wear & Tear |
| Cooling System Leaks | No |
| Coolant Appearance | 3 - Normal Wear & Tear |
| Oil Leaks | Yes |
| Oil Leak Notes | Dried oil seepages seen, Wetness & discoloration observed, Wet areas with drops forming due to oil leakage |
| Comments | Wetness found near bottom of engine |
| Oil Appearance | 3 - Normal Wear & Tear |
| Oil Appearance Notes | Appropriate oil level |
| Fuel Leaks | No |
| Equipped with DPF (Diesel Particulate Filter) | Yes |
| DPF Condition | 3 - Normal Wear & Tear |
| DPF Condition Notes | Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated |
| Requires DEF (Diesel Exhaust Fluid) | Yes |
| DEF Tank | 3 - Normal Wear & Tear |
| DEF Tank Condition | Area around DEF tank cap is clean, fluid is clear & appears free of contaminants |
| Overall Engine Rating | 2 - Above Average Wear & Tear |
| Overall Engine Appearance | Areas of dried seepage seen on engine hoses & components |
| Overall Engine Comments | Normal wear and tear with minor leaks |

Chassis & Drivetrain Inspection Points

On-Highway: Underbody Components

Chassis & Drivetrain Photos

Inspection Report (On-Highway Service Truck)

| | | | | | |
|---------------------------------------|--|--|--|--|--|
| Chassis & Drivetrain Underside Photos |  | | | | |
| |  | | | | |
| |  | | | | |
| |  | | | | |
| |  | | | | |
| |  | | | | |
| |  | | | | |
| |  | | | | |
| |  | | | | |

Chassis Inspection Points

| | |
|---------------------------|--|
| Frame | 3 - Normal Wear & Tear |
| Suspension | 2 - Above Average Wear & Tear |
| Steer Axle | 3 - Normal Wear & Tear |
| Steering Components | 3 - Normal Wear & Tear |
| Overall Chassis Condition | 3 - Normal Wear & Tear |
| Overall Chassis Comments | Normal wear and tear no major issues to report |

Drivetrain Inspection Points

| | |
|--------------------------------|------------------|
| Transmission Info (Make/Model) | Unable to verify |
|--------------------------------|------------------|

Inspection Report (On-Highway Service Truck)

| | |
|------------------------------|--|
| Transmission | 3 - Normal Wear & Tear |
| PTO | 3 - Normal Wear & Tear |
| Rear Differential | 3 - Normal Wear & Tear |
| Front Differential | 0 |
| Brake Shoe Thickness | 50% |
| Air Brake System Leaks | No |
| Air Brake Hose Condition | 3 - Normal Wear & Tear |
| Overall Drivetrain Condition | 3 - Normal Wear & Tear |
| Overall Drivetrain Comments | Normal wear and tear no major issues to report |

Wheels & Tires Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points

| | |
|------------------------------------|---|
| Wheels & Hubs | 3 |
| Wheel Seal Leaks | No |
| Tire Brand | Handcook |
| Tire Size | 11R22.5 |
| Front Left Tire - Ratio Remaining | 50% |
| Front Left Tire Photos |  |
| Front Right Tire - Ratio Remaining | 50% |
| Front Right Tire Photos |  |
| Rear Right Tire - Ratio Remaining | 70% |
| Rear Right Tire Photos |  |
| Rear Left Tire - Ratio Remaining | 70% |
| Rear Left Tire Photos |  |

Inspection Points

Service Truck Body

Inspection Report (On-Highway Service Truck)

Inspection Points: Tool Truck Body

| | |
|------------------------|--|
| Tool Truck Body Photos |      |
| |    |
| Service Body | 2 - Above Average Wear & Tear |
| Toolboxes | 2 - Above Average Wear & Tear |
| Liftgate Function | 0 |
| Crane | 3 - Normal Wear & Tear |
| Crane Photos |  |
| Stabilizer Jacks | 3 - Normal Wear & Tear |

Functional Test

Functionality Assessment

Functionality Assessment

| | |
|-----------------------------------|--|
| Engine | 3 - Normal Wear & Tear |
| Transmission/Drivetrain | 3 - Normal Wear & Tear |
| Travel (Forward/Reverse/Steering) | 3 - Normal Wear & Tear |
| Brakes | 3 - Normal Wear & Tear |
| Hydraulic System | 3 - Normal Wear & Tear |
| Electric Operating System | 3 - Normal Wear & Tear |
| Controls | 2 - Above Average Wear & Tear |
| Comments | Worn decals and cut wiring |
| Safety Systems | 3 - Normal Wear & Tear |
| Core Functions | 3 - Normal Wear & Tear |
| Attachments | 3 - Normal Wear & Tear |
| Overall Functional Test Comments | Normal wear and tear no major issues to report |

Inspection Summary

Overall Assessment

Inspection Report (On-Highway Service Truck)

| Inspection Rating Criteria | Rating Scale | Explanation |
|--------------------------------|---|---|
| | 1 - Service Required | Requires immediate repairs to function as expected. |
| | 2 - Above Average Wear & Tear | Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed. |
| | 3 - Normal Wear & Tear | Exhibits wear that is consistent with age and usage. Operation is normal, and as expected. |
| | 4 - Very Light or Minimal Wear | Exhibits very minimal wear. Operation is better than expected given age and usage. |
| | 5 - Like New, Recently Replaced | Excellent condition, free of visible wear or damage. Operation is within factory specifications. |
| Exterior Rating | 2 - Above Average Wear & Tear | |
| Interior Rating | 2 - Above Average Wear & Tear | |
| Safety Rating | 3 - Normal Wear & Tear | |
| Quality Rating | 3 - Normal Wear & Tear | |
| Functionality Rating | 3 - Normal Wear & Tear | |
| Overall Rating | 3 - Normal Wear & Tear | |
| What's Great About the Machine | -starts right up -no abnormal noise heard for engine compartment | |
| What Needs Work | -wiring to control in cab -dried seepage and wetness near bottom of engine | |
| Date/Time | 11-13-2023 | |
| Inspector Name | Javier Bocanegra | |