

General Info

B&B Stock Number	A8652557
Year	2018
Make	Caterpillar
Model	299D2
Serial Number	CAT0299DTFD203523
Hour Meter Reading	2027.4
Previous Application (e.g., earth moving, mining, demolition, etc)	Unknown

Dimensions

A. Length (ft and inches)	13ft 5in
B. Width (ft and inches)	6ft 3in
C. Height (ft and inches)	8ft 11in
Operational Weight (lbs)	11, 608

Features and Configuration

Control Station Type	Cab
Bucket	Yes
Bucket Specs	78in wide, 34.5in long, 21.5in tall
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
High Flow	No
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos







Operating Video

Click to Download

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos



General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation		
·····	1 - Service Required	Requires immediate repairs to function as expected.		
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.		
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.		
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.		
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.		
Body Panels	3 - Normal Wear & Tear			
Body Panel Condition	No visible damage, good paint condition and panel fitment, Other (see comments)			
Comments	some minor scratches were seen on the exterior			
Doors / Canopy Latches	3 - Normal Wear & Tear			
Doors / Canopy Latches Condition	No visible damage			
Steps / Ladders	3 - Normal Wear & Tear			
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound			
Handrails	3 - Normal Wear & Tear			
Handrails Condition	Handrails are fully intact and appear structurally sound			
Glass	0			
Mirrors	0			
Exterior Lights	3 - Normal Wear & Tear			




Exterior Lights Condition	No visible damage, lighting system is operational		
Overall Exterior	3 - Normal Wear & Tear		
Comments	The exterior is in good condition with a normal amount of wear and tear		

Control Station Inspection Points

Control Station

Control Station Photos





Cabin Lights	3 - Normal Wear & Tear		
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly		
Safety Lock Out / Stop	3 - Normal Wear & Tear		
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional		
Controls & Switches	3 - Normal Wear & Tear		
Controls & Switches Condition	All switches are installed and functional		
Hour Meter Activity	3 - Normal Wear & Tear		
Hour Meter Condition	Hour meter is functional and in good condition		
Other Gauge Activity	3 - Normal Wear & Tear		
Other Gauge Condition	All cockpit gauges are functional and in good condition		
Heater & A/C	0		
Travel Alarm	3 - Normal Wear & Tear		
Travel Alarm Condition	Travel alarm is installed and functioning as expected		
Horn	3 - Normal Wear & Tear		
Horn Condition	Horn is installed and functioning as expected		
Backup Camera	0		
Control Station Overall Rating	3 - Normal Wear & Tear		
Control Station Overall Condition	Good cabin appearance, solid floors, panels, and ceiling		

Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate



Engine Compartment Photos



Engine Type (Make, Model, Cylinders, Hp)	Cat, C3.8, 95hp			
Emissions Tier	Tier 4F			
Engine Serial Number	unable to verify			
Engine Fuel Type	Diesel			
Blow-by (Visual Observation Check)	Yes			
Unusual Noises (Upon Start-up, Idle, Shutdown)	No			
Engine Smoke (Upon Start-up, Idle, Shutdown)	No			
Engine Exhaust Color	Clear			
Battery	3 - Normal Wear & Tear			
Battery Condition	Dusty & dirty appearance			
Radiator	3 - Normal Wear & Tear			
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks			
Belts	3 - Normal Wear & Tear			
Belt Condition	Belts appear in good condition & alignment with proper tension			
Hoses	3 - Normal Wear & Tear			
Hose Condition	Firm, pliant hoses with no signs of wear or leaks			
Water Pump	3 - Normal Wear & Tear			
Water Pump Condition	No unusual pump noises heard			
Cooling System Leaks	No			
Coolant Appearance	3 - Normal Wear & Tear			
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination			
Oil Leaks	No			
Oil Appearance	3 - Normal Wear & Tear			
Oil Appearance Notes	Appropriate oil level, Clean oil appearance, no signs of cross contamination			
Fuel Leaks	No			
Equipped with DPF (Diesel Particulate Filter)	Yes			
DPF Condition	3 - Normal Wear & Tear			
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated			



Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	The engine is in good working condition

Drivetrain Inspection Points

Drivetrain

Drivetrain Inspection Points

Drivetrain Photos			
Hydrostatic Transmission?	Yes		
2 Speed?	Yes		
Hydrostatic Drive Configuration	Other (see comments)		
Comments	Drive motor		
Drive	Other (see comments)		
Other Drive Type	tracks		
Transmission Components	3 - Normal Wear & Tear		
Transmission Condition	Good forward and reverse function, No unusual noises or vibrations		
Drive Motors	3 - Normal Wear & Tear		
Parking Brake	3 - Normal Wear & Tear		
Parking Brake Function	Good brake function		
Overall Drivetrain Rating	3 - Normal Wear & Tear		
Overall Drivetrain Comments	The drivetrain is fully operational and in good condition		

Undercarriage Inspection Points

Rubber Track Undercarriage

Undercarriage Photos

Undercarriage Photos







Inspection Points

Track Width (inches)	17 3/4in
Track Length (inches)	87in
Roller Frames	3 - Normal Wear & Tear
Track Belt	3 - Normal Wear & Tear
Rubber Belt Drive Lugs	3 - Normal Wear & Tear
Track Tensioners	3 - Normal Wear & Tear
Front Idlers	3 - Normal Wear & Tear
Rear Idlers	3 - Normal Wear & Tear
Track Rollers	3 - Normal Wear & Tear
Sprockets	3 - Normal Wear & Tear
Overall Undercarriage Rating	3 - Normal Wear & Tear
Left Track Belt - Percent Remaining Estimate	70%
Right Track Belt - Percent Remaining Estimate	70%
Overall Comments	The undercarriage is in good working order

Chassis Photos

Chassis Photos				
	6	To	TO	
			0	0

Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Lift Arm	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Quick Coupler	0
Quick Coupler to Arms Pins	0



Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	The chassis is in good condition

Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos			
Wet or Damp Hydraulic Lines / Fittings	No		
Hydraulic Lines/Fittings	3 - Normal Wear & Tear		
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition		
Hydraulic Pump(s)	3 - Normal Wear & Tear		
Unusual Noises	No		
Hydraulic Pump Notes	No unusual noises heard during operation		

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No



Comments	Hydraulic cylinders are in good working order		
Hydraulic System Overall	3 - Normal Wear & Tear		
Comments	The overall hydraulic system is fully functional with a normal amount of wear and tear		

Bucket Inspection Points

Bucket Photos	
Bucket	3 - Normal Wear & Tear
Bucket Edge / Deflectors	3 - Normal Wear & Tear

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	The machine is fully functional and operational

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	
Interior Rating	3 - Normal Wear & Tear	



Safety Rating	3 - Normal Wear & Tear			
Quality Rating	3 - Normal Wear & Tear			
Functionality Rating	3 - Normal Wear & Tear			
Overall Rating	3 - Normal Wear & Tear			
Summary Video	Click to Download			
What's Great About the Machine	The machine started right up without any issues and is fully functional			
What Needs Work	Some rust was seen on the hydraulic connections going to the drive motors			
Any Additional Info from the Seller?	No			
Date/Time	12-01-2023			
Inspector Name	Steven Mesa			