



## Inspection Report (On-Highway Service Truck)

### General Info

B&B Stock Number	A3412548
Year	2016
Make	Ford
Model	F550
Serial Number	1FDUF5GT0GEB33556
Truck Odometer Reading	169889
Current Inspection / State Cert / DOT	Unable to verify
Previous Application (e.g., earth moving, mining, demolition, etc)	Service truck

### Dimensions

Length (ft and inches)	23' 8"
Width (ft and inches)	7' 11"
Height (ft and inches)	7' 8"
Wheelbase (ft and inches)	7'
GVWR (lbs)	18,000 lb

### Features and Configuration

Drive Type	4X2
Overdrive	Yes
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	No
Engine Brake	No
Differential Lock	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Auxiliary Engine	No
Liftgate	No
Generator	No
Welder	No

## Inspection Report (On-Highway Service Truck)

Air Compressor	Yes
Air Compressor Make & Model	Vmac/ VR150
Air Compressor Specifications (cfm, psi, Hp)	150cfm, 90psi
Crane	No
Stabilizer Jacks	No
Other Configuration Details / Features / Notes	Fuel storage and dispensing system

### Exterior 360 Walkaround

### 360 Walkaround & Operating Video

### Walkaround Photos & Operating Video

Exterior Walkaround Photos	
Operating Video	<a href="#">Click to Download</a>

### General Appearance Inspection Points

### General Appearance





































### Inspection Rating Criteria

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.

### General Appearance Photos

Close-up Exterior Photos	
--------------------------	--

### Inspection Report (On-Highway Service Truck)

					
					
			Dent on rear right storage box door		
					
					
					
					
					
		Dent on driver door			Ripped welds on rear guard
					

### General Appearance Inspection Points

Body Panels	2 - Above Average Wear & Tear
Body Panel Condition	Visible chipped paint or dents
Comments	Scratches, dents and ripped welds
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	Intermittent sticking observed on one or more latches/doors
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound




































## Inspection Report (On-Highway Service Truck)

Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational






































### Cab Inspection Points

#### On Highway - Cab



#### Cab Interior Photos

Cab Interior Photos					
					
					
					
					
					
					

### Inspection Report (On-Highway Service Truck)







						Broken display to radio
						
						Worn steering wheel
						Stained and dirty headliner
						Compressor switch Ripped driver seat
						
						Peeling paint on door handle
						

## Inspection Report (On-Highway Service Truck)

VIN/Serial Number Plate Photo	 <p>INCOMPLETE VEHICLE MANUFACTURED BY FORD MOTOR COMPANY DATE: 10/15 GVWR: 8165 KG (18000 LB) FRONT GAWR: 2722 KG (6000 LB) REAR GAWR: 6196 KG (13660 LB) 225/70R19.5G 128/126N WITH 19.5x8.0RW TIRE RIMS AT 655 kPa/ 95 PSI COLD VIN: 1FDUF5GT0GEB33556 DUAL EXT PNT: 21 RC: 72 DSG: WB 165 INT TR 105/95 R T AXLE TR SPR 5 4N W CCB UNK 05USA-1520472-04</p>
Odometer Photo	 <p>169889 mi 74F N ULTRA LOW SULFUR DIESEL FUEL ONLY P R N D M 2 1</p>
Odometer Activity	3 - Normal Wear & Tear
Odometer Condition	Odometer is working and in good condition
Controls/Switches/Gauges	3 - Normal Wear & Tear
Controls/Switches/Gauges Condition	All switches/gauges are in good condition and functioning
Brake System Type	Hydraulic
Clutch	0
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is functioning as expected
Reverse Alarm / Backup Camera	3 - Normal Wear & Tear
Reverse Alarm / Backup Camera Condition	Reverse alarm working as expected
Heater & A/C	3 - Normal Wear & Tear
Heat & A/C Condition	Fan vents are very dirty, Heater and A/C work as expected
Interior Lights	1 - Service Required
Interior Lights Condition	One or more lights are inoperable/damaged
Comments	Passenger side dome light inoperative



## Inspection Report (On-Highway Service Truck)

	    
	
<b>Engine Type (Make, Model, Cylinders, Hp)</b>	Ford. 6.7, Power Stroke, 6 cyl, 300 Hp
<b>Emissions Tier</b>	Tier 4F
<b>Engine Serial Number</b>	Unable to verify
<b>Engine Fuel Type</b>	Diesel
<b>Blow-by (Visual Observation Check)</b>	No
<b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b>	No
<b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>	No
<b>Engine Exhaust Color</b>	Clear
<b>Battery</b>	3 - Normal Wear & Tear
<b>Battery Condition</b>	Dusty & dirty appearance
<b>Radiator</b>	3 - Normal Wear & Tear
<b>Radiator Condition</b>	Radiator fins & components appear to be in good working order, no signs of damage or leaks
<b>Belts</b>	3 - Normal Wear & Tear
<b>Belt Condition</b>	Belts appear in good condition & alignment with proper tension
<b>Hoses</b>	3 - Normal Wear & Tear
<b>Hose Condition</b>	Firm, pliant hoses with no signs of wear or leaks
<b>Water Pump</b>	3 - Normal Wear & Tear
<b>Water Pump Condition</b>	No unusual pump noises heard
<b>Cooling System Leaks</b>	No
<b>Coolant Color / Appearance</b>	3 - Normal Wear & Tear
<b>Coolant Color/Appearance Notes</b>	Normal Translucent appearance, no visual signs of contamination
<b>Oil Leaks</b>	No
<b>Oil Color / Appearance</b>	3 - Normal Wear & Tear
<b>Oil Color / Appearance Notes</b>	Appropriate oil level






































## Inspection Report (On-Highway Service Truck)

Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	Normal wear and tear. No major issues to report

### Chassis & Drivetrain Inspection Points

#### On-Highway: Underbody Components

#### Chassis & Drivetrain Photos

Chassis & Drivetrain Underside Photos					
					
					
					
					
					
					

## Inspection Report (On-Highway Service Truck)



### Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Suspension	3 - Normal Wear & Tear
Steer Axle	3 - Normal Wear & Tear
Steering Components	3 - Normal Wear & Tear
Overall Chassis Condition	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear

### Drivetrain Inspection Points

Transmission Info (Make/Model)	Unable to verify
Transmission	3 - Normal Wear & Tear
PTO	0
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation
Front Differential	0
Brake Shoe Thickness	50%
Air Brake System Leaks	N/A
Air Brake Hose Condition	0
Overall Drivetrain Condition	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear. No major issues to report





### Wheels & Tires Inspection Points

#### Wheels & Tires

#### Wheels & Tires Inspection Points

Wheels & Hub Condition	3
Wheel Seal Leaks	No
Tire Brand	Toyo
Tire Size	225/70R19.5


## Inspection Report (On-Highway Service Truck)

Front Left Tire - Ratio Remaining	90%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	90%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	90%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	90%
Rear Left Tire Photos	

## Additional Inspection Points

### Service Truck Body

### Additional Inspection Points: Tool Truck

Tool Truck Body Photos	
Bed Body	3 - Normal Wear & Tear
Toolboxes	3 - Normal Wear & Tear
Liftgate Function	0

### Additional Features

Air Compressor Condition	3 - Normal Wear & Tear
Air Compressor Functionality	Not tested

## Inspection Report (On-Highway Service Truck)



### Functional Test

#### Functionality Assessment

#### Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Overall this truck showed sings of normal wear and tear. There were no active leaks or abnormal nosies heard.

### Inspection Summary

#### Overall Assessment

Inspection Rating Criteria	<table border="1"> <thead> <tr> <th>Rating Scale</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>1 - Service Required</td> <td>Requires immediate repairs to function as expected.</td> </tr> <tr> <td>2 - Above Average Wear &amp; Tear</td> <td>Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.</td> </tr> <tr> <td>3 - Normal Wear &amp; Tear</td> <td>Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.</td> </tr> <tr> <td>4 - Very Light or Minimal Wear</td> <td>Exhibits very minimal wear. Operation is better than expected given age and usage.</td> </tr> <tr> <td>5 - Like New, Recently Replaced</td> <td>Excellent condition, free of visible wear or damage. Operation is within factory specifications.</td> </tr> </tbody> </table>	Rating Scale	Explanation	1 - Service Required	Requires immediate repairs to function as expected.	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
	Rating Scale	Explanation											
	1 - Service Required	Requires immediate repairs to function as expected.											
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.											
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.											
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.											
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.												
Exterior Rating	3 - Normal Wear & Tear												
Interior Rating	2 - Above Average Wear & Tear												
Safety Rating	3 - Normal Wear & Tear												
Quality Rating	3 - Normal Wear & Tear												
Functionality Rating	3 - Normal Wear & Tear												
Overall Rating	3 - Normal Wear & Tear												



## Inspection Report (On-Highway Service Truck)

<b>What's Great About the Machine</b>	-Vehicle mounted air compressor -Fuel storage and dispensing system -
<b>What Needs Work</b>	-Ripped weld on rear guard -Ripped driver seat -Broken display screen to radio
<b>Date/Time</b>	09-14-2023
<b>Inspector Name</b>	Javier Bocanegra