

Inspection Report (Bulldozer)

General Info

B&B Stock Number	A5058844
Year	2021
Make	Caterpillar
Model	D3
Serial Number	CAT000D3CXKY00853
Hour Meter Reading	1318.8hrs
Previous Application (e.g., earth moving, mining, demolition, etc)	used in civil construction

Dimensions

A. Length (ft and inches)	15ft
B. Width (ft and inches)	8ft 51/2in
C. Height (ft and inches)	9ft
D. Attachment Width (ft and inches)	9ft 8.5in
Operational Weight (lbs)	21,810lbs

Features and Configuration

Blade	Yes
Blade Type	PAT
Blade Specs	9ft 8.5in wide, 3ft 3.5in tall
Ripper	No
Heat	Yes
A/C	Yes
Radio	No
Backup Camera	Yes
Grade Control System	No
Telematics	No
OMM (Operator & Maintenance Manual)	No

Exterior Walkaround Photos

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos
















General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos	

General Appearance Inspection Points

General Appearance insp		I
Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	4 - Very Light or Minimal W	/ear
Body Panel Condition	No visible damage, good p	aint condition and panel fitm
Doors / Canopy Latches	4 - Very Light or Minimal W	/ear
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully inta	ct and appear structurally sc
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact ar	nd appear structurally sound
Glass	0	
Mirrors	0	
Exterior Lights	4 - Very Light or Minimal W	/ear
Exterior Lights Condition	No visible damage, lighting	system is operational



Inspection Report (Bulldozer)

Overall Exterior	4 - Very Light or Minimal Wear
Comments	The overall exterior is in very good condition. It has minimal wear and tear

Control Station Inspection Points

Control Station

Control Station	
Control Station Photos	
Control Station Photos	
Serial Number Plate	EAT BATERPILLAR CET CATERPLIAR CET C
Hour Meter/Odometer	01:17 PM
Control Station Type	Open Cab (OROPS)
Option List	Unable to Confirm
Seat	3 - Normal Wear & Tear



Inspection Report (Bulldozer)

Seat Condition	Seat(s) in good condition, no stains or tears in upholstery, Seat adjustment controls move through full range of travel, Seat belt is intact and in good condition, Seat belt secures properly
Cabin Lights	3 - Normal Wear & Tear
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	3 - Normal Wear & Tear
Heater & A/C Condition	Heater and A/C work as expected
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	3 - Normal Wear & Tear
Backup Camera Condition	Back up camera is installed and functioning as expected
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Other (see comments), Good cabin appearance, solid floors, panels, and ceiling
Comments	The ceiling of the machine does have some staining

Engine Inspection Points

Engine

Engine Compartment Photos



Engine Data Plate	EMSON CORRESTOR CAN TO THE ANALYSIS AND ANALYSIS ANALYSIS AND ANALYSIS ANALYSIS AND ANALYSIS ANALYSIS AND ANALYSIS ANALYSIS AND ANALYSIS AND ANALYSIS ANALYSIS AND ANALYSIS AND ANALYSIS ANALYS	
Engine Compartment Photos		
Engine Type (Make, Model, Cylinders, Hp)	Cat, C3.6, 104Hp	
Emissions Tier	Tier 4F	
Engine Serial Number	Unable to verify	
Engine Fuel Type	Diesel	
Blow-by (Visual Observation Check)	N/A	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Exhaust Color	Clear	
Battery	3 - Normal Wear & Tear	
Battery Condition	Clean & dry appearance, tight connections	
Radiator	3 - Normal Wear & Tear	
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks	
Belts	3 - Normal Wear & Tear	
Belt Condition	Belts appear in good condition & alignment with proper tension	
Hoses	3 - Normal Wear & Tear	
Hose Condition	Firm, pliant hoses with no signs of wear or leaks	
Water Pump	3 - Normal Wear & Tear	
Water Pump Condition	No unusual pump noises heard	



Inspection Report (Bulldozer)

Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Oil Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Clean & dry
Overall Engine Comments	The engine is in good working order.

Drivetrain Inspection Points

Drivetain

Drivetrain Inspection Points

Drivetrain Photos	
Hydrostatic Transmission?	Yes
Speeds	Unable to Verify
Drive Type	N/A (Track Undercarriage)
Transmission Components	3 - Normal Wear & Tear
Transmission Condition	Good forward and reverse function, No unusual noises or vibrations
Drive Motors	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Parking Brake Function	Good brake function
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	The drivetrain is in good working order

Undercarriage Inspection Points



Track Undercarriage

Basic Information

High Drive Configuration	No
Sealed and Lubricated Track Undercarriage (SALT)?	Yes
Oil Filled?	Yes
Grease Filled?	Yes
Low Ground Pressure (LGP)?	Yes
Track Shoe Width (inches)	2ft 2in
Length of Track on Ground (ft and inches)	8ft 11in
Number of Carrier Rollers (per side)	1
Number of Rollers (per side)	7
Number of Shoes (per side)	36

Undercarriage Photos

Official flago i flotos				
Undercarriage Photos			A un	
	30000			
		Source of the second	No Free States	

Undercarriage Inspection Points

Sprocket Teeth	3 - Normal Wear & Tear
Track Bushings	3 - Normal Wear & Tear
Track Frames	3 - Normal Wear & Tear
Pivot Shafts	3 - Normal Wear & Tear
Equalizer Bar & Joints	3 - Normal Wear & Tear
Front Idler	3 - Normal Wear & Tear
Track Tensioner	3 - Normal Wear & Tear
Track links	3 - Normal Wear & Tear
Bottom Rollers	3 - Normal Wear & Tear
Carrier Rollers	3 - Normal Wear & Tear
Overall Undercarriage	3 - Normal Wear & Tear



Inspection Report (Bulldozer)

Overall Percent Estimate	70%
Overall Undercarriage Comments	The undercarriage is in good working order, but the tracks are a little loose.

Chassis Inspection Points

Onassis inspection i onto	
Chassis Photos	
Push Arm / C-Frame Condition	3 - Normal Wear & Tear
Push Arm Pivot / C-Frame Trunnions Condition	3 - Normal Wear & Tear
Tilt Linkage Pin & Bushings	3 - Normal Wear & Tear
Angle Linkage Pin & Bushings	3 - Normal Wear & Tear
Blade Trunnions / Bushings	3 - Normal Wear & Tear
Frame Condition	3 - Normal Wear & Tear
Belly Pans	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	The chassis is in good condition

Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos			
Wet or Damp Hydraulic Lines / Fittings	No		
Hydraulic Lines/Fittings	3 - Normal Wear & Tear		
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition		
Hydraulic Pump(s)	3 - Normal Wear & Tear		
Unusual Noises	No		
Hydraulic Pump Notes	No unusual noises heard during operation		

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos			
	-60		



Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear
Comments	The overall hydraulic system is in good working order

Attachment Inspection Points

Attachments

Additional Attachments

Attachment Condition 0

Functional Test

Functionality Assessment

Functionality Assessment

diotoriality 7 00000 mont		
Engine	3 - Normal Wear & Tear	
Transmission/Drivetrain	3 - Normal Wear & Tear	
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear	
Brakes	3 - Normal Wear & Tear	
Hydraulic System	3 - Normal Wear & Tear	
Electric Operating System	0	
Controls	3 - Normal Wear & Tear	
Safety Systems	3 - Normal Wear & Tear	
Core Functions	3 - Normal Wear & Tear	
Attachments	3 - Normal Wear & Tear	
Overall Functional Test Comments	The machine is fully functional	

Inspection Summary

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
3	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.



Inspection Report (Bulldozer)

Exterior Rating	4 - Very Light or Minimal Wear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	4 - Very Light or Minimal Wear
Quality Rating	4 - Very Light or Minimal Wear
Functionality Rating	4 - Very Light or Minimal Wear
Overall Rating	4 - Very Light or Minimal Wear
Summary Video	Click to Download
What's Great About the Machine	This machine has been well taken care of.
What Needs Work	The tracks are a little loose
Any Additional Info from the Seller?	This machine was used in civil construction
Date/Time	01-18-2024
Inspector Name	Steven Mesa