

Inspection Report (Skid Steer/Track Loader)

General Info

A1940132
2017
John Deere
333G
1T0333GMKHF311823
1498.7
Earth moving
Pine State of Jehovah's Witnesses Papé Machinery Construction & Forestry Papé Machinery Construction & Forestry Lat: 37.517942999999995 Long: -121.94246700000001

Features and Configuration

Features and Configuration	
Travel System	Track Undercarriage
Bucket	Yes
Bucket Specs	84"
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
High Flow	Yes
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No



Inspection Report (Skid Steer/Track Loader)

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	
Operating Video	Click to Download

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos	
	3K59 DEERE 3G UL3K59 DEERE
	DEERE UL3K59 333G RE UL3K59 333G DEER

General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	2 - Above Average Wear &	Tear
Body Panel Condition	Some panel misalignment	observed, Visible chipped pa




Inspection Report (Skid Steer/Track Loader)

Doors / Canopy Latches	2 - Above Average Wear & Tear
Doors / Canopy Latches Condition	Intermittent sticking observed on one or more latches/doors
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational
Overall Exterior	3 - Normal Wear & Tear
Comments	Normal wear and tear Rear impact damaged to rear left panel and rear grille and latching mechanism

Control Station Inspection Points


Control Station

Control Station Photos





Inspection Report (Skid Steer/Track Loader)





Hour Meter/Odometer



Control Station Type	Enclosed Cab (EROPS)
Option List	Unable to Confirm
Seat	2 - Above Average Wear & Tear
Seat Condition	Seat(s) have minor surface staining or small tears, Seat belt secures properly
Cabin Lights	3 - Normal Wear & Tear
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
Safety Lock Out / Stop	3 - Normal Wear & Tear



Inspection Report (Skid Steer/Track Loader)

Sefety Leek Out / Step Condition	Cafaty look out daying in present in good condition, and functional	
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional	
Controls & Switches	3 - Normal Wear & Tear	
Controls & Switches Condition	All switches are installed and functional	
Hour Meter Activity	3 - Normal Wear & Tear	
Hour Meter Condition	Hour meter is functional and in good condition	
Other Gauge Activity	3 - Normal Wear & Tear	
Other Gauge Condition	All cockpit gauges are functional and in good condition	
Heater & A/C	3 - Normal Wear & Tear	
Heater & A/C Condition	Heater and A/C work as expected	
Travel Alarm	3 - Normal Wear & Tear	
Travel Alarm Condition	Travel alarm is installed and functioning as expected	
Horn	3 - Normal Wear & Tear	
Horn Condition	Horn is installed and functioning as expected	
Backup Camera	0	
Control Station Overall Rating	3 - Normal Wear & Tear	
Control Station Overall Condition	Good cabin appearance, solid floors, panels, and ceiling	

Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate



Engine Compartment Photos















Inspection Report (Skid Steer/Track Loader)

Engine Type (Make, Model, Cylinders, Hp)	Unable to verify	
Emissions Tier	Tier 4F	
Engine Serial Number	Unable to verify	
Engine Fuel Type	Diesel	
Blow-by (Visual Observation Check)	No	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Exhaust Color	Clear	
Battery	3 - Normal Wear & Tear	
Battery Condition	Dusty & dirty appearance	
Radiator	3 - Normal Wear & Tear	
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks	
Belts	3 - Normal Wear & Tear	
Belt Condition	Belts appear in good condition & alignment with proper tension	
Hoses	3 - Normal Wear & Tear	
Hose Condition	Firm, pliant hoses with no signs of wear or leaks	
Water Pump	3 - Normal Wear & Tear	
Water Pump Condition	No unusual pump noises heard	
Cooling System Leaks	No	
Coolant Appearance	3 - Normal Wear & Tear	
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination	
Oil Leaks	No	
Oil Appearance	3 - Normal Wear & Tear	



Inspection Report (Skid Steer/Track Loader)

Oil Appearance Notes	Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is dirty, fluid is clear and appears free of contaminants
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	Normal wear and tear Rear fan contacting rear grille

Drivetrain Inspection Points

Drivetrain


Drivetrain Inspection Points

Drivetrain Photos	
Hydrostatic Transmission?	Yes
Speeds	Variable Speed
Drive Type	N/A (Track Undercarriage)
Transmission Components	3 - Normal Wear & Tear
Transmission Condition	Good forward and reverse function
Drive Motors	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report

Travel System Inspection Points

Rubber Track Undercarriage

Undercarriage Photos














Inspection Report (Skid Steer/Track Loader)



Inspection Points

inspection Foints	
Track Width (inches)	18"
Track Length (inches)	80"
Roller Frames	3 - Normal Wear & Tear
Track Belt	2 - Above Average Wear & Tear
Comments	Slices to track
Rubber Belt Drive Lugs	2 - Above Average Wear & Tear
Comments	Worn
Track Tensioners	3 - Normal Wear & Tear
Front Idlers	3 - Normal Wear & Tear
Rear Idlers	3 - Normal Wear & Tear
Sprockets	3 - Normal Wear & Tear
Overall Undercarriage Rating	3 - Normal Wear & Tear
Left Track Belt - Percent Remaining Estimate	30%
Right Track Belt - Percent Remaining Estimate	30%
Overall Comments	Normal wear and tear Both tracks worn

Chassis Photos



Inspection Report (Skid Steer/Track Loader)

Chassis Photos	
	333c ilus per
	DERF. U.S. 333G

Chassis Inspection Points

Chacolo hiopocach i chiac	
Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Lift Arms	2 - Above Average Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Quick Coupler	3 - Normal Wear & Tear
Quick Coupler to Arms Pins	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear Left lift arm rear impact

Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

riyaraano Oyotom mo	
Hydraulic System Photos	



Inspection Report (Skid Steer/Track Loader)

Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Comments	Normal wear and tear
Hydraulic System Overall	3 - Normal Wear & Tear

Bucket Inspection Points

Bucket Photos			
Bucket	3 - Normal Wear & Tear		
Bucket Edge / Deflectors	2 - Above Average Wear & Tear		
Comments	Left corner of blade missing		



Inspection Report (Skid Steer/Track Loader)

Functional Test

Functionality Assessment

Functionality Assessment

Engine	2 - Above Average Wear & Tear
Comments	Damage to rear fan
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Normal wear and tear no major issues to report

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
moposition realing entities	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	2 - Above Average Wear 8	Tear
Interior Rating	3 - Normal Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
Summary Video	Click to Download	
What's Great About the Machine	Starts right up with no abno	ormal noise
What Needs Work	Rear impact to grille, fan a	nd left lifting arm



Inspection Report (Skid Steer/Track Loader)

Date/Time	02-01-2024
Inspector Name	Javier Bocanegra