

## Inspection Report (Forklift)

### General Info

B&B Stock Number	A3176348
Year	2014
Make	Hyundai
Model	40D-9F
Serial Number	HHKHFFV34LK0000065
Hour Meter Reading	11116.2
Previous Application (e.g., earth moving, mining, demolition, etc)	Warehouse

### Features and Configuration

Forks / Work Tool Specs	4 ft forks
Side Shift	Yes
Tilt Carriage	Yes
Tilt Mast	No
Frame Leveling	No
Additional Attachment(s)?	No
Auxiliary Hydraulics	No
Engine Type	Internal Combustion
Wheel Type	Solid
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	Yes
OMM (Operator & Maintenance Manual)	No
Telematics	No
Other Configuration Details / Notes	Hydraulic fork spread

### Exterior 360 Walkaround

### 360 Walkaround & Operating Video

### Walkaround Photos & Operating Video

Exterior Walkaround Photos	
----------------------------	--























## Inspection Report (Forklift)

	  	
Operating Video	<a href="#">Click to Download</a>	

### General Appearance Inspection Points

#### General Appearance

#### General Appearance Photos

Close-up Exterior Photos	    
	    
	    
	    
	 

### General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	
Body Panels	2 - Above Average Wear & Tear	
Body Panel Condition	Visible chipped paint or dents	
Doors / Canopy Latches	2 - Above Average Wear & Tear	
Doors / Canopy Latches Condition	Loose or missing latches, hinges or handles, Intermittent sticking observed on one or more latches/doors, Bent or damaged frame/components	































## Inspection Report (Forklift)

Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	2 - Above Average Wear & Tear
Glass Condition	Minor chips or cracks observed
Comments	Top right of windshield
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	4 - Very Light or Minimal Wear
Exterior Lights Condition	No visible damage, lighting system is operational
Overall Exterior	3 - Normal Wear & Tear
Comments	Damaged left driver door, cracked windshield and exterior paint chipping at rear of machine

## Control Station Inspection Points




### Control Station

### Control Station Photos

Control Station Photos					
					
					
					
					
					



## Inspection Report (Forklift)

	
<b>Serial Number Plate</b>	
<b>Hour Meter/Odometer</b>	
<b>Control Station Type</b>	Enclosed Cab (EROPS)
<b>Option List</b>	Unable to Confirm
<b>Seat</b>	3 - Normal Wear & Tear
<b>Seat Condition</b>	Seat(s) have minor surface staining or small tears, Seat belt secures properly
<b>Cabin Lights</b>	3 - Normal Wear & Tear
<b>Cabin Lights Condition</b>	Cabin lights are installed with all light covers in place, bulbs are installed and working properly



## Inspection Report (Forklift)







Safety Lock Out / Stop	0
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	2 - Above Average Wear & Tear
Heater & A/C Condition	Fan vents are damaged, Heater and A/C work as expected
Travel Alarm	0
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	1 - Service Required
Backup Camera Condition	Back up camera is installed but inoperative or has reduced functionality
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Good cabin appearance, solid floors, panels, and ceiling

## Engine Inspection Points

### Engine

### Engine Compartment Photos

### Inspection Report (Forklift)

<p>Engine Data Plate</p>	 <p> <b>Kubota</b> KUBOTA CORPORATION        2018/09 7495-0-2        EMISSION CONTROL INFORMATION        THIS ENGINE MEETS 2018 Tier 4 EMISSION REGULATIONS FOR U.S. EPA AND CALIFORNIA HIGHWAY OFF ENGINES.  <b>Kubota</b> KUBOTA Corporation        MODEL : V3800-DR-T1-EF03 ENGINE DISP. : 3.8L        FAMILY : JKBXL03.8CMO CATEGORY: 37-55kW        POWER : 54.6kW/2200 rpm. IN: 0.25mm EX: 0.25mm        VALVE CLEARANCE (COLD) : IN: 0.25mm EX: 0.25mm        ECS: EM, DF, L, TC, EGR, CAC, ECM, DOC 2018/09 34101-1        ULTRA-LOW SULFUR DIESEL FUEL ONLY DEL. ASSY     </p>				
<p>Engine Compartment Photos</p>					
					
					
					
					

## Inspection Report (Forklift)

Engine Type (Make, Model, Cylinders, Hp)	Kubota, V3800
Emissions Tier	Tier 4F
Engine Serial Number	Unable to verify
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	Yes
Engine Smoke Notes	Engine smoke observed upon start up
Engine Exhaust Color	White
Battery	4 - Very Light or Minimal Wear
Battery Condition	Like new, recently replaced
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Oil Appearance Notes	Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	No




## Inspection Report (Forklift)

Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Normal wear and tear no major issues to report

## Drivetrain Inspection Points


### Drivetrain

### Drivetrain Inspection Points




Drivetrain Photos	
Hydrostatic Transmission?	No
Transmission Info (Make/Model/Speeds)	Unable to verify
Drive Type	2WD
Transmission Components	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report
Front Axle	3 - Normal Wear & Tear
Rear Axle	3 - Normal Wear & Tear

## Wheels & Tires


















### Wheels & Tires Inspection Points

Wheels & Hubs	3 - Normal Wear & Tear
Wheel Seal Leaks	No
Tire Brand	Mitchell industrial tires
Tire Size	300-15 8.00
Front Left Tire - Ratio Remaining	70%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	70%

## Inspection Report (Forklift)

Front Right Tire Photos	 
Rear Right Tire - Ratio Remaining	70%
Rear Right Tire Photos	 
Rear Left Tire - Ratio Remaining	70%
Rear Left Tire Photos	 

## Chassis Inspection Points


Chassis Photos	    
	    
	    
	 
Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Carriage Appearance	2 - Above Average Wear & Tear
Comments	Slight bend to backrest
Mast Condition	3 - Normal Wear & Tear
Chain / Tensioners	3 - Normal Wear & Tear
Rollers & Guides	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear no major issues to report

## Hydraulics Overall Inspection Points


### Hydraulics Overall

## Inspection Report (Forklift)

### Hydraulic System Inspection Points

Hydraulic System Photos	
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Dried seepages observed
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

### Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear
Comments	Normal wear and tear with signs of dried seepage

### Functional Test

#### Functionality Assessment

#### Functionality Assessment

Engine	3 - Normal Wear & Tear
--------	------------------------



## Inspection Report (Forklift)

Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Normal wear and tear no major issues to report

## Overall Assessment

### Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	2 - Above Average Wear & Tear	
Interior Rating	3 - Normal Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
What's Great About the Machine	The great thing about this machine is the engine, It starts right over with no abnormal sounds.	
What Needs Work	The things that need work are the left door frame and lower window. As well as the front windshield crack and reverse camera system.	
Date/Time	02-13-2024	
Inspector Name	Javier Bocanegra	