

## Inspection Report (Forklift)

### General Info

B&B Stock Number	A5261562
Year	2014
Make	Hyundai
Model	110D-9
Serial Number	HHKHFT21OG0000013
Hour Meter Reading	14508.7
Previous Application (e.g., earth moving, mining, demolition, etc)	Warehouse

### Features and Configuration


Max Lift Height	Unable to verify
Max Lift Capacity	Unable to verify
Forks / Work Tool Specs	10'
Side Shift	Yes
Tilt Carriage	No
Tilt Mast	Yes
Frame Leveling	No
Additional Attachment(s)?	No
Auxiliary Hydraulics	No
Engine Type	Internal Combustion
Wheel Type	Solid
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	Yes
OMM (Operator & Maintenance Manual)	Yes
Telematics	No

### OMM Specifications

#### OMM Specifications

Detail Specifications	Take photos of the detailed spec pages included in the operator's manual
-----------------------	--

## Inspection Report (Forklift)



## Exterior 360 Walkaround

### 360 Walkaround & Operating Video


### Walkaround Photos & Operating Video



## General Appearance Inspection Points

### General Appearance

### General Appearance Photos



## Inspection Report (Forklift)



### General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	2 - Above Average Wear & Tear	
Body Panel Condition	Visible chipped paint or dents, Areas of surface rust observed	
Doors / Canopy Latches	2 - Above Average Wear & Tear	
Doors / Canopy Latches Condition	Intermittent sticking observed on one or more latches/doors	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	3 - Normal Wear & Tear	
Glass Condition	Glass intact, no visible damage	
Mirrors	3 - Normal Wear & Tear	
Mirror Condition	Mirrors present and intact, no visible damage	
Exterior Lights	3 - Normal Wear & Tear	
Exterior Lights Condition	No visible damage, lighting system is operational	
Overall Exterior	3 - Normal Wear & Tear	
Comments	Bent left light guard, Chipped paint throughout machine, Areas of surface rust observed, bent right mast light	


















































### Control Station Inspection Points

#### Control Station

#### Control Station Photos





### Inspection Report (Forklift)

Control Station Photos					
					
					
					
					
				Unknown check engine lights error	
					
					
					
					



## Inspection Report (Forklift)

Serial Number Plate	 <p>A close-up photograph of a metal serial number plate for a Hyundai forklift. The plate is mounted on a dark surface and contains the following information:       <ul style="list-style-type: none"> <li>Brand: HYUNDAI</li> <li>Model: H100-10</li> <li>Type: DIESEL</li> <li>Truck Weight: 38530 lb</li> <li>Product Certification Number: 9999912370000001</li> <li>Dimensions: A (24 in), B (197 in), C (24 in)</li> <li>Load Capacity: 25000 lb</li> <li>Part Number: 92F1-00432</li> </ul> </p>
Hour Meter/Odometer	 <p>A photograph of the forklift's dashboard. The digital display shows:       <ul style="list-style-type: none"> <li>Engine RPM: 747</li> <li>Time: 02:14</li> <li>Weight: 0 lb</li> <li>Hour Meter: 14509.5 Hr</li> <li>Odometer: 23868 mile</li> <li>Temperature: 48.2 F</li> <li>Pressure: 82.0</li> <li>Gear indicator: P (Park)</li> <li>Other indicators: H, la, and various warning lights.</li> </ul> </p>
Control Station Type	Enclosed Cab (EROPS)
Option List	Pilot Controls
Seat	2 - Above Average Wear & Tear
Seat Condition	Seat(s) has major surface staining or tears, Seat belt secures properly
Cabin Lights	3 - Normal Wear & Tear
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
Safety Lock Out / Stop	0
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	3 - Normal Wear & Tear
Heater & A/C Condition	Heater and A/C work as expected
Travel Alarm	0



## Inspection Report (Forklift)

Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	3 - Normal Wear & Tear
Backup Camera Condition	Back up camera is installed and functioning as expected
Control Station Overall Rating	3 - Normal Wear & Tear
Control Station Overall Condition	Good cabin appearance, solid floors, panels, and ceiling

## Engine Inspection Points

### Engine

### Engine Compartment Photos

Engine Data Plate					
Engine Compartment Photos					
Engine Type (Make, Model, Cylinders, Hp)	Cummins, QSB6.7 173				
Emissions Tier	Tier 4F				
Engine Serial Number	22194335				
Engine Fuel Type	Diesel				
Blow-by (Visual Observation Check)	No				
Unusual Noises (Upon Start-up, Idle, Shutdown)	No				
Engine Smoke (Upon Start-up, Idle, Shutdown)	Yes				

## Inspection Report (Forklift)

Engine Smoke Notes	Engine smoke observed upon start up
Engine Exhaust Color	White
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Appearance	2 - Above Average Wear & Tear
Coolant Appearance Notes	Other (see comments)
Comments	Low coolant
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Normal wear and tear low coolant observed


### Drivetrain Inspection Points

#### Drivetrain

### Drivetrain Inspection Points





### Inspection Report (Forklift)

Drivetrain Photos	
Hydrostatic Transmission?	No
Transmission Info (Make/Model/Speeds)	Unable to verify
Drive Type	2WD
Transmission Components	3 - Normal Wear & Tear
Transmission Condition	Good forward and reverse function, No unusual noises or vibrations
Parking Brake	3 - Normal Wear & Tear
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report
Front Axle	3 - Normal Wear & Tear
Rear Axle	0

### Wheels & Tires











#### Wheels & Tires Inspection Points

Wheel Seal Leaks	Yes
Comments	Front right wheel hub
Wheel Seal Leak Photos	
Tire Brand	GS - solid
Tire Size	10.00-20
Front Left Tire - Ratio Remaining	50%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	50%

## Inspection Report (Forklift)

Front Right Tire Photos	 
Rear Right Tire - Ratio Remaining	50%
Rear Right Tire Photos	 
Rear Left Tire - Ratio Remaining	50%
Rear Left Tire Photos	 

## Chassis Inspection Points

Chassis Photos	    
	    
Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Carriage Appearance	3 - Normal Wear & Tear
Mast Condition	3 - Normal Wear & Tear
Chain / Tensioners	3 - Normal Wear & Tear
Rollers & Guides	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear No major issues to report





## Hydraulics Overall Inspection Points

### Hydraulics Overall

### Hydraulic System Inspection Points

Hydraulic System Photos	    
	    

## Inspection Report (Forklift)

	   
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

## Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	    
	 
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear

## Functional Test

### Functionality Assessment

### Functionality Assessment

Engine	2 - Above Average Wear & Tear
Comments	Check engine light on
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	4 - Very Light or Minimal Wear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear



## Inspection Report (Forklift)

<b>Overall Functional Test Comments</b>	Normal wear and tear Unknown check engine light error
---	--

## Overall Assessment

### Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
<b>Exterior Rating</b>	2 - Above Average Wear & Tear	
<b>Interior Rating</b>	3 - Normal Wear & Tear	
<b>Safety Rating</b>	2 - Above Average Wear & Tear	
<b>Quality Rating</b>	3 - Normal Wear & Tear	
<b>Functionality Rating</b>	3 - Normal Wear & Tear	
<b>Overall Rating</b>	3 - Normal Wear & Tear	
<b>Summary Video</b>	<a href="#">Click to Download</a>	
<b>What's Great About the Machine</b>	The great thing about this machine is its well maintained cab interior.	
<b>What Needs Work</b>	The things that need work on this machine are the bent front left light guard, The chipped paint throughout exterior of machine, and the check engine light	
<b>Date/Time</b>	02-14-2024	
<b>Inspector Name</b>	Javier Bocanegra	