

Inspection Report (Forklift)

General Info

B&B Stock Number	A6215243
Year	2014
Make	Hyundai
Model	70D-9
Serial Number	HHKHFA03HG0000192
Hour Meter Reading	13857.3
Previous Application (e.g., earth moving, mining, demolition, etc)	Warehouse

Features and Configuration

Side Shift	Yes
Tilt Carriage	No
Tilt Mast	Yes
Frame Leveling	No
Additional Attachment(s)?	No
Auxiliary Hydraulics	No
Engine Type	Internal Combustion
Wheel Type	Solid
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	Yes
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Other Configuration Details / Notes	Hydraulic fork spreader

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	  































Inspection Report (Forklift)

Operating Video	Click to Download
-----------------	-----------------------------------

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos					
					
					
					
					
					

General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	
3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	
4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.	
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents	
Doors / Canopy Latches	1 - Service Required	
Doors / Canopy Latches Condition	Other (see comments)	
Comments	Latches to engine compartment lost latching	































Inspection Report (Forklift)

Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational
Overall Exterior	3 - Normal Wear & Tear
Comments	Door latches to engine compartment not latching, paint chips at rear of machine, right side door, lower dent, left side door has dents




Control Station Inspection Points

Control Station

Control Station Photos

Control Station Photos					
					
					
					
					
					

Inspection Report (Forklift)

	
Serial Number Plate	
Hour Meter/Odometer	
Control Station Type	Enclosed Cab (EROPS)
Option List	Unable to Confirm
Seat	2 - Above Average Wear & Tear
Seat Condition	Seat(s) has major surface staining or tears, Seat belt shows limited functionality or does not secure properly
Comments	Major seat damage, seatbelt not operational
Cabin Lights	3 - Normal Wear & Tear
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly

Inspection Report (Forklift)

Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	1 - Service Required
Heater & A/C Condition	Only heat functionality works
Travel Alarm	0
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	3 - Normal Wear & Tear
Backup Camera Condition	Back up camera is installed and functioning as expected
Control Station Overall Rating	2 - Above Average Wear & Tear
Control Station Overall Condition	Other (see comments)
Comments	Broken interior paneling, damage seat, Seatbelt Not operational,






Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate					
Engine Compartment Photos					

Inspection Report (Forklift)

	    
Engine Type (Make, Model, Cylinders, Hp)	Cummins, QSF 3.8
Emissions Tier	Tier 4F
Engine Serial Number	89291113
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	Yes
Engine Smoke Notes	Engine smoke observed upon start up
Engine Exhaust Color	White
Battery	3 - Normal Wear & Tear
Battery Condition	Inaccessible, unable to determine condition
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Oil Appearance Notes	Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear



Inspection Report (Forklift)

DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	Normal wear and tear No major issues to report

Drivetrain Inspection Points

Drivetrain





Drivetrain Inspection Points

Drivetrain Photos	
	
Hydrostatic Transmission?	No
Transmission Info (Make/Model/Speeds)	Unable to verify
Drive Type	2WD
Transmission Components	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations, Good forward and reverse function
Parking Brake	3 - Normal Wear & Tear
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report
Front Axle	3 - Normal Wear & Tear
Rear Axle	0


Wheels & Tires

Wheels & Tires Inspection Points

Inspection Report (Forklift)

Wheels & Hubs	3 - Normal Wear & Tear			
Wheel Seal Leaks	No			
Tire Brand	GS - Solid			
Tire Size	8.25-15			
Front Left Tire - Ratio Remaining	50%			
Front Left Tire Photos				
Front Right Tire - Ratio Remaining	50%			
Front Right Tire Photos				
Rear Right Tire - Ratio Remaining	50%			
Rear Right Tire Photos				
Rear Left Tire - Ratio Remaining	50%			
Rear Left Tire Photos				

Chassis Inspection Points

Chassis Photos					
Frame	3 - Normal Wear & Tear				
Stance	3 - Normal Wear & Tear				
Carriage Appearance	3 - Normal Wear & Tear				
Mast Condition	3 - Normal Wear & Tear				
Chain / Tensioners	3 - Normal Wear & Tear				
Rollers & Guides	3 - Normal Wear & Tear				


Inspection Report (Forklift)

Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Normal wear and tear No major issues to report


Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System Inspection Points

Hydraulic System Photos	
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No
Hydraulic Pump Notes	No unusual noises heard during operation

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear

Functional Test

Inspection Report (Forklift)

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	2 - Above Average Wear & Tear
Comments	Seatbelt not operational
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Normal wear and tear Seatbelt not operational

Overall Assessment

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	2 - Above Average Wear & Tear	
Interior Rating	2 - Above Average Wear & Tear	
Safety Rating	2 - Above Average Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
What's Great About the Machine	The thing that is great about this machine is its engine, it starts right up with no abnormal noises	
What Needs Work	The things that need work on this machine are the paint chips throughout the exterior of the machine, Damage rear tail lights, Damaged operator seat and A non-operable seatbelt.	
Date/Time	02-15-2024	



Inspection Report (Forklift)

Inspector Name	Javier Bocanegra
----------------	------------------