



Direct To Auction Form

General Info

B&B Stock Number	A6421268
Category	Other
Year	N/A
Make	Barber
Model	TC30
Fleet ID	E95-10
Serial Number / VIN	N/A
Serial Number Plate / VIN Sticker	
Hour Meter Reading	N/A
Hour Meter Photo	

Dimensions

Overall Length (ft and inches)	30'
Overall Width (ft and inches)	7'6"
Overall Height (ft and inches)	11'
Wheel Base (ft and inches) - ON HIGHWAY MACHINES	
Operational Weight (lbs)	N/A

Direct To Auction Form

Off Highway Equipment

Travel System	
Comments	
Drive Type	
Comments	
Fuel Type	
Control Station Type	
Operator Controls	
A/C	
Heat	
Radio	
Reverse Camera	

All On-Highway Trucks

Is this vehicle titled?	
Cab Type	
Drive Type	
Comments	
Transmission	
Fuel Type	
PTO	
Engine Brake	
Air Brakes	
A/C	
Heat	
Radio	
Rear Camera	
Cruise Control	
Over Drive	

Backhoe

Loader Bucket	
Loader Bucket Size (yd3 / inches)	
Digging Bucket	
Bucket Size (yd3 / inches)	
Extend-a-hoe	

Direct To Auction Form

Outriggers/Stabilizers	
Auxiliary Hydraulics	
Quick Coupler	

Bulldozer

Blade	
Blade Type	
Ripper	
GPS/Grade Control System	
System Make/Model	

Compact Track Loader

High Flow	
Loader Bucket	
Bucket Size (yd3 / inches)	
Auxiliary Hydraulics	
Quick Coupler	

Compactor

Blade	
Vibratory System	
Water Spray System	

Excavator

Blade	
Bucket	
Bucket Size (yd3 / inches)	
Auxiliary Hydraulics	
Thumb	
Thumb Type	
Extended Stick Option	
Stick Length (ft. in.)	
Quick Coupler	

Forklift

Forks	
Length x Width (inches)	
Side Shift	

Direct To Auction Form

Lifts

Jib	
Outriggers/Stabilizers	
Hydraulic Leveling	
Electrical Power to Platform	

Motor Grader

Ripper	
Blade	
Push Block	
Front/Mid Scarifier	
GPS/Grade Control System	
System Make/Model	

Scraper

Engine Configuration	
Elevating Bowl	
GPS/Grade Control System	
System Make/Model	

Skid Steer

Loader Bucket	
Bucket Size (yd3 / inches)	
High Flow	
Auxiliary Hydraulics	
Quick Coupler	

Skip Loader

Loader Bucket	
Bucket Size (yd3 / inches)	
Box Blade	
Auxiliary Hydraulics	
Quick Coupler	

Telehandler

Forks	
Length x Width (inches)	
Work Basket	



Direct To Auction Form

Outriggers/Stabilizers	
Hydraulic Leveling	
Side Shift	
Quick Coupler	

Wheel Loader

Loader Bucket	
Bucket Size (yd3 / inches)	
Forks	
Length x Width (inches)	
Auxiliary Hydraulics	
Quick Coupler	

Generator

Towable?	
Trailer VIN	
Trailer GVWR (Gross Vehicle Weight Rating)	
Is this trailer titled?	
Trailer Brakes	
kW Output / Power Rating (kW)	

Bucket Truck

Lift Make/Model	
Lift SN Plate	
Date of Last Periodic / Annual Inspection	
Work Basket	
Outriggers / Stabilizers	

Service/Specialty Truck

Auxiliary Engine	
Auxiliary Fuel Tank	
Lube System	
Air Compressor	
Make/ Model	
Welder	
Make/ Model	
Crane	

Direct To Auction Form

Make/ Model	
Hitch	
Hitch Type	
Other Hitch Type	

Tank Trucks

Tank Size (Gallons)	
Water Spray System	

Trailer

Trailer GVWR (Gross Vehicle Weight Rating)	
Is this trailer titled?	
Trailer Brakes	
Hitch	
Other Hitch Type	

Other Features & Attachments

OMM (Operator & Maintenance Manual)	No
Other Features & Attachments	

360 Walkaround Photos

Exterior Walkaround Photos					
					

General Appearance







Close-Up Exterior Photos			
Exterior Comments	The machines exterior has some wear and tear that's quite normal when considering it age.		

Control Station

Control Station				
Control Station Overall Comments	Operator station has normal wear. Not all operator gauges were functional.			

Direct To Auction Form

Engine

Engine Data Plate					
Engine Compartment					
					
Engine Type (Make, Model, Cylinders, Hp)	N/A				
Engine Overall Comments	Once the engine fired up (Hard Starting, possibly due to fuel injection pump issue) it sounded okay.				






Drivetrain Components

Drivetrain Photos					
					
					

Direct To Auction Form

Drivetrain Comments	Unable to verify drivetrains functionality.
---------------------	---

Hydraulics

Hydraulic Pump/Fittings/Hoses/Cylinders/Pins	    
Hydraulic System Comments	Unable to test the hydraulics at the time of the inspection.




Chassis

Chassis Photos	    
Comments	The main frame was in descent shape with no obvious signs of major structural issues seen. Some cracks were observed at the front wheel.

Underbody Inspection Points

Underbody Photos	  
Underbody Comments	Underbody shows signs of leaks. No major obvious issues besides the possible leaks were observed.

Attachments

Attachment Photos	  
Attachment Comments	The attachment had a descent appearance. The wheels functionality

Functionality Assessment

Is this machine operable?	No
Video - Operational or 360	Click to Download
Comments	The machine needed assistance to fire up and stay running. Because of the engine being unable to stay running, the majority of the machine was not functional at the time of he inspection.