



Inspection Report (On-Highway Truck Cab + Chassis)

General Info

B&B Stock Number	A6967198
Year	2008
Make	Volvo
Model	unknown
Serial Number	4V4MC9GF98N488956
Serial Plate	
Odometer Reading	479473.8
Odometer	
Current Inspection / State Cert / DOT	unknown
Previous Application (e.g., earth moving, mining, demolition, etc)	This truck was used in a food bank

Dimensions

Length (ft and inches)	22ft 4in
Width (ft and inches)	8ft 2in
Height (ft and inches)	12ft 9in
Wheelbase (ft and inches)	13ft 1.5in
GVWR (lbs)	50,000lbs

Inspection Report (On-Highway Truck Cab + Chassis)

Features and Configuration

Drive Type	4X2
Overdrive	No
Heat	No
A/C	Yes
Radio	No
Backup Camera	No
Cruise Control	Yes
PTO	No
Engine Brake	N/A
Differential Lock	Yes
Auxiliary Engine	No
Liftgate	No
Telematics	No
OMM (Operator & Maintenance Manual)	No

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	  
Operating Video	Click to Download

















General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos	    
	    

Inspection Report (On-Highway Truck Cab + Chassis)

					
					
					
			A dent is present on the passenger side door	Cracks were seen around the bolts on the driver side.	The fender is cracked around the bolts
					
	This is a crack on the driver side fender near the bolts.				

General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Visible chipped paint or dents, Other (see comments)	
Comments	There is a dent on the passenger side door	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	4 - Very Light or Minimal Wear	

























Inspection Report (On-Highway Truck Cab + Chassis)

Glass Condition	Glass intact, no visible damage
Mirrors	4 - Very Light or Minimal Wear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational
Overall Exterior	3 - Normal Wear & Tear
Comments	Damage to the right-hand side door was seen. The door still works, and the latches shut.

Cab Inspection Points

On Highway - Cab

Cab Interior Photos

Cab Interior Photos					
				The driver side cabin light is missing	The driver side seat has some small tears on it.
					
					
	When you push or pull on the parking break, the dashboard surrounding the area is loose. The parking break itself work and is fully functional.				
					
					
Odometer Activity	3 - Normal Wear & Tear				

Inspection Report (On-Highway Truck Cab + Chassis)

Odometer	Odometer is working and in good condition
Controls/Switches/Gauges	3 - Normal Wear & Tear
Controls/Switches/Gauges	All switches/gauges are in good condition and functioning
Brake System Type	Air Brakes
Air Brakes Build Correct Pressure	Yes
Clutch	0
Horn	3 - Normal Wear & Tear
Horn Function	Horn is functioning as expected
Reverse Alarm / Backup Camera	0
Heater & A/C	3 - Normal Wear & Tear
Heat & A/C	A/C Blows cool - noticeably cooler than air temp
Interior Lights	2 - Above Average Wear & Tear
Interior Lights	One or more lights are inoperable/damaged
Seats/Seat Belts	2 - Above Average Wear & Tear
Seats/Seat Belt	Seat belt secures properly, Seat(s) have minor surface staining or small tears, Seat belt has nicks, cuts, holes, or fraying
Cab Interior Overall	3 - Normal Wear & Tear












Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate					
Engine Compartment Photos					

Inspection Report (On-Highway Truck Cab + Chassis)

	    
	    
	
Engine Type (Make, Model, Cylinders, Hp)	Volvo, VE D12-365, Hp 365
Emissions Tier	Undetermined
Engine Serial Number	616478
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	Yes
Comments	A small amount of blowback was seen.
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	2 - Above Average Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Appearance	2 - Above Average Wear & Tear




































Inspection Report (On-Highway Truck Cab + Chassis)

Oil Appearance Notes	Appropriate oil level, Thick, opaque oil appearance
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	The engine is in good working order. A little blowback was seen during blowback check.

Chassis & Drivetrain Inspection Points

On-Highway: Underbody Components

Chassis & Drivetrain Photos

Chassis & Drivetrain Underside Photos					
					
					
					
					
					
					

Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Suspension	3 - Normal Wear & Tear
Steer Axle	3 - Normal Wear & Tear
Steering Components	3 - Normal Wear & Tear

Inspection Report (On-Highway Truck Cab + Chassis)

Overall Chassis Condition	3 - Normal Wear & Tear
Overall Chassis Comments	Is in good condition



Drivetrain Inspection Points

Transmission Info (Make/Model)	RTO-14910B-DM3 10 SP
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations
PTO	0
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation
Front Differential	3 - Normal Wear & Tear
Front Differential Condition	Dry housing appearance, no unusual noises heard during operation
Brake Shoe Thickness	50%
Air Brake System Leaks	Yes
Comments	in the engine bay of the machine there is a small air leak coming from the black hose
Air Brake Hose Condition	3 - Normal Wear & Tear
Overall Drivetrain Condition	3 - Normal Wear & Tear
Overall Drivetrain Comments	The drivetrain is in good condition.

Wheels & Tires Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points

Wheel Type	Pneumatic
Wheel Seal Leaks	No
Tire Brand	Firestone
Tire Size	285/85R24.5
Front Left Tire - Ratio Remaining	50%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	70%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	70%

Inspection Report (On-Highway Truck Cab + Chassis)

Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	70%
Rear Left Tire Photos	
Wheels & Hubs	3 - Normal Wear & Tear
Comments	The tires located at the middle axel have 90% left on tread.

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	0
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	0
Overall Functional Test Comments	The truck is fully functional and operational

Inspection Summary

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	
Interior Rating	2 - Above Average Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	

Inspection Report (On-Highway Truck Cab + Chassis)

Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal Wear & Tear
Overall Rating	3 - Normal Wear & Tear
Summary Video	Click to Download
What's Great About the Machine	The tires located at the center of the truck have 90% life left on the tread.
What Needs Work	A small leak was detected coming from a black airhose located under the hood on the left-hand side firewall. The exhaust pipe underneath the cab has a small leak in it. When you push or pull the airbreaks, the counsel around it is loose.
Any Additional Info from the Seller?	This machine was used at a food bank.
Date/Time	03-27-2024
Inspector Name	Steven Mesa