



Inspection Report (On-Highway Truck Cab + Chassis)

General Info

B&B Stock Number	A5909592
Year	2012
Make	Freightliner
Model	M2
Serial Number	1FUJJC5DV7CHBJ7011
Serial Plate	
Odometer Reading	119800
Odometer	
Current Inspection / State Cert / DOT	unable to determine
Previous Application (e.g., earth moving, mining, demolition, etc)	This truck was used at a food bank.

Dimensions

Length (ft and inches)	24ft 5in
Width (ft and inches)	8ft 4 in
Height (ft and inches)	12ft 6in
Wheelbase (ft and inches)	15ft 5.5in
GVWR (lbs)	52,000

Inspection Report (On-Highway Truck Cab + Chassis)

Features and Configuration

Drive Type	4X2
Overdrive	No
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	No
Engine Brake	2 Position
Differential Lock	Yes
Auxiliary Engine	No
Liftgate	No
Telematics	No
OMM (Operator & Maintenance Manual)	No

Exterior 360 Walkaround

360 Walkaround & Operating Video

Walkaround Photos & Operating Video

Exterior Walkaround Photos					
					
Operating Video	Click to Download				

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos					
					

Inspection Report (On-Highway Truck Cab + Chassis)



General Appearance Inspection Points


Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Areas of surface rust observed	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	3 - Normal Wear & Tear	
Glass Condition	Glass intact, no visible damage	
Mirrors	3 - Normal Wear & Tear	
Mirror Condition	Mirrors present and intact, no visible damage	
Exterior Lights	3 - Normal Wear & Tear	
Exterior Lights Condition	No visible damage, lighting system is operational	
Overall Exterior	3 - Normal Wear & Tear	
Comments	Overall, the body is in good condition. Some areas of light rust were seen on the front bumper and on some of the trucks rims.	

Inspection Report (On-Highway Truck Cab + Chassis)

Cab Inspection Points

On Highway - Cab

Cab Interior Photos



Odometer Activity	3 - Normal Wear & Tear
Odometer	Odometer is working and in good condition
Controls/Switches/Gauges	3 - Normal Wear & Tear
Controls/Switches/Gauges	All switches/gauges are in good condition and functioning
Brake System Type	Air Brakes
Air Brakes Build Correct Pressure	Yes
Clutch	3 - Normal Wear & Tear
Clutch Function	Clutch is functioning as expected
Horn	3 - Normal Wear & Tear
Horn Function	Horn is functioning as expected
Reverse Alarm / Backup Camera	0
Heater & A/C	2 - Above Average Wear & Tear
Heat & A/C	A/C Blows cool - noticeably cooler than air temp
Interior Lights	3 - Normal Wear & Tear
Interior Lights	All interior lights are installed and functioning
Seats/Seat Belts	3 - Normal Wear & Tear



Inspection Report (On-Highway Truck Cab + Chassis)

Seats/Seat Belt	Seat(s) in good condition, no stains or tears in upholstery, Seat belt secures properly
Cab Interior Overall	3 - Normal Wear & Tear

Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate					
Engine Compartment Photos					
Engine Type (Make, Model, Cylinders, Hp)	Detroit, Hp 277				
Emissions Tier	Tier 4F				
Engine Serial Number	unable to verify				
Engine Fuel Type	Diesel				
Blow-by (Visual Observation Check)	Yes				
Comments	The blowby check was good				
Unusual Noises (Upon Start-up, Idle, Shutdown)	Yes				
Unusual Noise Notes	High-pitched metallic pinging heard				
Comments	The sound went away after the truck warmed up				

Inspection Report (On-Highway Truck Cab + Chassis)
























Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Coolant Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Oil Appearance Notes	Appropriate oil level, Very dark, black & burnt oil appearance
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	The engine is in good condition

Chassis & Drivetrain Inspection Points

On-Highway: Underbody Components

Chassis & Drivetrain Photos

Inspection Report (On-Highway Truck Cab + Chassis)

Chassis & Drivetrain Underside Photos					
					
					
					
					

Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Suspension	3 - Normal Wear & Tear
Steer Axle	3 - Normal Wear & Tear
Steering Components	3 - Normal Wear & Tear
Overall Chassis Condition	3 - Normal Wear & Tear
Overall Chassis Comments	The chassis is in good condition

Drivetrain Inspection Points





Transmission Info (Make/Model)	Eaton, FROF-15210C
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations
PTO	0
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation
Front Differential	3 - Normal Wear & Tear
Front Differential Condition	Dry housing appearance, no unusual noises heard during operation
Brake Shoe Thickness	50%
Air Brake System Leaks	No
Air Brake Hose Condition	3 - Normal Wear & Tear
Overall Drivetrain Condition	3 - Normal Wear & Tear
Overall Drivetrain Comments	The drivetrain is in good operational condition

Inspection Report (On-Highway Truck Cab + Chassis)

Wheels & Tires Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points

Wheel Type	Solid, Pneumatic				
Wheel Seal Leaks	No				
Tire Brand	BFGoodrich				
Tire Size	275/80R 22.5S				
Front Left Tire - Ratio Remaining	70%				
Front Left Tire Photos					
Front Right Tire - Ratio Remaining	70%				
Front Right Tire Photos					
Rear Right Tire - Ratio Remaining	50%				
Rear Right Tire Photos					
Rear Left Tire - Ratio Remaining	70%				
Rear Left Tire Photos					
Wheels & Hubs	3 - Normal Wear & Tear				
Comments	central axel, both inside tires are at a 50, outside tires are at 90%.				

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	0
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear

Inspection Report (On-Highway Truck Cab + Chassis)

Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	The truck is fully functional and operational

Inspection Summary

Overall Assessment

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	3 - Normal Wear & Tear	
Interior Rating	3 - Normal Wear & Tear	
Safety Rating	3 - Normal Wear & Tear	
Quality Rating	3 - Normal Wear & Tear	
Functionality Rating	3 - Normal Wear & Tear	
Overall Rating	3 - Normal Wear & Tear	
Summary Video	Click to Download	
What's Great About the Machine	5 of the rear tires have 90% life left on the tread. The truck started right up without any issues.	
What Needs Work	Areas of minor rusting was seen on the front bumper and on some of the trucks rims.	
Any Additional Info from the Seller?	This truck was used in a food bank	
Date/Time	03-27-2024	
Inspector Name	Steven Mesa	