



## Inspection Report (On-Highway Truck Cab + Chassis)

### General Info

B&B Stock Number	A9653085
Year	2007
Make	Freightliner
Model	Columbia
Serial Number	1FUJA6CK97LX83192
Serial Plate	
Odometer Reading	737504
Odometer	
Current Inspection / State Cert / DOT	unable to verify
Previous Application (e.g., earth moving, mining, demolition, etc)	This truck was used at a food bank

### Dimensions

Length (ft and inches)	23ft 3in
Width (ft and inches)	8ft 3in
Height (ft and inches)	12ft
Wheelbase (ft and inches)	14ft 5.5in
GVWR (lbs)	52,000lbs

## Inspection Report (On-Highway Truck Cab + Chassis)

### Features and Configuration

Drive Type	4X2
Overdrive	Yes
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	No
Engine Brake	2 Position
Differential Lock	Yes
Auxiliary Engine	No
Liftgate	No
Telematics	No
OMM (Operator & Maintenance Manual)	No

### Exterior 360 Walkaround

### 360 Walkaround & Operating Video

### Walkaround Photos & Operating Video

Exterior Walkaround Photos	    
	  
Operating Video	<a href="#">Click to Download</a>












### General Appearance Inspection Points

### General Appearance

### General Appearance Photos

Close-up Exterior Photos	    
	    

## Inspection Report (On-Highway Truck Cab + Chassis)

					
					
		<p>A dent was noticed directly behind the 5th wheel</p>			

## General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	3 - Normal Wear & Tear	
Body Panel Condition	Other (see comments), Some panel misalignment observed, Visible chipped paint or dents	
Comments	When the hood is closed, the right-hand side of the trucks hood shuts but is misaligned by a small amount. This is because the bracket that holds the hood in place is bent on the right-hand side.	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Glass	4 - Very Light or Minimal Wear	
Glass Condition	Glass intact, no visible damage	
Mirrors	4 - Very Light or Minimal Wear	
Mirror Condition	Mirrors present and intact, no visible damage	
Exterior Lights	4 - Very Light or Minimal Wear	






















## Inspection Report (On-Highway Truck Cab + Chassis)

Exterior Lights Condition	No visible damage, lighting system is operational
Overall Exterior	3 - Normal Wear & Tear
Comments	The exterior is in good shape with signs of normal wear and tear throughout the exterior.

### Cab Inspection Points

#### On Highway - Cab

#### Cab Interior Photos

Cab Interior Photos					
					
					
					
					The dashboard on the passenger side is loose.
					This area is damaged
Odometer Activity	3 - Normal Wear & Tear				
Odometer	Odometer is working and in good condition				
Controls/Switches/Gauges	3 - Normal Wear & Tear				
Controls/Switches/Gauges	All switches/gauges are in good condition and functioning				
Brake System Type	Air Brakes				
Air Brakes Build Correct Pressure	Yes				
Clutch	3 - Normal Wear & Tear				
Clutch Function	Clutch is functioning as expected				
Horn	3 - Normal Wear & Tear				
Horn Function	Horn is functioning as expected				




















## Inspection Report (On-Highway Truck Cab + Chassis)

Reverse Alarm / Backup Camera	0
Heater & A/C	3 - Normal Wear & Tear
Heat & A/C	A/C Blows cool - noticeably cooler than air temp
Interior Lights	3 - Normal Wear & Tear
Interior Lights	All interior lights are installed and functioning
Seats/Seat Belts	3 - Normal Wear & Tear
Seats/Seat Belt	Seat belt secures properly, Seat(s) have minor surface staining or small tears
Cab Interior Overall	3 - Normal Wear & Tear
Comments	The cab is in good condition with a normal amount of wear and tear.









### Engine Inspection Points

#### Engine

#### Engine Compartment Photos

Engine Data Plate					
Engine Compartment Photos					
	 <p>this area has a fuel leak.</p>	 <p>Fuel leak</p>			
					
					

## Inspection Report (On-Highway Truck Cab + Chassis)

	    
	  
<b>Engine Type (Make, Model, Cylinders, Hp)</b>	Detroit, Series 60, Hp 515
<b>Emissions Tier</b>	Undetermined
<b>Engine Serial Number</b>	unable to verify
<b>Engine Fuel Type</b>	Diesel
<b>Blow-by (Visual Observation Check)</b>	Yes
<b>Comments</b>	The blowby check was good
<b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b>	No
<b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>	No
<b>Engine Exhaust Color</b>	Clear
<b>Battery</b>	3 - Normal Wear & Tear
<b>Battery Condition</b>	Clean & dry appearance, tight connections
<b>Radiator</b>	3 - Normal Wear & Tear
<b>Radiator Condition</b>	Radiator fins & components appear to be in good working order, no signs of damage or leaks
<b>Belts</b>	3 - Normal Wear & Tear
<b>Hoses</b>	3 - Normal Wear & Tear
<b>Water Pump</b>	3 - Normal Wear & Tear
<b>Cooling System Leaks</b>	No
<b>Coolant Appearance</b>	3 - Normal Wear & Tear
<b>Oil Leaks</b>	No
<b>Oil Appearance</b>	3 - Normal Wear & Tear
<b>Oil Appearance Notes</b>	Very dark, black & burnt oil appearance, Appropriate oil level
<b>Fuel Leaks</b>	Yes
<b>Fuel Leak Notes</b>	Wet spots & streaking on fuel lines indicate an active leak
<b>Equipped with DPF (Diesel Particulate Filter)</b>	No
<b>Requires DEF (Diesel Exhaust Fluid)</b>	No
























## Inspection Report (On-Highway Truck Cab + Chassis)

Overall Engine Rating	2 - Above Average Wear & Tear
Overall Engine Appearance	Active leaks/pooling observed in & around engine compartment
Overall Engine Comments	A fuel leak was seen on the engine. The seller is aware and is going to fix the issue.

### Chassis & Drivetrain Inspection Points

#### On-Highway: Underbody Components

#### Chassis & Drivetrain Photos

Chassis & Drivetrain Underside Photos					
				<p>This area around the transmission is wet and has signs of a small active leak.</p>	
					
	<p>Active leaking around the transmission bell was seen.</p>				
					
					
					

### Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Suspension	3 - Normal Wear & Tear
Steer Axle	3 - Normal Wear & Tear
Steering Components	3 - Normal Wear & Tear

## Inspection Report (On-Highway Truck Cab + Chassis)

Overall Chassis Condition	3 - Normal Wear & Tear
Overall Chassis Comments	The chassis is in good working order



### Drivetrain Inspection Points

Transmission Info (Make/Model)	Eaton
Transmission	2 - Above Average Wear & Tear
Transmission Condition	No unusual noises or vibrations, Other (see comments)
Comments	The transmission had a small leak coming from around the bell.
PTO	0
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation
Front Differential	3 - Normal Wear & Tear
Front Differential Condition	Dry housing appearance, no unusual noises heard during operation
Brake Shoe Thickness	50%
Air Brake System Leaks	No
Air Brake Hose Condition	3 - Normal Wear & Tear
Overall Drivetrain Condition	3 - Normal Wear & Tear
Overall Drivetrain Comments	The drivetrain is fully functional.

### Wheels & Tires Inspection Points

#### Wheels & Tires

#### Wheels & Tires Inspection Points

Wheel Type	Pneumatic
Wheel Seal Leaks	No
Tire Brand	Bridgestone
Tire Size	11R22.5
Front Left Tire - Ratio Remaining	70%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	50%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	70%



## Inspection Report (On-Highway Truck Cab + Chassis)

Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	50%
Rear Left Tire Photos	
Wheels & Hubs	3 - Normal Wear & Tear
Comments	the left-hand side rear tires have 70% life left on tread

### Functional Test

#### Functionality Assessment

#### Functionality Assessment

Engine	2 - Above Average Wear & Tear
Comments	An active fuel leak was seen on the left-hand side of the engine.
Transmission/Drivetrain	2 - Above Average Wear & Tear
Comments	A small leak was seen around the bell area of the transmission
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	0
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	2 - Above Average Wear & Tear
Comments	An small fuel leak was seen
Core Functions	3 - Normal Wear & Tear
Attachments	0
Overall Functional Test Comments	The trucknis fully functional and operational

### Inspection Summary

#### Overall Assessment

Inspection Rating Criteria	<b>Rating Scale</b>	<b>Explanation</b>
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.

## Inspection Report (On-Highway Truck Cab + Chassis)

<b>Exterior Rating</b>	3 - Normal Wear & Tear
<b>Interior Rating</b>	3 - Normal Wear & Tear
<b>Safety Rating</b>	2 - Above Average Wear & Tear
<b>Quality Rating</b>	2 - Above Average Wear & Tear
<b>Functionality Rating</b>	3 - Normal Wear & Tear
<b>Overall Rating</b>	2 - Above Average Wear & Tear
<b>Summary Video</b>	<a href="#">Click to Download</a>
<b>What's Great About the Machine</b>	On the rear axels, 6 tires have 70% life on them.
<b>What Needs Work</b>	A fuel leak was found on the left-hand side of the engine. A small active leak was seen coming from the transmission around the bell area, and the hood is misaligned a little bit.
<b>Any Additional Info from the Seller?</b>	The owner was aware of the fuel leak and is going to fix the issue.
<b>Date/Time</b>	03-28-2024
<b>Inspector Name</b>	Steven Mesa