

Job #: 70040 /

VIN: 1GDL7H1EX2J508826

#### 2002 GMC 7500 / 0

Specifications	
Year	2002
Make	GMC
Model	C7
Date of Inspection	04/04/2024
Location of Inspection	754 Wiltsie Bridge Rd , Ancram, NY, 12502, USA
VIN	1GDL7H1EX2J508826
GVWR	29.260 lbs
Odometer	88,841
Engine Hours	Could Not Be Located
EMS Warning Lights	No Active Warninigs
Cab Interior	No Damages Observed
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission Type	Manual
Pedals	No Damages Observed
Floorboard	See Notes
Radio	No
A/C	No
Switches and Controls	See Notes
Power Mirrors	No
Heated Mirrors	No
Steering Wheel	No Damages Observed
Mirrors	See Notes
Steps	See Notes
Handrails	No Damages Observed
Exhaust Pipe	No Damages Observed
Engine Compartment	See Notes
Oil Dipstick	Low Level / Dark Color
Coolant Level	Low Level
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	See Notes
Rear Lights	See Notes
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	High Speed
Left Steer Tire Size	295/75R22.5
Left Outer Drive Tire Condition	No Damages Observed
Left Outer Drive Tire Brand	High Speed
Left Outer Drive Tire Size	295/75R22.5
Left Inner Drive Tire Condition	No Damages Observed



#### **Video Inspection Link**

https://app.aspenfieldservices.com/jobs/video/7uD8PtsxqRLfq7NpK

#### **Notes / Description**

The unit runs and drives. The engine information was acquired via a VIN decoder software. The mileage on the unit appears to be low for the amount of wear on the unit and year of the unit. The front left fender is broken and missing a piece out of it. The front grill is missing a piece out of it and paint is worn. The right turn signal lens appears to be taped together. The hood appears to have some paint scratches on it. The expanded metal platform above the cab has holes in it and appears to be bent. The right door has a dent in it at the bottom. The right and left lower sides of the box have dents and rust spots on it. The rear tailgate appears to be rusted on the bottom right edge. The paint is peeling on the storage boxes. The left mirror bracket is missing a bolt out of it. The left door paint is peeling. The frame rails and undercarriage is rusty. The rear bumper is bent. The rear wheel chocks are missing and the metal housings are bent. The right leaf spring brackets are missing bolts through them. The rear right top signal light lens is cracked. The right rocker panel below the door appears to be rusted out. The upper step on the left fuel tank appears to be bent. The interior light in the cab is missing the lens cover. The rubber floor covering on the driver side is worn through and torn. The seat is dirty and stained. The floor mat on the right side appears to be torn and missing a piece of the rubber. There is wiring that appears to be disconnected by the outrigger hand controls. The cover over the front left outrigger controls is bent. The front left outrigger hand control is missing a knob on the handle. The coolant is low in the reservoir. The A/C compressor belt appears to be missing. The metal lines in the engine compartment on the left side appear to be oily and possibly leaking. The engine oil is dark in color and low level on the dipstick. The oil fill cap appears to be missing on the fill neck in the engine compartment. The cross braces under the box appear to be rusted through.



Job #: 70040 /

VIN: 1GDL7H1EX2J508826

Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	High Speed
Right Steer Tire Size	295/75R22.5
Right Outer Drive Tire Condition	No Damages Observed
Right Outer Drive Tire Brand	High Speed
Right Outer Drive Tire Size	295/75R22.5
Right Inner Drive Tire Condition	No Damages Observed
Axle Information	Front: 10,300 lbs / Rear: 18,960 lbs
Transmission Information	Could Not Be Located
Engine Information	8.1L



Front Left / 04-04-2024



Front / 04-04-2024



Front Right / 04-04-2024



Right / 04-04-2024



Rear Right / 04-04-2024



Rear / 04-04-2024



Rear Left / 04-04-2024




Left / 04-04-2024



VIN: 1GDL7H1EX2J508826 / GVWR / Axle Information / 04-04-2024



Odometer: 88,841 / 04-04-2024



Axle / Suspensions / 04-04-2024




Mirrors / 04-04-2024




Steps / 04-04-2024



Suspensions / 04-04-2024



Axle / 04-04-2024



Axle / 04-04-2024



Rear Lights / 04-04-2024



Front Lights / 04-04-2024



Suspensions / 04-04-2024



Axle / 04-04-2024




Exhaust Pipe / 04-04-2024



Mirrors / 04-04-2024



Steps / 04-04-2024



Axle / Suspensions / 04-04-2024



Handrails / 04-04-2024





Driver's Seat / 04-04-2024



Floorboard / Pedals / 04-04-2024



Steering Wheel / 04-04-2024



Transmission Shifter / 04-04-2024



Switches and Controls / 04-04-2024



Switches and Controls / 04-04-2024



Floorboard / 04-04-2024



Passenger's Seat / 04-04-2024



Cab Interior / 04-04-2024



Switches and Controls / 04-04-2024



Switches and Controls / 04-04-2024



Engine Compartment / 04-04-2024




Boom Arm / 04-04-2024



Coolant Level / 04-04-2024



Coolant Level / 04-04-2024



Oil Dipstick / 04-04-2024



Left Steer Tire Condition / 04-04-2024



Left Steer Tire Condition / 04-04-2024



Left Steer Tire Size / 04-04-2024



Left Steer Tire Brand / 04-04-2024



Left Outer Drive Tire Condition / 04-04-2024



Left Outer Drive Tire Condition / Left Inner Drive Tire Condition / 04-04-2024




Left Outer Drive Tire Brand / 04-04-2024



Left Outer Drive Tire Size / 04-04-2024



Right Outer Drive Tire Condition / Right Outer Drive Tire Brand / 04-04-2024



Right Outer Drive Tire Size / 04-04-2024



Right Outer Drive Tire Condition / Right Inner Drive Tire Condition / 04-04-2024



Right Steer Tire Size / 04-04-2024



Right Steer Tire Brand / 04-04-2024



Right Steer Tire Condition / 04-04-2024



Right Steer Tire Condition / 04-04-2024