



## Inspection Report (Scissor Lift)

### General Info

B&B Stock Number	A8912439
Year	2011
Make	JLG
Model	2630ES
Serial Number	0200204446
Serial Plate Photo	
Hour Meter Reading	296.3
Hour Meter Photo	
Previous Application (e.g., earth moving, mining, demolition, etc)	Sanitation district

### Features and Configuration

## Inspection Report (Scissor Lift)

Max Lift Height	25'
Max Lift Capacity	500lbs
Drive	2WD
Electric Powertrain	Yes
Hydraulic Leveling	No
Electric Power to Platform	Yes
Deck Extensions	Yes
Deck Extension Measurements	3'
Outriggers	No
Additional Attachment(s)?	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No

### Exterior 360 Walkaround

#### 360 Walkaround & Operation Video

#### Walkaround Photos & Operating Video

Exterior Walkaround Photos	
Operating Video	<a href="#">Click to Download</a>

### General Appearance Inspection Points

#### General Appearance

#### General Appearance Photos

Close-up Exterior Photos	
--------------------------	--

## Inspection Report (Scissor Lift)




### General Appearance Inspection Points

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	2 - Above Average Wear & Tear	
Body Panel Condition	Some panel misalignment observed, Visible chipped paint or dents, Areas of surface rust observed	
Doors / Canopy Latches	0	
Steps / Ladders	3 - Normal Wear & Tear	
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound	
Handrails	1 - Service Required	
Handrails Condition	Bent or broken railings, Handrails are not structurally sound	
Comments	Hardware missing causing misalignment with deck rails	
Glass	0	
Mirrors	0	
Exterior Lights	0	
Overall Exterior	2 - Above Average Wear & Tear	
Comments	Above average wear and tear. Signs of surface rust. Bent rails.	


### Control Station Inspection Points

#### Control Station

#### Control Station Photos



## Inspection Report (Scissor Lift)
















	
<b>Control Station Type</b>	Platform
<b>Control Type</b>	Other
<b>Control Configuration</b>	N/A
<b>Seat</b>	0
<b>Cabin Lights</b>	0
<b>Safety Lock Out / Stop</b>	3 - Normal Wear & Tear
<b>Safety Lock Out / Stop Condition</b>	Safety lock out device is present, in good condition, and functional
<b>Controls &amp; Switches</b>	3 - Normal Wear & Tear
<b>Controls &amp; Switches Condition</b>	All switches are installed and functional
<b>Hour Meter Activity</b>	3 - Normal Wear & Tear
<b>Hour Meter Condition</b>	Hour meter is functional and in good condition
<b>Other Gauge Activity</b>	0
<b>Heater &amp; A/C</b>	0
<b>Travel Alarm</b>	3 - Normal Wear & Tear
<b>Travel Alarm Condition</b>	Travel alarm is installed and functioning as expected
<b>Horn</b>	1 - Service Required
<b>Horn Condition</b>	One or more elements of the horn assembly are missing
<b>Backup Camera</b>	0
<b>Control Station Overall Rating</b>	2 - Above Average Wear & Tear
<b>Control Station Overall Condition</b>	Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling

### Powertrain Inspection Points

#### Electric Operating System

#### Electric Operating System Photos





## Inspection Report (Scissor Lift)

Electric Operating System Photos	    
	    
	    
Battery Condition	3 - Normal Wear & Tear
Battery Charger	3 - Normal Wear & Tear
Cables & Connections	3 - Normal Wear & Tear
Tight Connections?	Yes
Solenoids	3 - Normal Wear & Tear
Wire Harness	3 - Normal Wear & Tear
Fuse Panel(s)	0
Computer Appearance	3 - Normal Wear & Tear
Screen Discoloration?	Yes
Electric Operating System Overall Rating	3 - Normal Wear & Tear
Overall Electric Operating System Comments	Normal wear and tear no major issues to report

## Drivetrain Inspection Points

### Drivetrain


## Drivetrain Inspection Points

Drivetrain Photos	   
Hydrostatic Transmission?	Yes
Speeds	2 Speed
Drive Type	2WD
Differential Lock	No
Transmission Components	0
Drive Motors	3 - Normal Wear & Tear

## Inspection Report (Scissor Lift)

Parking Brake	0
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report


## Chassis Inspection Points

Chassis Photos	
Frame	2 - Above Average Wear & Tear
Comments	Surface rust observed, and dense to some of the scissor rails
Front Axle Appearance	0
Rear Axle Appearance	0
Wheels & Tires	3 - Normal Wear & Tear
Tire Brand	Camso
Tire Size	406x1.25
Front Left Tire - Ratio Remaining	70%
Rear Left Tire - Ratio Remaining	70%
Front Right Tire - Ratio Remaining	70%
Rear Right Tire - Ratio Remaining	70%
Overall Chassis	2 - Above Average Wear
Overall Chassis Comments	Above average wear and tear service rust observed minor dents to scissor rails. Left side pothole protector not engaging.

## Hydraulics Overall Inspection Points


### Hydraulics Overall

### Hydraulic System Inspection Points

Hydraulic System Photos	
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No

## Hydraulic Cylinder Inspection Points

## Inspection Report (Scissor Lift)

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear

## Functional Test

### Functionality Assessment

### Functionality Assessment

Engine	0
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	0
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	2 - Above Average Wear & Tear
Comments	Minor cosmetic damage to display
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	0
Overall Functional Test Comments	Normal wear, and tear with minor cosmetic damage to controls

## Overall Assessment

### Overall Assessment

Inspection Rating Criteria	<b>Rating Scale</b>	<b>Explanation</b>
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Exterior Rating	2 - Above Average Wear & Tear	
Interior Rating	0	
Safety Rating	2 - Above Average Wear & Tear	
Quality Rating	2 - Above Average Wear & Tear	



## Inspection Report (Scissor Lift)

<b>Functionality Rating</b>	3 - Normal Wear & Tear
<b>Overall Rating</b>	2 - Above Average Wear & Tear
<b>What's Great About the Machine</b>	The thing that is great about this machine is that both upper and lower controls function as specified by the manufacturer?
<b>What Needs Work</b>	The things that need work on this machine are the missing hardware for the rail extensions, the bent top rails and the pothole protector on the left side not engaging
<b>Date/Time</b>	04-15-2024
<b>Inspector Name</b>	Javier Bocanegra