



Inspection Report (Skip Loader)

General Info

B&B Stock Number	A5246690
Year	1998
Make	Case
Model	570LXT
Serial Number	JJG0260804
Serial Plate Photo	
Hour Meter Reading	2955.9
Hour Meter Photo	

Features and Configuration

Bucket	Yes
Bucket Specs	6' 11"
Box Blade	Yes
Box Blade Specs	7'
Additional Attachment(s)?	No
Auxiliary Hydraulics	No
Heat	No
A/C	No









Inspection Report (Skip Loader)

Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

360 Walkaround & Operating Video















Walkaround Photos & Operating Video

Exterior Walkaround Photos					
					
Operating Video	Click to Download				
Additional Video	Click to Download				
Additional Video	Click to Download				

General Appearance Inspection Points

General Appearance

General Appearance Photos

Close-up Exterior Photos					
					
					

General Appearance Inspection Points

Inspection Report (Skip Loader)

Inspection Rating Criteria	Rating Scale	Explanation
	1 - Service Required	Requires immediate repairs to function as expected.
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.
	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
Body Panels	2 - Above Average Wear & Tear	
Body Panel Condition	Some panel misalignment observed, Visible chipped paint or dents, Areas of surface rust observed	
Comments	Engine cover panel sticks / hard to open	
Doors / Canopy Latches	0	
Steps / Ladders	3 - Normal Wear & Tear	
Handrails	3 - Normal Wear & Tear	
Glass	0	
Mirrors	3 - Normal Wear & Tear	
Exterior Lights	3 - Normal Wear & Tear	
Overall Exterior	3 - Normal Wear & Tear	
Comments	Normal wear and tear no major issues to report	


Control Station Inspection Points

Control Station

Control Station Photos

Control Station Photos


Inspection Report (Skip Loader)

	
Control Station Type	Open Cab (OROPS)
Control Type	Pilot Controls
Control Configuration	N/A
Seat	2 - Above Average Wear & Tear
Seat Condition	Seat(s) have minor surface staining or small tears, Seat belt secures properly
Comments	Seat is loose due to seat lock being loose
Cabin Lights	0
Safety Lock Out / Stop	0
Controls & Switches	3 - Normal Wear & Tear
Hour Meter Activity	3 - Normal Wear & Tear
Other Gauge Activity	3 - Normal Wear & Tear
Heater & A/C	0
Travel Alarm	0
Horn	3 - Normal Wear & Tear
Backup Camera	0
Control Station Overall Rating	3 - Normal Wear & Tear











Engine Inspection Points

Engine

Engine Compartment Photos

Engine Data Plate	
Engine Compartment Photos	

Inspection Report (Skip Loader)


	    
	    
Engine Type (Make, Model, Cylinders, Hp)	Case, 4-390
Emissions Tier	Undetermined
Engine Serial Number	45765627
Engine Fuel Type	Diesel
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Like new, recently replaced
Radiator	3 - Normal Wear & Tear
Belts	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Water Pump	3 - Normal Wear & Tear
Cooling System Leaks	No
Coolant Appearance	3 - Normal Wear & Tear
Oil Leaks	No
Oil Appearance	3 - Normal Wear & Tear
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Rating	3 - Normal Wear & Tear
Overall Engine Appearance	Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Above average wear and tear due to dry seepage found throughout engine compartment

Drivetrain Inspection Points


Inspection Report (Skip Loader)

Drivetrain

Drivetrain Inspection Points

Drivetrain Photos	
Hydrostatic Transmission?	No
Drive Type	2WD
Differential Lock	Yes
Transmission Components	3 - Normal Wear & Tear
Parking Brake	2 - Above Average Wear & Tear
Overall Drivetrain Rating	3 - Normal Wear & Tear
Overall Drivetrain Comments	Normal wear and tear no major issues to report

Chassis Inspection Points

Chassis Photos	
Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Front Axle	3 - Normal Wear & Tear
Rear Axle	3 - Normal Wear & Tear
Oscillating Pin	0
Lift Arm	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Tilt Linkage	3 - Normal Wear & Tear
Tilt Linkage Pins & Bushings	3 - Normal Wear & Tear
Bucket to Arm Pins	3 - Normal Wear & Tear












Inspection Report (Skip Loader)

Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Norma wear and tear no major issues to report

Wheels & Tires Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points


Wheel Type	Pneumatic		
Wheel Seal Leaks	Yes		
Comments	Possible front wheel seal leak		
Wheel Seal Leak Photos			
Tire Brand	Solideal		
Tire Size	19.5L-24(rear) / 12-16.5 (fronts)		
Front Left Tire - Ratio Remaining	10%		
Front Left Tire Photos			
Front Right Tire - Ratio Remaining	10%		
Front Right Tire Photos			
Rear Right Tire - Ratio Remaining	50%		
Rear Right Tire Photos			
Rear Left Tire - Ratio Remaining	50%		
Rear Left Tire Photos			
Wheels & Hubs	3 - Normal Wear & Tear		

Hydraulics Overall Inspection Points


Hydraulics Overall

Hydraulic System Inspection Points

Inspection Report (Skip Loader)

Hydraulic System Photos	
Wet or Damp Hydraulic Lines / Fittings	No
Hydraulic Lines/Fittings	3 - Normal Wear & Tear
Hydraulic Pump(s)	3 - Normal Wear & Tear
Unusual Noises	No

Hydraulic Cylinder Inspection Points

Hydraulic Cylinder Photos	
Mounting Pins	3 - Normal Wear & Tear
Cylinder Oil Leaks	No
Hydraulic System Overall	3 - Normal Wear & Tear

Box Blade & Scarifier Inspection Points

Loader Bucket	3 - Normal Wear & Tear
Bucket Edge / Deflectors	2 - Above Average Wear & Tear
Gannon Box	3 - Normal Wear & Tear
Blade	3 - Normal Wear & Tear

Inspection Report (Skip Loader)

Scarifier	2 - Above Average Wear & Tear
Comments	Missing one

Functional Test

Functionality Assessment

Functionality Assessment

Engine	3 - Normal Wear & Tear
Transmission/Drivetrain	3 - Normal Wear & Tear
Travel (Forward/Reverse/Steering)	3 - Normal Wear & Tear
Brakes	3 - Normal Wear & Tear
Hydraulic System	3 - Normal Wear & Tear
Electric Operating System	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Safety Systems	3 - Normal Wear & Tear
Core Functions	3 - Normal Wear & Tear
Attachments	3 - Normal Wear & Tear
Overall Functional Test Comments	Normal wear and tear no major issues to report

Overall Assessment

Overall Assessment

Inspection Rating Criteria	<table border="1"> <thead> <tr> <th>Rating Scale</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>1 - Service Required</td> <td>Requires immediate repairs to function as expected.</td> </tr> <tr> <td>2 - Above Average Wear & Tear</td> <td>Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.</td> </tr> <tr> <td>3 - Normal Wear & Tear</td> <td>Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.</td> </tr> <tr> <td>4 - Very Light or Minimal Wear</td> <td>Exhibits very minimal wear. Operation is better than expected given age and usage.</td> </tr> <tr> <td>5 - Like New, Recently Replaced</td> <td>Excellent condition, free of visible wear or damage. Operation is within factory specifications.</td> </tr> </tbody> </table>	Rating Scale	Explanation	1 - Service Required	Requires immediate repairs to function as expected.	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.	5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.
	Rating Scale	Explanation											
	1 - Service Required	Requires immediate repairs to function as expected.											
	2 - Above Average Wear & Tear	Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed.											
	3 - Normal Wear & Tear	Exhibits wear that is consistent with age and usage. Operation is normal, and as expected.											
	4 - Very Light or Minimal Wear	Exhibits very minimal wear. Operation is better than expected given age and usage.											
5 - Like New, Recently Replaced	Excellent condition, free of visible wear or damage. Operation is within factory specifications.												
Exterior Rating	2 - Above Average Wear & Tear												
Interior Rating	3 - Normal Wear & Tear												
Safety Rating	3 - Normal Wear & Tear												
Quality Rating	3 - Normal Wear & Tear												
Functionality Rating	3 - Normal Wear & Tear												
Overall Rating	3 - Normal Wear & Tear												
What's Great About the Machine	The great thing about this machine is that it starts right up with no abnormal noises heard												



Inspection Report (Skip Loader)

What Needs Work	The things that need work on this machine are the dried seepage found throughout engine compartment, damaged hood to engine compartment
Date/Time	04-16-2024
Inspector Name	Javier Bocanegra